

16700 Valley View Ave
 Suite 100
 La Mirada, California 90638



Phone: (714) 523-9811
 Fax: (714) 523-9810
 www.enccorp.net

3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|---------------------|---|-------------------------------|------------------|------------|--------------------|--------------------------|----------|
| AQUATIC CENTER | POOL HOUSE ROOF, POOL HOUSE PUMP ROOM | PENETRATION MASTIC | POSITIVE | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 1 - 1ST FLOOR | DATA & FILE ROOMS | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 1 - 2ND FLOOR | ATTIC | ASBESTOS TAPE | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 11 |
| BLDG. 1 - 2ND FLOOR | ATTIC | FIREPROOFING INSULATION | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 11 |
| BLDG. 1 - 2ND FLOOR | BOOK ROOM, OFFICE, WORK ROOM AND ROOM 200 | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 1 - 2ND FLOOR | LIBRARY | CEILING SPRAY | | | | MATERIAL HAS BEEN ABATED | |

Risk Factor Response by Color:
 Red High Risk = Immediate: Perform repairs and/or abatement as soon as possible | Yellow Moderate Risk = Caution: Perform repairs and response action when feasible | Green Low Risk = Continue Periodic Surveillance and O and M Procedures

16700 Valley View Ave
 Suite 100
 La Mirada, California 90638



Phone : (714) 523-9811
 Fax: (714) 523-9810
 www.enccorp.net

3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Triability | Recommended Action | Comment | Priority |
|---------------------|------------------------------|-------------------------------|------------------|------------|--------------------|--------------------------|----------|
| BLDG. 2 - 1ST FLOOR | CLASSROOMS 104-111 & 117-119 | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 2 - 1ST FLOOR | ROOM 104 EAST SIDE | TSI - PIPE INSULATION | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 2 - 1ST FLOOR | TECHNOLOGY OFFICE | TSI - ELBOW MUD | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 2 - 1ST FLOOR | THROUGHOUT | FIRE DOORS | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 2 - 2ND FLOOR | CLASSROOMS 206-219 | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |

Risk Factor Response by Color:
 Red High Risk = Immediate: Perform repairs and/or abatement as soon as possible | Yellow Moderate Risk = Caution: Perform repairs and response action when feasible | Green Low Risk = Continue Periodic Surveillance and O and M Procedures



3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|---------------------|---|------------------------------------|------------------|------------|--------------------|--------------------------|----------|
| BLDG. 2 - 2ND FLOOR | LITTLE THEATER (ROOM 207) | ELECTRICAL WIRE INSULATION (WHITE) | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 10 |
| BLDG. 2 - 2ND FLOOR | LITTLE THEATER OFFICE (ROOM 207) | CEILING SPRAY | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 10 |
| BLDG. 2 - 2ND FLOOR | LITTLE THEATER OFFICE (ROOM 207) AND STAGE STORAGE ROOM | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 10 |
| BLDG. 2 - 3RD FLOOR | CLASSROOMS 308-319 | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 3 - 1ST FLOOR | ATTIC AREA | FIREPROOFING INSULATION | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 11 |
| BLDG. 3 - 1ST FLOOR | CAFETERIA | CEILING SPRAY | | | | MATERIAL HAS BEEN ABATED | |

16700 Valley View Ave
 Suite 100
 La Mirada, California 90638



Phone : (714) 523-9811
 Fax : (714) 523-9810
 www.enccorp.net

3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|-----------------------|--|-------------------------------|------------------|------------|--------------------|---|----------|
| BLDG. 3 - 1ST FLOOR | FACULTY DINING AND HALLWAY | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 3 - 1ST FLOOR | INTERIOR WALLS | PLASTER (TAN) | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 3 - 2ND FLOOR | COSMETOLOGY CLASSROOMS, LOCKER ROOM, AND HALLWAY | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 5 - 1ST FLOOR | MAIN LOBBY | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT. NEW 12" TILE HAS BEEN INSTALLED IN THE STUDENT STORE | 8 |
| BLDG. 5 - 1ST FLOOR | NORTH GYM (STOREROOM) | TSI - ELBOW MUD | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 5 - LOWER LEVEL | BOILER ROOM | BOILER INSULATION | | | | MATERIAL HAS BEEN ABATED | |

Risk Factor Response by Color:
 Red High Risk = Immediate: Perform repairs and/or abatement as soon as possible | Yellow Moderate Risk = Caution: Perform repairs and response action when feasible | Green Low Risk = Continue Periodic Surveillance and O and M Procedures

16700 Valley View Ave
 Suite 100
 La Mirada, California 90638



Phone : (714) 523-9811
 Fax: (714) 523-9810
 www.enccorp.net

3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|-----------------------|---|----------------------------------|------------------|------------|--------------------|--|----------|
| BLDG. 5 - LOWER LEVEL | BOILER ROOM | TSI - ELBOW MUD | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 10 |
| BLDG. 5 - LOWER LEVEL | BOILER ROOM | EXHAUST STACKS INSULATION | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 5 - LOWER LEVEL | BOILER ROOM, STORAGE ROOM AND NORTH/SOUTH TUNNELS | BLOWN-IN INSULATION (WHITE) | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 5 - LOWER LEVEL | FACULTY ROOM, COACH'S OFFICE AND CUSTODIAN'S OFFICE AND LOCKER ROOM | 12" WHITE FLOOR TILE & MASTIC | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 5 - LOWER LEVEL | NORTH TUNNEL | PIPING ELBOW INSULATION (JOINTS) | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 10 |
| BLDG. 5 - LOWER LEVEL | SOUTH TUNNEL | PIPING ELBOW INSULATION (JOINTS) | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT. PARIAL SPOT ABATEMENT IN 2014 | 10 |



3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|-----------------------|---|-------------------------------|------------------|------------|--------------------|--|----------|
| BLDG. 5 - LOWER LEVEL | STORAGE ROOM AT TUNNEL ENTRY | PIPING ELBOW INSULATION | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 10 |
| | | | | | | | |
| BLDG. 5 - ROOF | NORTH AND SOUTH END | TSI - ELBOW INSULATION | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 10 |
| BLDG. 5 - ROOF | NORTH AND SOUTH END | WHITE CLOTH | | | | MATERIAL HAS BEEN ABATED PER CUSTODIAL STAFF | |
| BLDG. 5 - ROOF | NORTH AND SOUTH END LOCATED BETWEEN THE NORTH AND SOUTH GYMS IN MECHANICAL PIT AREA | EXPANSION JOINTS | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 10 |
| | | | | | | | |
| BLDG. 5 - ROOF | ROOF (COOLING TOWER) LOCATED ABOVE THE SOUTH SIDE OF THE GYM/3RD FLOOR ROOF ACCESS | TRANSITE PANELS | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 6 - 1ST FLOOR | CLASSROOMS 150 | 12" WHITE FLOOR TILE & MASTIC | | | | MATERIAL HAS BEEN ABATED | |

Risk Factor Response by Color:
 Red High Risk = Immediate; Perform repairs and/or abatement as soon as possible | Yellow Moderate Risk = Caution; Perform repairs and response action when feasible | Green Low Risk = Continue Periodic Surveillance and O and M Procedures



3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|---------------------|---------------------------------|-------------------------------|------------------|------------|--------------------|--|----------|
| BLDG. 6 - 2ND FLOOR | BUILDING INTERIOR | TSI - ELBOW MUD | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 6 - 2ND FLOOR | CLASSROOMS 250-259 (EXCEPT 228) | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 6 - 3RD FLOOR | ATTIC AREA | FIREPROOFING INSULATION | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 11 |
| BLDG. 6 - 3RD FLOOR | CLASSROOMS 350-359 | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 6 - 3RD FLOOR | CUSTODIANS ROOM 6311 | TSI - ELBOW INSULATION | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 6 - 3RD FLOOR | FUME HOODS | TRANSITE PANEL | ASSUMED | NON | O & M PROGRAM | MATERIAL LOCATED IN CHEMICAL STORAGE ROOM. ROOMS 6302-6303 | 8 |

Risk Factor Response by Color:
 Red High Risk = Immediate: Perform repairs and/or abatement as soon as possible | Yellow Moderate Risk = Caution: Perform repairs and response action when feasible | Green Low Risk = Continue Periodic Surveillance and O and M Procedures



3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|---------------------|---------------------------|-------------------------------|------------------|------------|---|--|----------|
| BLDG. 7 - 1ST FLOOR | INTERIOR WALLS | PLASTER (TAN) | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 7 - 1ST FLOOR | ROOM 160 (NEW ROOM 71111) | 12" WHITE FLOOR TILE & MASTIC | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 7 - 2ND FLOOR | ATTIC AREA | FIREPROOFING | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 11 |
| BLDG. 7 - 2ND FLOOR | CLASSROOMS 261-267 | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT, LOCATED IN ALL ROOMS EXCEPT 264 & 265 | 8 |
| BLDG. 7 - 2ND FLOOR | KILN | TRANSITE PANEL | ASSUMED | NON | REPAIR DAMAGED MATERIAL AND O&M PROGRAM | MATERIAL DAMAGED AT DOOR | 3 |
| BLDG. 7 - 2ND FLOOR | ROOM 262 STORAGE ROOM | TSI - ELBOW INSULATION | | | | MATERIAL HAS BEEN ABATED | |

16700 Valley View Ave
 Suite 100
 La Mirada, California 90638



Phone : (714) 523-9811
 Fax: (714) 523-9810
 www.encomp.net

3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|-----------------------|---|-------------------------------|------------------|------------|--------------------|---|----------|
| BLDG. 7 - LOWER LEVEL | ATTIC | TSI - PIPE COVERING | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT, LOCATED IN ATTIC ABOVE ROOM 160 | 11 |
| | INTERIOR WALLS | PLASTER (TAN) | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT, LOCATED IN ROOMS 160 & 164 | 8 |
| BLDG. 8 - MUSIC ROOMS | ATTIC (ABOVE OFFICE HALLWAY) | FIREPROOFING INSULATION | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 8 |
| | CLASSROOMS 170, 171, PRACTICE ROOMS AND HALLWAY | 12" WHITE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 8 - MUSIC ROOMS | HALLWAY | ACOUSTIC CEILING SPRAY | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 9 - AUDITORIUM | CEILINGS OF BUILDING | ACOUSTIC CEILING SPRAY | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT, LOCATED IN LOBBY, WEST/EAST SPOT, SOUND ROOM & PROJECTION ROOM | 8 |

Risk Factor Response by Color:
 Red High Risk = Immediate: Perform repairs and/or abatement as soon as possible | Yellow Moderate Risk = Caution: Perform repairs and response action when feasible | Green Low Risk = Continue Periodic Surveillance and O and M Procedures



3-YEAR AHERA RE-INSPECTION REPORT

District: GLENDALE UNIFIED SCHOOL DISTRICT
School: GLENDALE HIGH SCHOOL
Site Code: 30-L

Date of Report: 6/3/2015
Inspector: ROBERT CISNEROS
Inspection Date: 12/23/2014

| Building | Space or Rooms | ACM (Material) | Percent Asbestos | Friability | Recommended Action | Comment | Priority |
|--------------------------|------------------------------------|---|------------------|------------|---|--|----------|
| BLDG. 9 - AUDITORIUM | MECHANICAL ROOM 180 | TSI - ELBOW INSULATION | ASSUMED | LOW | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLDG. 9 - AUDITORIUM | MECHANICAL ROOM/STORAGE ROOM | FIREPROOFING INSULATION | | | | MATERIAL HAS BEEN ABATED | |
| BLDG. 9 - AUDITORIUM | ROOM 180 DRESSING ROOM AND STAGE | 12" WHITE & BLUE FLOOR TILE & MASTIC | ASSUMED | NON | O & M PROGRAM | MATERIAL INTACT | 8 |
| BLEACHERS - HOME/VISITOR | BOILER ROOM | BOILER INSULATION - WHITE BLOCK | ASSUMED | LOW | REPAIR DAMAGED MATERIAL AND O&M PROGRAM | MATERIAL DAMAGED | 5 |
| BLEACHERS - HOME/VISITOR | HEATER ROOM | BLOWN-IN INSULATION (WHITE) TANK INSULATION | ASSUMED | LOW | O & M PROGRAM | MATERIAL NOT OBSERVED. PRESUMED IN TANL/BOILER | 8 |
| BLEACHERS - HOME/VISITOR | PRESS ROOM AND PUBLIC ADDRESS ROOM | 12" WHITE FLOOR TILE & MASTIC | | | | MATERIAL HAS BEEN ABATED | |