Oregon Water Resources Department PERMIT CONDITION WATER-LEVEL REPORTING FORM

Well owner:

	1/41 4 510/						-	-				
Name			SCHOOL/BE	L SCHOOL D	Applic		dia					
Address	1200 N. TE	ST			Permit	: [7,5.				
City/State/Zip	EUGENE			0	PR 97402		Certifi	cate:				
Phone/Fax/Cell	541-689-07		EXT. 4159		406-471-45	55	Userid	:		lyy b		
Email	JASON.BE	TTER	Y@BETHEL.	K12.	OR.US		Transf	er				
Your water right requires periodic static water-level measurements in your wells. Consult your permit or certificate to determine when measurements should be made, when reports are due, and who is allowed to make the measurements. Keep a copy of all measurement reports for your records. All wells that have been constructed must be measured regardless of whether they are being used. Please contact the Department if you are no longer the holder of this right or no longer have an interest in it. Complete one form for each well.												
Other water rights that list this well:												
Application number	er(s):											٦
Permit number(s):												1
Certificate number(s):												٦
Identification of measured well (Provide as much information as possible.)												
Water Resources Well Log ID:			LANE 74645		Owner's well name:		BETHEL SC	BETHEL SCHOOL DISTRICT				
Well ID (Well Ta	g) on Well: 1	L -	123253									
Well ID (Well Tag) on Well Log:L-					Well drilled by:		BILL FIELDER WELL DRILLING					٦
Start Card # on Well Log:			1031344		Total depth		59FT Casing diameter (inches): 6"					┨
Date drilled:			7/21/2016		Owner on well log:		BETHEL SCHOOL DISTRICT					┨
Water-Level Measurement												
Date of measurement: Measurements should be made to at least the nearest tenth of a foot (10.2'), the nearest inch (10' 3") of the nearest pound, if using a gage.												
Depth to water belo	w measuring	g point:	10)' 7"	A	irline l	enoth or transd	ucer denth			c.	
Measuring point he					ength or transducer depth: pressure: psi x 2.31= fee							
Depth to water below land surface:				11"		-	oressure:		psi x 2.31			
				5.0		iiut iii j	oressure.		psi x 2.31			eet
Measurement Statu Measurement Meth			Pumping ☐ Airline ☐	Ris Oth		ving 🗌	Other					-
Length of time well was idle prior to measurement: 24 HOURS												
Measuring point description: TOP OF WELL. REMOVED PITLESS WELL CAP.												
The measuring point is the reference point from which the measurement is made. Examples are: 1/2" access port in well cap; 1-1/2" port pipe on N side; pressure gage.												
Comments:												
When did water use begin for this well under this permit? Month 10 Year 2016												
I hereby certify that	the information	tion on	this report is acc	curate	e and represents	s the sta	atic water level	in the well	at the time	of me	asurement.	
Person making mea Signature of measur Company: Oregon Licensed number (c Daytime phone num Email address: pum	rer: • Water Servircle license	vices type: C	WRE, RG, PE,	wwo	C, Pump Install	er): C	CB#133505. (CPI:7-103				

If you have any questions about this notice, please call the Measurement & Reporting Section of the Department at 503-986-0822. Return this Form to: OWRD, Meas & Rept Section, 725 Summer St. NE, Suite. A, Salem, OR 97301-1266 or email as an attachment to reportingmmts@wrd.state.or.us. Additional forms can be obtained from our web site at: www.oregon.gov/owrd/