

---

March 2, 2022

**\*\* LABORATORY ANALYSIS REPORT \*\***

---

Radon test result report for:  
**HILLIARD HOUSE**

---

<b>Kit #</b>	<b>Room Id</b>	<b>Started</b>	<b>Ended</b>	<b>pCi/L</b>	<b>Analyzed</b>
9627768	CENTER BEDROOM	2022-02-22 @ 7:00 am	2022-02-25 @ 7:00 am	< 0.3	2022-03-02
9627796	E BEDROOM	2022-02-22 @ 7:00 am	2022-02-25 @ 7:00 am	2.6 ± 0.5	2022-03-02
9627760	FRONT ROOM	2022-02-22 @ 7:00 am	2022-02-25 @ 7:00 am	2.7 ± 0.5	2022-03-02
9627769	ROOM N OF KITCHEN	2022-02-22 @ 7:00 am	2022-02-25 @ 7:00 am	3.0 ± 0.5	2022-03-02
9627756	ROOM N OF KITCHEN	2022-02-22 @ 7:00 am	2022-02-25 @ 7:00 am	2.4 ± 0.5	2022-03-02
9627661	S ROOM	2022-02-22 @ 7:00 am	2022-02-25 @ 7:00 am	2.7 ± 0.4	2022-03-02
9627795	W BEDROOM	2022-02-22 @ 7:00 am	2022-02-25 @ 7:00 am	2.2 ± 0.4	2022-03-02

---

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498