

| Roosevelt MS- Lead Water Testing 2023 | | Water Test | | | Retest (if needed) | | | 2nd Retest (if needed) | | | Resolution- Action Items |
|---------------------------------------|-----------------|--------------|----------------|--------------|--------------------|-------------|--------------|------------------------|-------------|--------------|--------------------------|
| Location | Fixture Type | Date Sampled | Sample ID # | Result (ppb) | Date Sampled | Sample ID # | Result (ppb) | Date Sampled | Sample ID # | Result (ppb) | |
| East Gymnasium Entrance | Fountain | 10/7/22 | 20821400-181DW | 0.3 | | | | | | | |
| East Gymnasium Entrance | Fountain | 10/7/22 | 20821400-182DW | 0.6 | | | | | | | |
| East Gymnasium Entrance | Bottle Filler | 10/7/22 | 20821400-183WB | ND | | | | | | | |
| Nurses Office | Ice Machine | 10/7/22 | 20821400-188IM | 3.0 | | | | | | | |
| Room 125 | Sink | 10/7/22 | 20821400-064BF | 1.0 | | | | | | | |
| Room 129 | Sink | 10/7/22 | 20821400-136CF | 0.3 | | | | | | | |
| Room 137 | Sink | 10/7/22 | 20821400-148SF | 0.8 | | | | | | | |
| Room 143 | Sink | 10/7/22 | 20821400-009CF | ND | | | | | | | |
| Staff Room Restroom | Sink | 10/7/22 | 20821400-054BF | ND | | | | | | | |
| 2nd Floor East Hallway | Fountain | 10/7/22 | 20821400-056DW | 0.3 | | | | | | | |
| Staff Room | Water Dispenser | 10/7/22 | 20821400-052OT | ND | | | | | | | |
| Staff Room | Ice Machine | 10/7/22 | 20821400-187IM | ND | | | | | | | |
| Room 212 | Sink | 10/7/22 | 20821400-050CF | ND | | | | | | | |
| Room 213 | Sink | 10/7/22 | 20821400-048CF | 0.3 | | | | | | | |
| Room 213 | Fountain | 10/7/22 | 20821400-049DW | ND | | | | | | | |
| Room 217 | Fountain | 10/7/22 | 20821400-043DW | ND | | | | | | | |
| Room 151 | Fountain | 10/7/22 | 20821400-128DW | 0.4 | | | | | | | |
| Room 153 | Sink | 10/7/22 | 20821400-125CF | 0.2 | | | | | | | |
| Room 155 | Sink | 10/7/22 | 20821400-118CF | 0.4 | | | | | | | |
| Room 155 | Sink | 10/7/22 | 20821400-119CF | ND | | | | | | | |
| Room 155 | Sink | 10/7/22 | 20821400-123CF | ND | | | | | | | |
| Room 155 | Sink | 10/7/22 | 20821400-121CF | ND | | | | | | | |
| Kitchen | Sink | 10/7/22 | 20821400-115KF | 0.9 | | | | | | | |
| Kitchen | Sink | 10/7/22 | 20821400-112KF | ND | | | | | | | |
| Kitchen | Kettle Faucet | 10/7/22 | 20821400-184OT | 0.6 | | | | | | | |
| Kitchen | Sink | 10/7/22 | 20821400-102KF | ND | | | | | | | |
| Kitchen | Sprayer | 10/7/22 | 20821400-103KF | ND | | | | | | | |
| Room 188, Right | Sink | 10/7/22 | 20821400-178CF | 0.3 | | | | | | | |
| Room 188, Left | Sink | 10/7/22 | 20821400-179CF | 0.3 | | | | | | | |
| Room 191 | Fountain | 10/7/22 | 20821400-177DW | ND | | | | | | | |
| Science Prep Room | Sink | 10/7/22 | 20821400-166SF | 0.7 | | | | | | | |
| Room 193 | Sink | 10/7/22 | 20821400-173CF | 0.2 | | | | | | | |
| Room 193 | Fountain | 10/7/22 | 20821400-174DW | ND | | | | | | | |
| Room 195 | Sink | 10/7/22 | 20821400-163CF | ND | | | | | | | |
| Room 195 | Fountain | 10/7/22 | 20821400-164DW | ND | | | | | | | |
| Room 196 | Sink | 10/7/22 | 20821400-154SF | ND | | | | | | | |
| Room 196 | Ice Machine | 10/7/22 | 20821400-189IM | 0.4 | | | | | | | |
| Room 197 | Fountain | 10/7/22 | 20821400-156DW | ND | | | | | | | |
| Hall 185 | Fountain | 10/7/22 | 20821400-109CF | 0.5 | | | | | | | |
| Room 215 | Fountain | 10/7/22 | 20821400-044CF | ND | | | | | | | |

Fixtures not listed above tested below 1.0 parts per billion (ppb) during initial testing in 2016. Since Roosevelt MS was built after 2014 with lead-free standards and initial testing was below 1 ppb, these fixtures are exempt from future testing per OAR 333-061-0400
ND test result- lead was not detected