

Spencer Butte MS- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Kitchen	Sink	10/5/22	20821500-135KF	0.4							
Kitchen	Sink	10/5/22	20821500-127KF	2.1							
Kitchen Bathroom	Sink	10/5/22	20821500-131BF	1.4							
Cafeteria	Fountain	10/5/22	20821500-129DW	ND							
Cafeteria	Bottle Filler	10/5/22	20821500-128WB	ND							
Cafeteria Staff Room	Sink	10/5/22	20821500-130SF	20.2	11/8/22	20821500-130SF	1.2				Replaced fixture 11/1/22
Staff Room	Sink	10/5/22	20821500-138SF	0.2							
Cafeteria Women's Restroom-Right	Sink	10/5/22	20821500-125BF	0.7							
Cafeteria Women's Restroom-Left	Sink	10/5/22	20821500-124BF	1.0							
Cafeteria Men's Restroom-Left	Sink	10/5/22	20821500-126BF	0.5							
Cafeteria Men's Restroom-Center	Sink	10/5/22	20821500-133BF	1.0							
Cafeteria Men's Restroom-Right	Sink	10/5/22	20821500-134BF	0.6							
Main Office Conference Room	Sink	10/5/22	20821500-150SF	3.8							
Main Office Conference Room	Fountain	10/5/22	20821500-151DW	1.3							
Main Office Nurses Office	Fountain	10/5/22	20821500-149DW	2.8							
Main Office Nurses Office	Sink	10/5/22	20821500-120NF	2.8							
Main Office Restroom	Sink	10/5/22	20821500-119BF	0.2							
Main Office Sink	Sink	10/5/22	20821500-116SF	0.4							
Main Office Gender Neutral Rest	Sink	10/5/22	20821500-117BF	0.3							
North Wing Hallway	Bottle Filler	10/5/22	20821500-114WB	ND							
North Wing Hallway	Fountain	10/5/22	20821500-115DW	ND							
Custodial Room	Sink	10/5/22	20821500-113SF	2.8							
Music Room	Fountain	10/5/22	20821500-111DW	0.3							
Music Room	Sink	10/5/22	20821500-112CF	0.8							
Hallway @ Gym	Bottle Filler	10/5/22	20821500-109WB	ND							
Hallway @ Gym	Fountain	10/5/22	20821500-110DW	ND							
Large Gym	Fountain	10/5/22	20821500-107DW	0.3							
Boys Locker Room	Sink	10/5/22	20821500-102BF	0.4							
Boys Locker Room	Sink	10/5/22	20821500-103BF	0.7							
Boys Locker Room Staff Restroom	Sink	10/5/22	20821500-105BF	4.1							
North Gym Wing Boys Restroom-Right	Sink	10/5/22	20821500-099BF	0.4							
North Gym Wing Boys Restroom-Left	Sink	10/5/22	20821500-100BF	0.3							
North Gym Wing Girls Restroom-Right	Sink	10/5/22	20821500-096BF	0.4							
North Gym Wing Girls Restroom-Left	Sink	10/5/22	20821500-097BF	0.4							
Girls Locker Room Staff Restroom	Sink	10/5/22	20821500-090BF	4.8							
Girls Locker Room-Right	Sink	10/5/22	20821500-088BF	0.4							
Girls Locker Room-Left	Sink	10/5/22	20821500-089BF	0.5							
Girls Locker Room	Fountain	10/5/22	20821500-075DW	15.2	11/8/22	20821500-075DW	1.4				Replaced fixture 11/1/22
Small Gym	Fountain	10/5/22	20821500-091DW	0.7							
Room 36	Sink	10/5/22	20821500-095CF	1.1							
Room 36	Sink	10/5/22	20821500-147CF	0.5							
Room 36	Sink	10/5/22	20821500-094CF	0.4							
Room 34	Sink	10/5/22	20821500-148CF	1.0							
Room 33	Sink	10/5/22	20821500-104CF	1.5							
South Wing Center Hallway	Fountain	10/5/22	20821500-044DW	0.2							
South Wing Center Hallway	Bottle Filler	10/5/22	20821500-045WB	ND							
Library Work Room	Sink	10/5/22	20821500-042SF	2.5							
Life Skills Room	Sink	10/5/22	20821500-039BF	1.8							
IMC	Fountain	10/5/22	20821500-035DW	2.5							
Southeast Wing Women's Restroom-Right	Sink	10/5/22	20821500-143BF	1.1							
Southeast Wing Women's Restroom-Center	Sink	10/5/22	20821500-144BF	1.1							
Southeast Wing Women's Restroom-Left	Sink	10/5/22	20821500-145BF	1.4							
Southeast Wing Men's Restroom-Right	Sink	10/5/22	20821500-028BF	0.8							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.

ND test result- lead was not detected

Spencer Butte MS- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Southeast Wing Men's Restroom-Center	Sink	10/5/22	20821500-029BF	1.1							
Southeast Wing Men's Restroom-Left	Sink	10/5/22	20821500-030BF	1.8							
Southeast Hallway	Fountain	10/5/22	20821500-023DW	0.7							
Room 5	Sink	10/5/22	20821500-021CF	25.2	11/8/22	20821500-021CF	2.0				Replaced fixture 11/1/22
Room 5	Fountain	10/5/22	20821500-022DW	1.1							
Room 3	Sink	10/5/22	20821500-017CF	0.3							
Room 3	Fountain	10/5/22	20821500-018DW	0.6							
Room 1	Sink	10/5/22	20821500-011CF	1.7							
Room 1	Fountain	10/5/22	20821500-012DW	0.9							
Room 2 Storage Room	Utility Sink	10/5/22	20821500-007SF	39.9	Mixing Valve Installed at non-potable fixture						Mixing Valve installed 11/3/22, non-potable signage
Room 2 Prep Room	Sprayer	10/5/22	20821500-006CF	1.4							
Room 2 Prep Room	Sink	10/5/22	20821500-005SF	1.6							
Room 2 Prep Room	Insta-Hot	10/5/22	20821500-146OT	0.4							
Room 6	Sink	10/5/22	20821500-019CF	9.0							
Room 6	Fountain	10/5/22	20821500-020DW	12.2							
Room 6A	Sink	10/5/22	20821500-025SF	0.5							
Room 8	Sink	10/5/22	20821500-038CF	2.8							
Room 8	Sink	10/5/22	20821500-033CF	0.7							
Room 8	Sink	10/5/22	20821500-032CF	ND							
Room 8	Sink	10/5/22	20821500-027CF	0.3							
Room 8	Sink	10/5/22	20821500-031CF	28.0	11/8/22	20821500-031CF	0.7				Replaced fixture 11/1/22
Room 8	Sink	10/5/22	20821500-036CF	23.1	11/8/22	20821500-036CF	1.5				Replaced fixture 11/1/22
Room 8	Sink	10/5/22	20821500-037CF	4.0							
Southwest Wing Women's Restroom-Right	Sink	10/5/22	20821500-048BF	0.5							
Southwest Wing Women's Restroom-Left	Sink	10/5/22	20821500-049BF	0.8							
Southwest Wing Men's Restroom-Left	Sink	10/5/22	20821500-050BF	0.7							
Southwest Wing Men's Restroom-Right	Sink	10/5/22	20821500-051BF	0.6							
Southwest Wing Staff Restroom	Sink	10/5/22	20821500-053BF	2.7							
Southwest Wing Hallway	Fountain	10/5/22	20821500-054DW	0.6							
Southwest Wing Staff Unisex Restroom-Left	Sink	10/5/22	20821500-057BF	0.6							
Southwest Wing Staff Unisex Restroom-Right	Sink	10/5/22	20821500-058BF	0.8							
Southwest Wing Staff Room	Sink	10/5/22	20821500-059SF	0.4							
Southwest Wing Central Hallway	Fountain	10/5/22	20821500-060DW	ND							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.
ND test result- lead was not detected