

Scope of work in conjunction with Specs.

- 1) All windows and window frames must be ordered from Arcadia Glass pre-manufactured
- 2) The windows have asbestos and paint have lead, so contractor is responsible for abatement and clearance certification
- 3) All furniture is to be moved and covered by contractor
- 4) All furniture is to be returned to its original location and everything must be cleaned
- 5) Contractor is responsible for covering the windows with plywood and securing the building and its contents
- 6) Contractor is to provide their own portable restroom
- 7) Contractor is to arrange all working hours with Project Manager
- 8) All windows must be finished from both sides in Horizon blue
- 9) Contractor is responsible for all materials
- 10) Contractor is responsible for clean-up
- 11) Contractor is follow specs and plans accordingly along with the following requirements mentioned above
- 12) Contractor is responsible for all the paint around the windows