

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
Bailey Hill															
Room 11	Sink	7/11/16	BAHES-I-001	483.00	9/2/16	BAHES-F-081	4.37	9/29/16	10/1/16	BAHES-I-117	15.30				
Room 11	Fountain	7/11/16	BAHES-I-002	35.90	9/2/16	BAHES-F-080	7.43	Decommissioned	Decommissioned	Decommissioned					
Hallway outside Room 12	Fountain	7/11/16	BAHES-I-003	22.80	9/2/16	BAHES-F-075	2.10	9/29/16	10/1/16	BAHES-I-113	11.90				
Room 12	Sink	7/11/16	BAHES-I-004	57.80	9/2/16	BAHES-F-078	2.69	9/29/16	10/1/16	BAHES-I-115	6.21				
Room 12	Fountain	7/11/16	BAHES-I-005	25.30	9/2/16	BAHES-F-077	1.42	Decommissioned	Decommissioned	Decommissioned					
Room 12 East Restroom	Sink	7/11/16	BAHES-I-006	47.60	9/2/16	BAHES-F-076	1.73	9/29/16	10/1/16	BAHES-I-114	6.01				
Room 12 West Restroom	Sink	7/11/16	BAHES-I-007	4.07											
Room 11 West Restroom	Sink	7/11/16	BAHES-I-008	19.80	9/2/16	BAHES-F-079	1.69	9/29/16	10/1/16	BAHES-I-116	10.30				
Room 10 West Restroom	Sink	7/11/16	BAHES-I-009	18.80											
North Hall Men's Restroom (South)	Sink	7/11/16	BAHES-I-010	19.10											
North Hall Men's Restroom (North)	Sink	7/11/16	BAHES-I-011	37.40	No Flush Taken	No Flush Taken		10/19/16	10/20/16	BAHES-I-137	24.50	New gate valve, replaced multiple solder fittings.	12/1/16	BAHES-I-138	11.10
North Hall Women's Restroom (North)	Sink	7/11/16	BAHES-I-012	20.20	9/2/16	BAHES-F-072	1.74	9/29/16	10/1/16	BAHES-I-110	41.70	New gate valve, replaced multiple solder fittings.	12/1/16	BAHES-I-139	13.70
North Hall Women's Restroom (South)	Sink	7/11/16	BAHES-I-013	222.00	9/2/16	BAHES-F-073	45.30	9/29/16	10/1/16	BAHES-I-111	28.80	New gate valve, replaced multiple solder fittings. Non Potable sources. Non-Potable stickers applied at location. For further action taken.	12/1/16	BAHES-I-140	43.00
Room 13	Sink	7/11/16	BAHES-I-014	22.70	9/2/16	BAHES-F-071	7.30	9/29/16	10/1/16	BAHES-I-109	9.27				
Room 13	Fountain	7/11/16	BAHES-I-015	58.80	9/2/16	BAHES-F-070	18.60	9/29/16	10/1/16	BAHES-I-108	67.30	New gate valve, replaced multiple solder fittings.	12/1/16	BAHES-I-141	10.40
Room 14	Sink	7/11/16	BAHES-I-016	932.00	9/2/16	BAHES-F-069	2.94	Decommissioned	Decommissioned	Decommissioned					
Room 14	Fountain	7/11/16	BAHES-I-017	911.00	9/2/16	BAHES-F-068	13.20	Decommissioned	Decommissioned	Decommissioned					
Room 15	Sink	7/11/16	BAHES-I-018	673.00	9/2/16	BAHES-F-066	49.00	Decommissioned	Decommissioned	Decommissioned					
Room 15	Fountain	7/11/16	BAHES-I-019	271.00	9/2/16	BAHES-F-065	5.49	Decommissioned	Decommissioned	Decommissioned					
Room 16	Sink	7/11/16	BAHES-I-020	323.00	9/2/16	BAHES-F-067	11.20	Decommissioned	Decommissioned	Decommissioned					
Health Center Restroom	Sink	7/11/16	BAHES-I-021	36.00	9/2/16	BAHES-F-084	3.44	9/29/16	10/1/16	BAHES-I-119	9.04				
Health Center	Sink	7/11/16	BAHES-I-022	38.50	9/2/16	BAHES-F-085	4.96	9/29/16	10/1/16	BAHES-I-120	1.08				
Staff Room	Sink	7/11/16	BAHES-I-023	8.15											
Instructional Materials Center	Sink	7/11/16	BAHES-I-024	14.80											
Hallway outside Multi Purpose Room	Fountain	7/11/16	BAHES-I-025	8.22											
Main Hall Women's Restroom	Sink	7/11/16	BAHES-I-026	11.30											
Main Hall Men's Restroom	Sink	7/11/16	BAHES-I-027	5.17											
Kitchen Handwash Sink	Sink	7/11/16	BAHES-I-028	12.00											
Kitchen Dish Sink	Sprayer	7/11/16	BAHES-I-029	4.29											
Kitchen Dish Sink	Sink	7/11/16	BAHES-I-030	8.32											
Kitchen	Ice Machine	7/11/16	BAHES-I-031	ND											
Library Storage	Sink	7/11/16	BAHES-I-032	10.90											
Room 9 South Restroom	Sink	7/11/16	BAHES-I-033	46.20	9/2/16	BAHES-F-086	1.71	9/29/16	10/1/16	BAHES-I-121	136.00	New gate valve, replaced multiple solder fittings. Non Potable sources. Non-Potable stickers applied at location. For further action taken.	12/1/16	BAHES-I-142	55.80
Room 9	Sink	7/11/16	BAHES-I-034	32.20	9/2/16	BAHES-F-088	ND	9/29/16	10/1/16	BAHES-I-122	1.68				
Room 9	Fountain	7/11/16	BAHES-I-035	21.10	9/2/16	BAHES-F-087	4.35	Decommissioned	Decommissioned	Decommissioned					
Room 8 North Restroom	Sink	7/11/16	BAHES-I-036	46.10	9/2/16	BAHES-F-089	1.57	9/29/16	10/1/16	BAHES-I-123	15.40				
Room 8 South Restroom	Sink	7/11/16	BAHES-I-037	236.00	9/2/16	BAHES-F-090	4.42	9/29/16	10/1/16	BAHES-I-124	53.00	New gate valve, replaced multiple solder fittings. Non Potable sources. Non-Potable stickers applied at location. For further action taken.	12/1/16	BAHES-I-143	52.80
Room 8	Sink	7/11/16	BAHES-I-038	21.20	9/2/16	BAHES-F-091	3.48	9/29/16	10/1/16	BAHES-I-125	8.03				
Room 8	Fountain	7/11/16	BAHES-I-039	11.20											
Room 7 North Restroom	Sink	7/11/16	BAHES-I-040	16.10											
Room 7 South Restroom	Sink	7/11/16	BAHES-I-041	13.80											
Room 7	Sink	7/11/16	BAHES-I-042	8.12											
Room 3 Boys Restroom	Sink	7/11/16	BAHES-I-043	13.50											
Room 3 Girls Restroom	Sink	7/11/16	BAHES-I-044	32.50	9/2/16	BAHES-F-097	3.96	9/29/16	10/1/16	BAHES-I-130	3.30				
Room 3 East entry	Fountain	7/11/16	BAHES-I-045	14.80											
Room 3 Southwest corner	Sink	7/11/16	BAHES-I-046	40.90	9/2/16	BAHES-F-099	4.23	9/29/16	10/1/16	BAHES-I-132	23.50	New gate valve, replaced multiple solder fittings.	12/1/16	BAHES-I-144	15.60
Room 3 Southwest corner	Fountain	7/11/16	BAHES-I-047	31.40	9/2/16	BAHES-F-098	11.30	9/29/16	10/1/16	BAHES-I-131	8.27				
Room 1	Sink	7/11/16	BAHES-I-048	92.80	9/2/16	BAHES-F-094	6.03	9/29/16	10/1/16	BAHES-I-127	24.60	New gate valve, replaced multiple solder fittings.	12/1/16	BAHES-I-145	4.90
Room 1	Fountain	7/11/16	BAHES-I-049	37.00	9/2/16	BAHES-F-093	5.13	9/29/16	10/1/16	BAHES-I-126	10.40				
Room 1/2 Boys Restroom	Sink	7/11/16	BAHES-I-050	35.40	9/2/16	BAHES-F-095	25.00	9/29/16	10/1/16	BAHES-I-128	2.07				
Room 1/2	Fountain	7/11/16	BAHES-I-051	7.00											
Room 1/2 Girls Restroom	Sink	7/11/16	BAHES-I-052	15.40											
Room 2	Sink	7/11/16	BAHES-I-053	149.80	9/2/16	BAHES-F-096	11.50	9/29/16	10/1/16	BAHES-I-129	26.50	New gate valve, replaced multiple solder fittings.	12/1/16	BAHES-I-146	7.27
Room 2	Fountain	7/11/16	BAHES-I-054	18.30											
Room 5	Sink	7/11/16	BAHES-I-055	135.00	9/2/16	BAHES-F-100	2.09	9/29/16	10/1/16	BAHES-I-133	12.50	New gate valve, replaced multiple solder fittings.	12/1/16	BAHES-I-147	4.72
Room 5	Fountain	7/11/16	BAHES-I-056	4.86											
Room 4/5 Girls Restroom	Sink	7/11/16	BAHES-I-057	6.97											
Room 4/5 Boys Restroom	Sink	7/11/16	BAHES-I-058	10.10											
Room 4 Southeast Corner	Sink	7/11/16	BAHES-I-059	2.70											
Room 4	Sink	7/11/16	BAHES-I-060	28.90	9/2/16	BAHES-F-102	1.85	9/29/16	10/1/16	BAHES-I-134	5.61				
Room 4	Fountain	7/11/16	BAHES-I-061	13.90											
Room 6 Girls Restroom	Sink	7/11/16	BAHES-I-062	9.90											
Room 6	Fountain	7/11/16	BAHES-I-063	7.91											
Room 6 Boys Restroom	Sink	7/11/16	BAHES-I-064	18.50	9/2/16	BAHES-F-103	1.77	9/29/16	10/1/16	BAHES-I-135	4.19				
Room 10	Fountain	9/2/16	BAHES-I-062	22.50	Decommissioned	Decommissioned		Decommissioned	Decommissioned	Decommissioned					
Room 10	Sink	9/2/16	BAHES-I-083	130.00	10/1/16	BAHES-F-106	21.60	Decommissioned	Decommissioned	Decommissioned					
East Wall Between Rooms 4/5	Fountain	9/2/16	BAHES-I-101	2.65				10/19/16	10/20/16	BAHES-I-136	48.40	New gate valve, replaced multiple solder fittings.	12/1/16	BAHES-I-148	7.81
Room 7	Sprayer	9/2/16	BAHES-I-092	14.90											
Kitchen Office	Sink	9/2/16	BAHES-I-104	919.00	Decommissioned	Decommissioned		Decommissioned	Decommissioned	Decommissioned					
Room 16 - Decommissioned															