

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Cal Young Middle School											
Room 603	Sink	6/23/2016	CYMS-I-001	3.16							
Room 603	Fountain	6/23/2016	CYMS-I-002	ND							
Room 602	Sink	6/23/2016	CYMS-I-003	4.56							
Room 602	Fountain	6/23/2016	CYMS-I-004	0.20							
Room 601	Sink	6/23/2016	CYMS-I-005	5.30							
Room 601	Fountain	6/23/2016	CYMS-I-006	0.30							
Room 604	Sink	6/23/2016	CYMS-I-007	4.19							
Room 604	Fountain	6/23/2016	CYMS-I-008	0.21							
2nd Floor Girls Restroom (North)	Sink	6/23/2016	CYMS-I-009	1.39							
2nd Floor Girls Restroom (South)	Sink	6/23/2016	CYMS-I-010	2.22							
2nd Floor Corridor (Upper)	Fountain	6/23/2016	CYMS-I-011	0.28							
2nd Floor Corridor (Lower)	Fountain	6/23/2016	CYMS-I-012	0.23							
2nd Floor Boys Restroom (North)	Sink	6/23/2016	CYMS-I-013	0.78							
2nd Floor Boys Restroom (South)	Sink	6/23/2016	CYMS-I-014	2.00							
Room 608	Sink	6/23/2016	CYMS-I-015	1.93							
Room 608	Insta-Hot	6/23/2016	CYMS-I-016	0.49							
Room 707	Sink	6/23/2016	CYMS-I-017	6.14							
Room 707	Fountain	6/23/2016	CYMS-I-018	ND							
2nd Floor Student Restroom	Sink	6/23/2016	CYMS-I-019	1.06							
2nd Floor Staff Restroom	Sink	6/23/2016	CYMS-I-020	0.62							
Room 706	Sink	6/23/2016	CYMS-I-021	1.17							
Room 706	Fountain	6/23/2016	CYMS-I-022	ND							
Room 701	Sink	6/23/2016	CYMS-I-023	5.39							
Room 701	Fountain	6/23/2016	CYMS-I-024	ND							
Room 702	Sink	6/23/2016	CYMS-I-025	4.76							
Room 702	Fountain	6/23/2016	CYMS-I-026	ND							
Room 705	Sink	6/23/2016	CYMS-I-027	1.54							
Room 705	Fountain	6/23/2016	CYMS-I-028	ND							
Room 704	Sink	6/23/2016	CYMS-I-029	4.32							
Room 704	Fountain	6/23/2016	CYMS-I-030	ND							
Room 703	Sink	6/23/2016	CYMS-I-031	4.63							
Room 703	Fountain	6/23/2016	CYMS-I-032	ND							
Room 203	Sink	6/23/2016	CYMS-I-033	0.70							
Room 203	Fountain	6/23/2016	CYMS-I-034	0.20							
Room 202	Sink	6/23/2016	CYMS-I-035	3.76							
Room 202	Fountain	6/23/2016	CYMS-I-036	ND							
Room 201	Sink	6/23/2016	CYMS-I-037	3.12							
Room 201	Fountain	6/23/2016	CYMS-I-038	ND							
Room 204 North Wall (West)	Sink	6/23/2016	CYMS-I-039	2.06							
Room 204 North Wall (Center)	Sink	6/23/2016	CYMS-I-040	0.98							
Room 204 North Wall (East)	Sink	6/23/2016	CYMS-I-041	4.87							
Room 204 North Wall	Fountain	6/23/2016	CYMS-I-042	0.20							
Room 204 South Wall (East)	Sink	6/23/2016	CYMS-I-043	0.97							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Cal Young Middle School</b>											
Room 204 South Wall (West)	Sink	6/23/2016	CYMS-I-044	0.56							
1st Floor Central Corridor Girls Restroom (North)	Sink	6/23/2016	CYMS-I-045	1.63							
1st Floor Central Corridor Girls Restroom (South)	Sink	6/23/2016	CYMS-I-046	1.59							
1st Floor Central Corridor Boys Restroom (North)	Sink	6/23/2016	CYMS-I-047	1.37							
1st Floor Central Corridor Boys Restroom (South)	Sink	6/23/2016	CYMS-I-048	1.91							
1st Floor Central Corridor (Upper)	Fountain	6/23/2016	CYMS-I-049	0.98							
1st Floor Central Corridor (Lower)	Fountain	6/23/2016	CYMS-I-050	1.21							
1st Floor Central Corridor Unisex Restroom	Sink	6/23/2016	CYMS-I-051	2.16							
1st Floor Central Corridor Men's Restroom	Sink	6/23/2016	CYMS-I-052	2.78							
1st Floor Central Corridor Women's Restroom	Sink	6/23/2016	CYMS-I-053	0.94							
Room 214 South Wall	Sink	6/23/2016	CYMS-I-054	1.70							
Room 214 East Wall	Sink	6/23/2016	CYMS-I-055	1.04							
Room 214 East Wall	Fountain	6/23/2016	CYMS-I-056	ND							
Room 208 North Wall (West)	Sink	6/23/2016	CYMS-I-057	3.78							
Room 208 North Wall (West)	Fountain	6/23/2016	CYMS-I-058	ND							
Room 208 North Wall (East)	Sink	6/23/2016	CYMS-I-059	4.06							
Room 208 East Wall (North)	Sink	6/23/2016	CYMS-I-060	4.12							
Room 208 East Wall (Center)	Sink	6/23/2016	CYMS-I-061	3.50							
Room 208 East Wall (South)	Sink	6/23/2016	CYMS-I-062	2.30							
Room 208 West Wall	Sink	6/23/2016	CYMS-I-063	2.73							
Science Prep Room	Sink	6/23/2016	CYMS-I-064	2.62							
Room 213 Large sink	Fountain	6/23/2016	CYMS-I-065	0.53							
Room 213 Large sink	Sink	6/23/2016	CYMS-I-066	5.54							
Room 213 Large sink	Sink	6/23/2016	CYMS-I-067	6.79							
Room 213 North West Corner Fixture	Sink	6/23/2016	CYMS-I-068	5.18							
Room 213 Large sink	Sink	6/23/2016	CYMS-I-069	5.33							
Room 212	Sink	6/23/2016	CYMS-I-070	2.79							
Room 212	Fountain	6/23/2016	CYMS-I-071	ND							
Room 209 North Wall (West)	Sink	6/23/2016	CYMS-I-072	2.92							
Room 209 North Wall (West)	Fountain	6/23/2016	CYMS-I-073	ND							
Room 209 North Wall (East)	Sink	6/23/2016	CYMS-I-074	4.74							
Room 209 West Wall (North)	Sink	6/23/2016	CYMS-I-075	3.87							
Room 209 West Wall (Center)	Sink	6/23/2016	CYMS-I-076	2.89							
Room 209 West Wall (South)	Sink	6/23/2016	CYMS-I-077	3.88							
Room 209 South East Corner	Sink	6/23/2016	CYMS-I-078	4.09							
Room 210 North Wall (West)	Sink	6/23/2016	CYMS-I-079	2.17							
Room 210 North Wall (West)	Fountain	6/23/2016	CYMS-I-080	ND							
Room 210 North Wall (East)	Sink	6/23/2016	CYMS-I-081	3.11							
Room 210 East Wall (North)	Sink	6/23/2016	CYMS-I-082	4.68							
Room 210 East Wall (Center)	Sink	6/23/2016	CYMS-I-083	3.88							
Room 210- East Wall (South)	Sink	6/23/2016	CYMS-I-084	2.22							
Room 210 SW Corner	Sink	6/23/2016	CYMS-I-085	2.78							
Room 211 West Wall	Sink	6/23/2016	CYMS-I-086	4.07							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Cal Young Middle School</b>											
Room 211 West Wall	Fountain	6/23/2016	CYMS-I-087	ND							
Room 211 East Wall	Sink	6/23/2016	CYMS-I-088	4.07							
Room 211 East Wall	Fountain	6/23/2016	CYMS-I-089	ND							
Room 301	Sink	6/23/2016	CYMS-I-090	4.46							
Room 301	Fountain	6/23/2016	CYMS-I-091	ND							
Room 302	Sink	6/23/2016	CYMS-I-092	4.88							
Room 302	Fountain	6/23/2016	CYMS-I-093	ND							
Cafeteria 410 (Lower)	Fountain	6/23/2016	CYMS-I-094	0.20							
Cafeteria 410 (Upper)	Fountain	6/23/2016	CYMS-I-095	0.20							
Kitchen Handwashing Sink	Sink	6/23/2016	CYMS-I-096	1.98							
Kitchen Dishwasher Area	Sink	6/23/2016	CYMS-I-097	0.52							
Kitchen Prep Area Handwashing Sink	Sink	6/23/2016	CYMS-I-098	3.69							
Kitchen Area Staff Restroom	Sink	6/23/2016	CYMS-I-099	0.93							
Girls Locker Room Restroom (West)	Sink	6/23/2016	CYMS-I-100	4.53							
Girls Locker Room Restroom (East)	Sink	6/23/2016	CYMS-I-101	4.80							
Girls Locker Room Coaches Office Restroom	Sink	6/23/2016	CYMS-I-102	4.23							
Gym Corridor North End (Upper)	Fountain	6/23/2016	CYMS-I-103	ND							
Gym Corridor North End (Lower)	Fountain	6/23/2016	CYMS-I-104	0.42							
Boys Locker Room Restroom (West)	Sink	6/23/2016	CYMS-I-105	8.71							
Boys Locker Room Restroom (East)	Sink	6/23/2016	CYMS-I-106	6.90							
North Corridor Boys Restroom	Sink	6/23/2016	CYMS-I-107	1.23							
North Corridor Girls Restroom	Sink	6/23/2016	CYMS-I-108	0.90							
Administrative Staff Men's Restroom	Sink	6/23/2016	CYMS-I-109	2.16							
Administrative Staff Women's Restroom	Sink	6/23/2016	CYMS-I-110	0.92							
Staff Lounge	Sink	6/23/2016	CYMS-I-111	0.76							
Staff Lounge	Insta-Hot	6/23/2016	CYMS-I-112	ND							
Health Room Restroom	Sink	6/23/2016	CYMS-I-113	3.28							
Health Room Restroom	Sink	6/23/2016	CYMS-I-114	2.62							
Kitchen Produce Sink	Sink	9/7/2016	CYMS-I-115	6.11							
Unisex Coaches Office Restroom	Sink	9/7/2016	CYMS-I-116	ND							
Staff Room Refrigerator - South	Ice Machine	10/8/2016	CYMS-I-117	ND							
Staff Room Refrigerator - North	Ice Machine	10/8/2016	CYMS-I-118	1.79							
Science Prep Between Room 208 & 209 Refrigerator	Ice Machine	10/8/2016	CYMS-I-119	1.90							
Science Prep Between Room 208 & 209 - Stand Alone	Ice Machine	10/8/2016	CYMS-I-120	ND							
Room 608 Refrigerator	Ice Machine	10/8/2016	CYMS-I-121	6.83							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.