

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
4J Education Center											
Financial Services Breakroom	Sink	7/6/2016	EDCEN-I-001	2.28							
Financial Services Breakroom	Insta-Hot	7/6/2016	EDCEN-I-002	0.91							
Outside Parr Room (B-249)	Sink	7/6/2016	EDCEN-I-003	1.36							
Outside Parr Room (B-249)	Insta-Hot	7/6/2016	EDCEN-I-004	0.38							
Instruction Offices Breakroom	Sink	7/6/2016	EDCEN-I-005	4.56							
Restroom in Breezeway outside Instruction	Sink	7/6/2016	EDCEN-I-006	7.57							
Women's Restroom Breezeway Outside Instruction	Sink	7/6/2016	EDCEN-I-007	3.57							
HR & Risk Management Breakroom	Sink	7/6/2016	EDCEN-I-008	2.20							
Nutrition Services Restroom	Sink	7/6/2016	EDCEN-I-009	1.07							
Nutrition Services Large Basin South Wall	Sink	7/6/2016	EDCEN-I-010	2.32							
Nutrition Services Handwash West Wall	Sink	7/6/2016	EDCEN-I-011	2.93							
Nutrition Services Dishwash Area Faucet	Sink	7/6/2016	EDCEN-I-012	2.51							
Tech Dept Break Room	Sink	7/6/2016	EDCEN-I-013	7.32							
Main Entrance Men's Restroom (Right)	Sink	7/6/2016	EDCEN-I-014	1.49							
Main Entrance Hallway to Left by FRC	Fountain	7/6/2016	EDCEN-I-015	ND							
Main Entrance Women's Restroom (Left)	Sink	7/6/2016	EDCEN-I-016	0.88							
Main Entrance Women's Restroom (Right)	Sink	7/6/2016	EDCEN-I-017	0.60							
Ed Support Services Breakroom	Sink	7/6/2016	EDCEN-I-018	2.30							
Library Services Women's Restroom	Sink	7/6/2016	EDCEN-I-019	1.29							
Library Services Small Hallway by Women's RR	Sink	7/6/2016	EDCEN-I-020	0.30							
ESS Records Breakroom	Sink	7/6/2016	EDCEN-I-021	2.96							
Custodial Office Main Work Room	Sink	7/6/2016	EDCEN-I-022	2.22							
Custodial Office Main Work Room	Insta-Hot	7/6/2016	EDCEN-I-023	1.76							
Custodial Office Main Work Room	Fountain	7/6/2016	EDCEN-I-024	0.56							
Custodial Office Hallway Across from RR	Fountain	7/6/2016	EDCEN-I-025	0.51							
Custodial Office Women's Restroom	Sink	7/6/2016	EDCEN-I-026	1.43							
Custodial Office Men's Restroom	Sink	7/6/2016	EDCEN-I-027	1.78							
Main Entrance - Men's Restroom Left	Sink	7/21/2016	EDCEN-I-028	ND							
Instruction Department - Kitchen Insta Hot	Insta-Hot	7/21/2016	EDCEN-I-029	ND							
Nutrition Dept - Kitchen Sprayer Next to Dishwasher	Sink	7/21/2016	EDCEN-I-030	3.52							
Warehouse Women's Restroom West Wall	Sink	7/21/2016	EDCEN-I-031	1.11							
Warehouse Men's Restroom North Wall	Sink	7/21/2016	EDCEN-I-032	4.02							
Custodial - Men's Restroom North Wall	Sink	7/21/2016	EDCEN-I-033	1.15							
Custodial - Women's Restroom South Wall	Sink	7/21/2016	EDCEN-I-034	1.10							
Unisex Restroom North Wall	Sink	7/21/2016	EDCEN-I-035	0.38							
East Wall Hallway	Sink	7/21/2016	EDCEN-I-036	6.08							
South Wall Hallway	Sink	7/21/2016	EDCEN-I-037	2.03							
Exam Room, Southeast Corner	Sink	7/21/2016	EDCEN-I-038	10.70							
Exam Room, Middle Hallway SE Room	Sink	7/21/2016	EDCEN-I-039	6.11							
Exam Room Middle Hallway NE Room	Sink	7/21/2016	EDCEN-I-040	0.75							
Exam Room Middle Hallway South Middle Room	Sink	7/21/2016	EDCEN-I-041	6.51							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location		First Draw			Flushed Draw			New Fixture First Draw			
4J Education Center	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Hand Sink Middle Hallway	Sink	7/21/2016	EDCEN-I-042	0.49							
Exam Room Middle Hallway North Middle Room	Sink	7/21/2016	EDCEN-I-043	1.27							
Exam Room Middle Hallway SW Room	Sink	7/21/2016	EDCEN-I-044	2.36							
Exam Room Middle Hallway NW Room	Sink	7/21/2016	EDCEN-I-045	0.77							
Food Services North Wall	Ice Machine	8/5/2016	EDCEN-I-046	ND							
Food Services Coffee Maker (Hard Piped Coffee Maker)	Insta-Hot	9/24/2016	EDCEN-I-047	ND							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.