

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Facilities Department											
Electrical Room	Fountain	6/30/2016	FACMAN-I-001	ND							
Electrical Room	Bottlefiller	6/30/2016	FACMAN-I-002	ND							
1st Floor Men's Restroom	Sink	6/30/2016	FACMAN-I-003	0.90							
1st Floor Shower Room	Sink	6/30/2016	FACMAN-I-004	0.37							
1st Floor Break Room	Insta-Hot	6/30/2016	FACMAN-I-005	0.77							
1st Floor Break Room	Sink	6/30/2016	FACMAN-I-006	2.00							
1st Floor Women's Restroom	Sink	6/30/2016	FACMAN-I-007	7.79							
2nd Floor Corridor	Fountain	6/30/2016	FACMAN-I-008	ND							
2nd Floor Corridor	Bottlefiller	6/30/2016	FACMAN-I-009	ND							
Room 21	Insta-Hot	6/30/2016	FACMAN-I-010	5.01							
Room 21	Sink	6/30/2016	FACMAN-I-011	4.83							
Room 22	Insta-Hot	6/30/2016	FACMAN-I-012	3.60							
Room 22	Sink	6/30/2016	FACMAN-I-013	8.71							
Room 23	Insta-Hot	6/30/2016	FACMAN-I-014	2.26							
Room 23	Sink	6/30/2016	FACMAN-I-015	1.53							
2nd Floor Unisex Restroom	Sink	6/30/2016	FACMAN-I-016	0.60							
Barn Building	Sink	6/30/2016	FACMAN-I-017	1.34							
Barn Building	Fountain	6/30/2016	FACMAN-I-018	0.70							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.