

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Fox Hollow Campus											
Instructional Materials Center	Sink	7/21/2016	CFHES-I-001	7.40							
Staff Room	Sink	7/21/2016	CFHES-I-002	1.88							
Staff Room	Insta-Hot	7/21/2016	CFHES-I-003	ND							
Women's Staff Restroom	Sink	7/21/2016	CFHES-I-004	0.33							
Office North of Staff Room	Sink	7/21/2016	CFHES-I-005	2.77							
Office North of Staff Room Restroom	Sink	7/21/2016	CFHES-I-006	1.08							
Men's Staff Restroom	Sink	7/21/2016	CFHES-I-007	5.85							
Room 9A (west)	Fountain	7/21/2016	CFHES-I-008	1.16							
Room 9A (west)	Sink	7/21/2016	CFHES-I-009	1.91							
Room 9A (west)	Fountain	7/21/2016	CFHES-I-010	0.57							
Room 9A (west)	Sink	7/21/2016	CFHES-I-011	1.77							
Room 3	Fountain	7/21/2016	CFHES-I-012	1.33							
Room 3	Sink	7/21/2016	CFHES-I-013	5.43							
Room 4	Fountain	7/21/2016	CFHES-I-014	0.65							
Room 4	Sink	7/21/2016	CFHES-I-015	0.91							
Boys Restroom between Rooms 2 & 4	Sink	7/21/2016	CFHES-I-016	2.02							
Girls Restroom between Rooms 2 & 4	Sink	7/21/2016	CFHES-I-017	1.55							
Janitorial closet between Rooms 2 & 4	Sink	7/21/2016	CFHES-I-018	9.45							
Room 2	Fountain	7/21/2016	CFHES-I-019	1.16							
Room 2	Sink	7/21/2016	CFHES-I-020	1.37							
Room 1	Fountain	7/21/2016	CFHES-I-021	0.72							
Room 1	Sink	7/21/2016	CFHES-I-022	0.84							
Room 7	Fountain	7/21/2016	CFHES-I-023	0.71							
Room 7	Sink	7/21/2016	CFHES-I-024	0.60							
Room 8	Fountain	7/21/2016	CFHES-I-025	2.01							
Room 8	Sink	7/21/2016	CFHES-I-026	1.02							
Boys Restroom Between Rooms 6 & 8	Sink	7/21/2016	CFHES-I-027	0.67							
Girls Restroom between Room 6 & 8	Sink	7/21/2016	CFHES-I-028	0.40							
Janitorial closet between Rooms 6 & 8	Sink	7/21/2016	CFHES-I-029	2.14							
Room 6	Fountain	7/21/2016	CFHES-I-030	0.27							
Room 6	Sink	7/21/2016	CFHES-I-031	0.21							
Room 5	Fountain	7/21/2016	CFHES-I-032	1.50							
Room 5	Sink	7/21/2016	CFHES-I-033	1.51							
Room 10	Fountain	7/21/2016	CFHES-I-034	0.51							
Room 10	Sink	7/21/2016	CFHES-I-035	19.80							
Bottom of South Stairs	Fountain	7/21/2016	CFHES-I-036	0.60							
Mop Sink next to Gym	Sink	7/21/2016	CFHES-I-037	0.75							
Bottom of North Stairs	Fountain	7/21/2016	CFHES-I-038	2.01							
Boys Restroom by Gym	Sink	7/21/2016	CFHES-I-039	ND							
Girl's Restroom by Cafeteria (Left)	Sink	7/21/2016	CFHES-I-040	3.77							
Girls Restroom by Cafeteria (Right)	Sink	7/21/2016	CFHES-I-041	1.04							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location		First Draw			Flushed Draw			New Fixture First Draw			
Fox Hollow Campus	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Kitchen Hand Wash	Sink	7/21/2016	CFHES-I-042	1.88							
Kitchen	Sink	7/21/2016	CFHES-I-043	1.48							
Kitchen Sprayer	Sink	7/21/2016	CFHES-I-044	2.21							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.