

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Bertha Holt Elementary School											
Kitchen Handwash only East side island	Sink	6/23/2016	HOLES-I-001	0.61							
Kitchen West wall faucet	Sink	6/23/2016	HOLES-I-002	1.78							
kitchen west wall sprayer	Sink	6/23/2016	HOLES-I-003	1.11							
Kitchen eye wash sink faucet	Sink	6/23/2016	HOLES-I-004	3.53							
Kitchen handwash west side island	Sink	6/23/2016	HOLES-I-005	0.41							
kitchen dishwasher sink sprayer	Sink	6/23/2016	HOLES-I-006	0.60							
kitchen dishwasher sink faucet	Sink	6/23/2016	HOLES-I-007	1.61							
Wheelchair access Restroom by cafeteria	Sink	6/23/2016	HOLES-I-008	0.44							
Between Gym & Cafeteria Lower (Right)	Fountain	6/23/2016	HOLES-I-009	0.46							
Between Gym & Cafeteria Upper (Left)	Fountain	6/23/2016	HOLES-I-010	ND							
Girls Wheelchair access Restroom across from cafeteria (Far Left)	Sink	6/23/2016	HOLES-I-011	1.93							
Girls wheelchair access Restroom across from cafeteria (Mid Left)	Sink	6/23/2016	HOLES-I-012	1.36							
Girls wheelchair access Restroom across from cafeteria (Mid Right)	Sink	6/23/2016	HOLES-I-013	0.76							
Girls wheelchair access Restroom across from cafeteria (far Right)	Sink	6/23/2016	HOLES-I-014	0.63							
Boys wheelchair access Restroom across from cafeteria (far Left)	Sink	6/23/2016	HOLES-I-015	2.38							
Boys wheelchair access Restroom across from cafeteria (Mid Left)	Sink	6/23/2016	HOLES-I-016	1.76							
Boys wheelchair access Restroom across from cafeteria (Mid Right)	Sink	6/23/2016	HOLES-I-017	1.70							
Boys wheelchair access Restroom across from cafeteria (Far Right)	Sink	6/23/2016	HOLES-I-018	1.11							
E53 - Classroom	Fountain	6/23/2016	HOLES-I-019	0.72							
E53 - Classroom	Sink	6/23/2016	HOLES-I-020	0.67							
Wheelchair access Restroom next to D12	Sink	6/23/2016	HOLES-I-021	0.38							
Boys Restroom next to D01 (Left)	Sink	6/23/2016	HOLES-I-022	1.11							
Boys Restroom next to D01 (Middle)	Sink	6/23/2016	HOLES-I-023	1.26							
Boys Restroom next to D01 (Right)	Sink	6/23/2016	HOLES-I-024	1.01							
D01 - Classroom	Fountain	6/23/2016	HOLES-I-025	0.27							
D01 - Classroom	Sink	6/23/2016	HOLES-I-026	1.64							
D02 - Classroom	Fountain	6/23/2016	HOLES-I-027	ND							
D02 - Classroom	Sink	6/23/2016	HOLES-I-028	1.17							
D03 - Classroom	Fountain	6/23/2016	HOLES-I-029	0.27							
D03 - Classroom	Sink	6/23/2016	HOLES-I-030	1.99							
D04 - Classroom	Fountain	6/23/2016	HOLES-I-031	0.41							
D04 - Classroom	Sink	6/23/2016	HOLES-I-032	2.24							
Between D04 & D05 - Commons	Fountain	6/23/2016	HOLES-I-033	0.49							
Between D04 & D05 - Commons	Sink	6/23/2016	HOLES-I-034	1.23							
D05 - Classroom	Fountain	6/23/2016	HOLES-I-035	0.44							
D05 - Classroom	Sink	6/23/2016	HOLES-I-036	1.09							
D06 - Classroom	Fountain	6/23/2016	HOLES-I-037	0.24							
D06 - Classroom	Sink	6/23/2016	HOLES-I-038	1.80							
Girls Restroom next to D05 (Left)	Sink	6/23/2016	HOLES-I-039	2.88							
Girls Restroom next to D05 (Mid)	Sink	6/23/2016	HOLES-I-040	1.19							
Girls Restroom next to D05 (Right)	Sink	6/23/2016	HOLES-I-041	1.33							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Bertha Holt Elementary School											
Wheelchair access Restroom next to C12	Sink	6/23/2016	HOLES-I-042	0.87							
Boys Restroom next to C12 (Left)	Sink	6/23/2016	HOLES-I-043	1.14							
Boys Restroom next to C12 (Mid)	Sink	6/23/2016	HOLES-I-044	1.03							
Boys Restroom next to C12 (Right)	Sink	6/23/2016	HOLES-I-045	0.83							
C01 - Classroom	Fountain	6/23/2016	HOLES-I-046	0.29							
C01 - Classroom	Sink	6/23/2016	HOLES-I-047	1.69							
C02 - Classroom	Fountain	6/23/2016	HOLES-I-048	0.29							
C02 - Classroom	Sink	6/23/2016	HOLES-I-049	1.52							
C03 - Classroom	Fountain	6/23/2016	HOLES-I-050	ND							
C03 - Classroom	Sink	6/23/2016	HOLES-I-051	1.20							
C04 - Classroom	Fountain	6/23/2016	HOLES-I-052	0.32							
C04 - Classroom	Sink	6/23/2016	HOLES-I-053	1.62							
Between C04 & C05 - Commons	Fountain	6/23/2016	HOLES-I-054	0.33							
Between C04 & C05 - Commons	Sink	6/23/2016	HOLES-I-055	2.08							
C05 - Classroom	Fountain	6/23/2016	HOLES-I-056	ND							
C05 - Classroom	Sink	6/23/2016	HOLES-I-057	3.20							
C06 - Classroom	Fountain	6/23/2016	HOLES-I-058	0.23							
C06 - Classroom	Sink	6/23/2016	HOLES-I-059	1.07							
Girls Restroom next to C06 (Left)	Sink	6/23/2016	HOLES-I-060	1.23							
Girls Restroom next to C06 (Mid)	Sink	6/23/2016	HOLES-I-061	1.53							
Girls Restroom next to C06 (Right)	Sink	6/23/2016	HOLES-I-062	1.24							
Media Center Office E22	Sink	6/23/2016	HOLES-I-063	3.87							
Workroom SW Corner across from Media Center	Sink	6/23/2016	HOLES-I-064	4.52							
Wheelchair access Restroom at East end of Media Center	Sink	6/23/2016	HOLES-I-065	0.38							
Girls Restroom by B06 (Left)	Sink	6/23/2016	HOLES-I-066	1.23							
Girls Restroom by B06 (Mid)	Sink	6/23/2016	HOLES-I-067	0.81							
Girls Restroom by B06 (Right)	Sink	6/23/2016	HOLES-I-068	0.89							
B06 - Classroom	Fountain	6/23/2016	HOLES-I-069	ND							
B06 - Classroom	Sink	6/23/2016	HOLES-I-070	0.88							
B05 - Classroom	Fountain	6/23/2016	HOLES-I-071	ND							
B05 - Classroom	Sink	6/23/2016	HOLES-I-072	1.73							
Between B05 & B04 - Commons	Fountain	6/23/2016	HOLES-I-073	0.23							
Between B05 & B04 - Commons	Sink	6/23/2016	HOLES-I-074	2.72							
B04 - Classroom	Fountain	6/23/2016	HOLES-I-075	0.20							
B04 - Classroom	Sink	6/23/2016	HOLES-I-076	0.26							
B03 - Classroom	Fountain	6/23/2016	HOLES-I-077	1.44							
B03 - Classroom	Sink	6/23/2016	HOLES-I-078	2.87							
B02 - Classroom	Fountain	6/23/2016	HOLES-I-079	ND							
B02 - Classroom	Sink	6/23/2016	HOLES-I-080	1.40							
B01 - Classroom	Fountain	6/23/2016	HOLES-I-081	ND							
B01 - Classroom	Sink	6/23/2016	HOLES-I-082	1.36							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Bertha Holt Elementary School											
Boys Restroom next to B01 (Left)	Sink	6/23/2016	HOLES-I-083	2.06							
Boys Restroom next to B01 (Mid)	Sink	6/23/2016	HOLES-I-084	1.04							
Boys Restroom next to B01 (Right)	Sink	6/23/2016	HOLES-I-085	1.03							
Wheelchair Access Restroom next to B12	Sink	6/23/2016	HOLES-I-086	0.53							
Wheelchair Access Restroom next to Boys Restroom in A wing	Sink	6/23/2016	HOLES-I-087	1.43							
Boys Restroom next to A01 (Left)	Sink	6/23/2016	HOLES-I-088	1.33							
Boys Restroom next to A01 (Mid)	Sink	6/23/2016	HOLES-I-089	1.03							
Boys Restroom next to A01 (Right)	Sink	6/23/2016	HOLES-I-090	2.04							
A01 - Classroom	Fountain	6/23/2016	HOLES-I-091	0.20							
A01 - Classroom	Sink	6/23/2016	HOLES-I-092	1.34							
A02 - Classroom	Fountain	6/23/2016	HOLES-I-093	ND							
A02 - Classroom	Sink	6/23/2016	HOLES-I-094	1.46							
A03 - Classroom	Fountain	6/23/2016	HOLES-I-095	0.28							
A03 - Classroom	Sink	6/23/2016	HOLES-I-096	1.30							
A04 - Classroom	Fountain	6/23/2016	HOLES-I-097	ND							
A04 - Classroom	Sink	6/23/2016	HOLES-I-098	0.31							
Between A04 & A05 - Commons	Fountain	6/23/2016	HOLES-I-099	0.34							
Between A04 & A05 - Commons	Sink	6/23/2016	HOLES-I-100	2.59							
A05 - Classroom	Fountain	6/23/2016	HOLES-I-101	0.26							
A05 - Classroom	Sink	6/23/2016	HOLES-I-102	1.33							
A06 - Classroom	Fountain	6/23/2016	HOLES-I-103	0.33							
A06 - Classroom	Sink	6/23/2016	HOLES-I-104	0.88							
Girls Restroom next to A06 (Left)	Sink	6/23/2016	HOLES-I-105	3.76							
Girls Restroom next to A06 (Mid)	Sink	6/23/2016	HOLES-I-106	1.18							
Girls Restroom next to A06 (Right)	Sink	6/23/2016	HOLES-I-107	1.52							
Across from Media Center Left Upper	Fountain	6/23/2016	HOLES-I-108	ND							
Across from Media Center Right Lower	Fountain	6/23/2016	HOLES-I-109	ND							
E11 - Classroom	Sink	6/23/2016	HOLES-I-110	0.29							
E11 - Classroom	Insta-Hot	6/23/2016	HOLES-I-111	ND							
Health Room Restroom	Sink	6/23/2016	HOLES-I-112	0.51							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.