

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	
Howard Elementary School (OLD)												
Portable Bldg EEP Room	Sink	6/21/2016	HOWES-I-001	0.43	6/21/2016	HOWES-I-002						
Portable Bldg ARC Room	Sink	6/21/2016	HOWES-I-003	0.34	6/21/2016	HOWES-I-004						
Quad Bldg Room 21	Sink	6/21/2016	HOWES-I-005	2.70	6/21/2016	HOWES-I-006						
Quad Bldg Room 21	Sink	6/21/2016	HOWES-I-007	0.58	6/21/2016	HOWES-I-008						
Quad Bldg Room 20	Sink	6/21/2016	HOWES-I-009	2.06	6/21/2016	HOWES-I-010						
Quad Bldg Room 20	Fountain	6/21/2016	HOWES-I-011	ND	6/21/2016	HOWES-I-012						
Quad Bldg Room 19	Sink	6/21/2016	HOWES-I-013	3.51	6/21/2016	HOWES-I-014						
Quad Bldg Room 19	Fountain	6/21/2016	HOWES-I-015	0.22	6/21/2016	HOWES-I-016						
Quad Bldg Girls Restroom	Sink	6/21/2016	HOWES-I-017	1.16	6/21/2016	HOWES-I-018						
Quad Bldg Boys Restroom	Sink	6/21/2016	HOWES-I-019	0.73	6/21/2016	HOWES-I-020						
Quad Bldg Room 22	Sink	6/21/2016	HOWES-I-021	2.13	6/21/2016	HOWES-I-022						
Quad Bldg Room 22	Fountain	6/21/2016	HOWES-I-023	4.61	6/21/2016	HOWES-I-024						
Room 10	Sink	6/21/2016	HOWES-I-025	2.50	6/21/2016	HOWES-I-026						
Room 9	Sink	6/21/2016	HOWES-I-027	16.50	6/21/2016	HOWES-I-028						
Room 9	Fountain	6/21/2016	HOWES-I-029	8.24	6/21/2016	HOWES-I-030						
Room 8	Sink	6/21/2016	HOWES-I-031	4.25	6/21/2016	HOWES-I-032						
Room 8	Fountain	6/21/2016	HOWES-I-033	0.37	6/21/2016	HOWES-I-034						
Room 7	Sink	6/21/2016	HOWES-I-035	1.36	6/21/2016	HOWES-I-036						
Room 6	Sink	6/21/2016	HOWES-I-037	3.48	6/21/2016	HOWES-I-038						
Girls Restroom near Office	Sink	6/21/2016	HOWES-I-039	0.62	6/21/2016	HOWES-I-040						
Central Corridor near Office	Fountain	6/21/2016	HOWES-I-041	2.37	6/21/2016	HOWES-I-042						
Nurses Office	Sink	6/21/2016	HOWES-I-043	3.76	6/21/2016	HOWES-I-044						
Upper Level Staff Lounge	Sink	6/21/2016	HOWES-I-045	2.04	6/21/2016	HOWES-I-046						
Kitchen West Sink	Sink	6/21/2016	HOWES-I-047	0.49	6/21/2016	HOWES-I-048						
Kitchen East Sink	Sink	6/21/2016	HOWES-I-049	0.96	6/21/2016	HOWES-I-050						
Room 3	Sink	6/21/2016	HOWES-I-051	1.57	6/21/2016	HOWES-I-052						
Room 3	Fountain	6/21/2016	HOWES-I-053	1.31	6/21/2016	HOWES-I-054						
Room 2	Sink	6/21/2016	HOWES-I-055	7.99	6/21/2016	HOWES-I-056						
Room 2	Fountain	6/21/2016	HOWES-I-057	2.91	6/21/2016	HOWES-I-058						
Room 10	Sink	6/21/2016	HOWES-I-059	3.11	6/21/2016	HOWES-I-060						
Room 10	Fountain	6/21/2016	HOWES-I-061	1.04	6/21/2016	HOWES-I-062						
Room 18	Sink	6/21/2016	HOWES-I-063	20.90	6/21/2016	HOWES-I-064	2.41					
Room 18	Fountain	6/21/2016	HOWES-I-065	1.16	6/21/2016	HOWES-I-066						
Room 16	Sink	6/21/2016	HOWES-I-067	12.10	6/21/2016	HOWES-I-068						
Room 16	Fountain	6/21/2016	HOWES-I-069	2.30	6/21/2016	HOWES-I-070						
Room 17	Sink	6/21/2016	HOWES-I-071	1.74	6/21/2016	HOWES-I-072						
Room 17	Fountain	6/21/2016	HOWES-I-073	3.56	6/21/2016	HOWES-I-074						
East Wing Girls Restroom	Sink	6/21/2016	HOWES-I-075	6.83	6/21/2016	HOWES-I-076						
East Wing Boys Restroom	Sink	6/21/2016	HOWES-I-077	7.01	6/21/2016	HOWES-I-078						
Room 15	Sink	6/21/2016	HOWES-I-079	39.60	6/21/2016	HOWES-I-080	2.31					
Room 15	Fountain	6/21/2016	HOWES-I-081	3.74	6/21/2016	HOWES-I-082						
Gymnasium	Fountain	6/21/2016	HOWES-I-083	3.40	6/21/2016	HOWES-I-084						
Room 14	Sink	6/21/2016	HOWES-I-085	26.40	6/21/2016	HOWES-I-086	3.07					

Building Demolished July 2016

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
 Water Quality: Lead Testing Results

Eugene School District 4J - Location		First Draw			Flushed Draw			New Fixture First Draw				
Howard Elementary School (OLD)		Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
Room 14	Fountain	6/21/2016	HOWES-I-087	3.53	6/21/2016	HOWES-I-088						
Room 13	Sink	6/21/2016	HOWES-I-089	5.28	6/21/2016	HOWES-I-090						
Room 13	Fountain	6/21/2016	HOWES-I-091	6.71	6/21/2016	HOWES-I-092						
Instructional Materials Room	Sink	6/21/2016	HOWES-I-093	24.00	6/21/2016	HOWES-I-094	4.81					
Girls Restroom near Library	Sink	6/21/2016	HOWES-I-095	4.56	6/21/2016	HOWES-I-096						
Boys Restroom	Sink	6/21/2016	HOWES-I-097	4.20	6/21/2016	HOWES-I-098						
Corridor outside Room 12	Fountain	6/21/2016	HOWES-I-099	1.99	6/21/2016	HOWES-I-100						
Room 12	Sink	6/21/2016	HOWES-I-101	1.83	6/21/2016	HOWES-I-102						
Room 12	Fountain	6/21/2016	HOWES-I-103	5.81	6/21/2016	HOWES-I-104						
Room 11	Sink	6/21/2016	HOWES-I-105	140.00	6/21/2016	HOWES-I-106	0.71					

Build

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.