

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Roosevelt Middle School (NEW)</b>											
Nurses Office	Sink	8/26/2016	NRMS-I-001	ND							
Nurses Office Restroom	Sink	8/26/2016	NRMS-I-002	ND							
Office Workroom	Sink	8/26/2016	NRMS-I-003	ND							
Office Women's Restroom	Sink	8/26/2016	NRMS-I-004	ND							
Office Men's Restroom	Sink	8/26/2016	NRMS-I-005	ND							
E-1 South Wall (East)	Sink	8/26/2016	NRMS-I-006	ND							
E-1 South Wall (West)	Sink	8/26/2016	NRMS-I-007	ND							
E-1 West Wall (South)	Sink	8/26/2016	NRMS-I-008	1.43							
E-1 West Wall (North)	Sink	8/26/2016	NRMS-I-009	ND							
E-1 West Wall (north Eye Wash)	Sink	8/26/2016	NRMS-I-010	2.99							
E-2 North Wall (East)	Sink	8/26/2016	NRMS-I-011	1.56							
E-2 North Wall (West)	Sink	8/26/2016	NRMS-I-012	1.38							
E-2 West Wall (North)	Sink	8/26/2016	NRMS-I-013	1.01							
E-2 West Wall (South)	Sink	8/26/2016	NRMS-I-014	ND							
E-2 West Wall (South Eye Wash)	Sink	8/26/2016	NRMS-I-015	6.31							
E-3 South Wall (East)	Sink	8/26/2016	NRMS-I-016	1.36							
E-3 South Wall (West)	Sink	8/26/2016	NRMS-I-017	1.87							
E-3 West Wall (South)	Sink	8/26/2016	NRMS-I-018	1.39							
E-3 West Wall (North)	Sink	8/26/2016	NRMS-I-019	1.91							
E-3 West Wall (North Eye Wash)	Sink	8/26/2016	NRMS-I-020	3.31							
E-4 North Wall (East)	Sink	8/26/2016	NRMS-I-021	ND							
E-4 North Wall (West)	Sink	8/26/2016	NRMS-I-022	1.01							
E-4 West Wall (North)	Sink	8/26/2016	NRMS-I-023	1.43							
E-4 West Wall (South)	Sink	8/26/2016	NRMS-I-024	1.05							
E-4 West Wall (South Eye Wash)	Sink	8/26/2016	NRMS-I-025	2.18							
E-5 (North)	Sink	8/26/2016	NRMS-I-026	1.56							
E-5 (South)	Sink	8/26/2016	NRMS-I-027	3.22							
E-5 (South)	Fountain	8/26/2016	NRMS-I-028	ND							
Corridor at Room 185	Sink	8/26/2016	NRMS-I-029	3.16							
Corridor at Room 185	Fountain	8/26/2016	NRMS-I-030	ND							
Kitchen Prep Area South Wall (West)	Sink	8/26/2016	NRMS-I-031	ND							
Kitchen Prep Area South Wall (Center)	Sink	8/26/2016	NRMS-I-032	1.61							
Kitchen Prep Area South Wall (East)	Sink	8/26/2016	NRMS-I-033	ND							
Kitchen Prep Area South Wall (East)	Sprayer	8/26/2016	NRMS-I-034	4.10							
Kitchen Handwash Station	Sink	8/26/2016	NRMS-I-035	1.10							
Kitchen Soup Pot	Sink	8/26/2016	NRMS-I-036	1.96							
Kitchen Oven	Sprayer	8/26/2016	NRMS-I-037	17.10							
Kitchen Dishroom South Wall Handwash	Sink	8/26/2016	NRMS-I-038	2.96							
Kitchen Dishroom Northwest Corner	Sink	8/26/2016	NRMS-I-039	2.83							
Kitchen Dishroom Northwest Corner	Sprayer	8/26/2016	NRMS-I-040	ND							
Kitchen Dishroom North Wall (West)	Sink	8/26/2016	NRMS-I-041	1.06							
Kitchen Dishroom North Wall (East)	Sink	8/26/2016	NRMS-I-042	ND							
Kitchen Area Unisex Restroom	Sink	8/26/2016	NRMS-I-043	ND							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Roosevelt Middle School (NEW)</b>											
Kitchen Area Girls Restroom	Sink	8/26/2016	NRMS-I-044	1.80							
Kitchen Area (Upper)	Fountain	8/26/2016	NRMS-I-045	ND							
Kitchen Area (Lower)	Fountain	8/26/2016	NRMS-I-046	ND							
Kitchen Area Bottle Filler	Bottle Filler	8/26/2016	NRMS-I-047	ND							
Kitchen Area Boys Restroom	Sink	8/26/2016	NRMS-I-048	ND							
PE Office Area (Upper)	Fountain	8/26/2016	NRMS-I-049	ND							
PE Office Area (Lower)	Fountain	8/26/2016	NRMS-I-050	ND							
PE Office Area Bottle Filler	Bottle Filler	8/26/2016	NRMS-I-051	ND							
PE Office Area Unisex Restroom	Sink	8/26/2016	NRMS-I-052	ND							
Girls Locker Room Restroom (South)	Sink	8/26/2016	NRMS-I-053	1.15							
Girls Locker Room Restroom (North)	Sink	8/26/2016	NRMS-I-054	ND							
Boys Locker Room Restroom	Sink	8/26/2016	NRMS-I-055	1.18							
C1 North Wall	Sink	8/26/2016	NRMS-I-056	ND							
C1 East Wall (North)	Sink	8/26/2016	NRMS-I-057	1.15							
C1 East Wall (South)	Sink	8/26/2016	NRMS-I-058	ND							
C1 South Wall (East)	Sink	8/26/2016	NRMS-I-059	10.20							
C1 South Wall (Center)	Sink	8/26/2016	NRMS-I-060	2.00							
C1 South Wall (West)	Sink	8/26/2016	NRMS-I-061	ND							
C1 West Wall	Sink	8/26/2016	NRMS-I-062	1.01							
C2 South Wall (East)	Sink	8/26/2016	NRMS-I-063	1.25							
C2 South Wall (East Eye Wash)	Sink	8/26/2016	NRMS-I-064	15.50							
C2 South Wall (West)	Sink	8/26/2016	NRMS-I-065	ND							
C3	Sink	8/26/2016	NRMS-I-066	ND							
C3 Eye Wash Station	Sink	8/26/2016	NRMS-I-067	17.00							
Lower Level A Wing East End (Upper)	Fountain	8/26/2016	NRMS-I-068	ND							
Lower Level A Wing East End (Lower)	Fountain	8/26/2016	NRMS-I-069	ND							
Lower Level A Wing East End	Bottle Filler	8/26/2016	NRMS-I-070	ND							
Lower Level A Wing East End Room 125	Sink	8/26/2016	NRMS-I-071	1.75							
Lower Level A Wing East End Unisex Restroom	Sink	8/26/2016	NRMS-I-072	ND							
A1	Sink	8/26/2016	NRMS-I-073	ND							
A1	Fountain	8/26/2016	NRMS-I-074	ND							
A2	Sink	8/26/2016	NRMS-I-075	ND							
A2	Fountain	8/26/2016	NRMS-I-076	ND							
A3	Sink	8/26/2016	NRMS-I-077	ND							
A3	Fountain	8/26/2016	NRMS-I-078	ND							
A4	Sink	8/26/2016	NRMS-I-079	ND							
A4	Fountain	8/26/2016	NRMS-I-080	ND							
A5	Sink	8/26/2016	NRMS-I-081	ND							
A5	Fountain	8/26/2016	NRMS-I-082	ND							
Lower Level A Wing Center (Upper)	Fountain	8/26/2016	NRMS-I-083	ND							
Lower Level A Wing Center (Lower)	Fountain	8/26/2016	NRMS-I-084	ND							
Lower Level A Wing Center	Bottle Filler	8/26/2016	NRMS-I-085	ND							
Lower Level A Wing East Unisex Restroom	Sink	8/26/2016	NRMS-I-086	ND							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Roosevelt Middle School (NEW)</b>											
Lower Level A Wing West Unisex Restroom	Sink	8/26/2016	NRMS-I-087	ND							
Lower Level A Wing Restroom Common Area (West)	Sink	8/26/2016	NRMS-I-088	1.29							
Lower Level A Wing Restroom Common Area (Center)	Sink	8/26/2016	NRMS-I-089	ND							
Lower Level A Wing Restroom Common Area (East)	Sink	8/26/2016	NRMS-I-090	ND							
Lower Level A Wing Boys Restroom	Sink	8/26/2016	NRMS-I-091	1.09							
Lower Level A Wing Girls Restroom	Sink	8/26/2016	NRMS-I-092	1.14							
A6	Sink	8/26/2016	NRMS-I-093	ND							
A6	Fountain	8/26/2016	NRMS-I-094	ND							
A7	Sink	8/26/2016	NRMS-I-095	1.20							
A7	Fountain	8/26/2016	NRMS-I-096	ND							
A9	Sink	8/26/2016	NRMS-I-097	ND							
A9	Fountain	8/26/2016	NRMS-I-098	ND							
A8	Sink	8/26/2016	NRMS-I-099	ND							
A8	Fountain	8/26/2016	NRMS-I-100	ND							
Room 137 Teacher Workroom	Sink	8/26/2016	NRMS-I-101	1.31							
Library Room 202	Sink	8/26/2016	NRMS-I-102	ND							
Upper Level A Wing East End (Upper)	Fountain	8/26/2016	NRMS-I-103	ND							
Upper Level A Wing East End (Lower)	Fountain	8/26/2016	NRMS-I-104	ND							
Upper Level A Wing East End	Bottle Filler	8/26/2016	NRMS-I-105	ND							
Upper Level A Wing East End South Unisex Restroom	Sink	8/26/2016	NRMS-I-106	ND							
Upper Level A Wing East End North Unisex Restroom	Sink	8/26/2016	NRMS-I-107	1.37							
Upper Level A Wing Staff Lounge	Sink	8/26/2016	NRMS-I-108	ND							
A22	Sink	8/26/2016	NRMS-I-109	1.15							
A22	Fountain	8/26/2016	NRMS-I-110	ND							
A21	Sink	8/26/2016	NRMS-I-111	1.33							
A21	Fountain	8/26/2016	NRMS-I-112	2.78							
A23	Sink	8/26/2016	NRMS-I-113	1.97							
A23	Fountain	8/26/2016	NRMS-I-114	ND							
A24	Sink	8/26/2016	NRMS-I-115	ND							
A24	Fountain	8/26/2016	NRMS-I-116	ND							
A25	Sink	8/26/2016	NRMS-I-117	ND							
A25	Fountain	8/26/2016	NRMS-I-118	1.06							
Teacher Workroom 218	Sink	8/26/2016	NRMS-I-119	ND							
Upper Level A Wing Center Unisex Restroom	Sink	8/26/2016	NRMS-I-120	ND							
Upper Level A Wing Center Restroom Common Area (West)	Sink	8/26/2016	NRMS-I-121	ND							
Upper Level A Wing Center Restroom Common Area (Center)	Sink	8/26/2016	NRMS-I-122	1.56							
Upper Level A Wing Center Restroom Common Area (East)	Sink	8/26/2016	NRMS-I-123	ND							
Upper Level A Wing Center Boys Restroom	Sink	8/26/2016	NRMS-I-124	ND							
Upper Level A Wing Center Girls Restroom	Sink	8/26/2016	NRMS-I-125	ND							
A26	Sink	8/26/2016	NRMS-I-126	ND							
A26	Fountain	8/26/2016	NRMS-I-127	ND							
A27	Sink	8/26/2016	NRMS-I-128	ND							
A27	Fountain	8/26/2016	NRMS-I-129	ND							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
<b>Roosevelt Middle School (NEW)</b>											
A29	Sink	8/26/2016	NRMS-I-130	ND							
A29	Fountain	8/26/2016	NRMS-I-131	ND							
A28	Sink	8/26/2016	NRMS-I-132	ND							
A28	Fountain	8/26/2016	NRMS-I-133	ND							
Staff Room Refrigerator - In Door	Dispencer	10/13/2016	NRMS-I-134	ND							
Staff Room Refrigerator - In Door	Ice Machine	10/13/2016	NRMS-I-135	ND							
Nurse Room - In Freezer	Ice Machine	10/13/2016	NRMS-I-136	2.48							
Home Ec - West Unit - In Freezer	Ice Machine	10/13/2016	NRMS-I-137	ND							
Home Ec - East Unit - In Freezer - See #I-140 for re-test.	Ice Machine	10/13/2016	NRMS-I-138	23.80	See Re-Test Sample Number NRMS-I-140						
Science Room - In Freezer	Ice Machine	10/13/2016	NRMS-I-139	ND							
Home Ec - East Unit - In Freezer - Re-Test of Sample #I-138	Ice Machine	11/1/2016	NRMS-I-140	ND							

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.