

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
<b>Sheldon High School</b>															
Main Office	Fountain	7/7/2016	SHEHS-I-001	55.10	9/12/2016	SHEHS-F-213	5.18	11/4/2016	11/8/2016	SHEHS-I-275	ND				
Main Office - Replaced old DF with new DF and BF unit	Bottle Filler							11/4/2016	11/8/2016	SHEHS-I-274	ND				
Main Office Workroom	Sink	7/7/2016	SHEHS-I-002	4.62											
Main Office Workroom	Insta-Hot	7/7/2016	SHEHS-I-003	1.07											
Main Office Women's Restroom (left)	Sink	7/7/2016	SHEHS-I-004	6.13											
Main Office Women's Restroom (right)	Sink	7/7/2016	SHEHS-I-005	3.46											
Main Office Men's Restroom	Sink	7/7/2016	SHEHS-I-006	3.41											
Main Office Staff Conference Room	Sink	7/7/2016	SHEHS-I-007	6.58											
Health Center Main Area	Sink	7/7/2016	SHEHS-I-008	43.70	9/12/2016	SHEHS-F-212	1.81	10/6/2016	10/7/2016	SHEHS-I-252	2.57				
Health Center Restroom	Sink	7/7/2016	SHEHS-I-009	5.50											
Health Center Exam Room	Sink	7/7/2016	SHEHS-I-010	11.80											
A5	Sink	7/7/2016	SHEHS-I-011	70.80	9/12/2016	SHEHS-F-215	6.08	10/6/2016	10/7/2016	SHEHS-I-253	2.39				
A4	Sink	7/7/2016	SHEHS-I-012	64.40	9/12/2016	SHEHS-F-214	14.50	10/6/2016	10/7/2016	SHEHS-I-255	21.10	Replaced angle stops	2/2/2017	SHEHS-I-293	16.00
Room across from A4	Sink	7/7/2016	SHEHS-I-013	218.00	9/12/2016	SHEHS-F-217	9.85	10/6/2016	10/7/2016	SHEHS-I-256	2.83				
A6	Sink	7/7/2016	SHEHS-I-014	64.80	9/12/2016	SHEHS-F-216	3.96	10/6/2016	10/7/2016	SHEHS-I-254	22.90	Replaced angle stops	2/2/2017	SHEHS-I-294	14.10
A9	Sink	7/7/2016	SHEHS-I-015	11.00											
Boys Restroom across from A7/A10 (left)	Sink	7/7/2016	SHEHS-I-016	0.21											
Boys Restroom across from A7/A10 (Mid)	Sink	7/7/2016	SHEHS-I-017	8.43											
Boys Restroom across from A7/A10 (right)	Sink	7/7/2016	SHEHS-I-018	9.59											
Girls Restroom across from A7/A10 (left)	Sink	7/7/2016	SHEHS-I-019	9.46											
Girls Restroom across from A7/A10 (Middle)	Sink	7/7/2016	SHEHS-I-020	13.00											
Girls Restroom across from A7/A10 (Middle)	Sink	7/7/2016	SHEHS-I-021	12.10											
Girls Restroom across from A7/A10 (Right)	Sink	7/7/2016	SHEHS-I-022	8.68											
Boys Restroom across from A3 (left)	Sink	7/7/2016	SHEHS-I-023	3.97											
Boys Restroom across from A3 (middle)	Sink	7/7/2016	SHEHS-I-024	2.59											
Boys Restroom across from A3 (right)	Sink	7/7/2016	SHEHS-I-025	2.70											
Girls Restroom across from A3 (left)	Sink	7/7/2016	SHEHS-I-026	2.78											
Girls Restroom across from A3 (middle)'	Sink	7/7/2016	SHEHS-I-027	3.33											
Girls Restroom across from A3 (right)	Sink	7/7/2016	SHEHS-I-028	2.57											
F2	Fountain	7/7/2016	SHEHS-I-029	21.80	9/12/2016	SHEHS-F-219	10.20	10/6/2016	10/7/2016	SHEHS-I-269	26.30	Replaced angle stops	2/2/2017	SHEHS-I-295	16.30
F2	Sink	7/7/2016	SHEHS-I-030	5.58											
F3	Fountain	7/7/2016	SHEHS-I-031	22.80	9/12/2016	SHEHS-F-220	6.98	10/6/2016	10/7/2016	SHEHS-I-270	11.20				
Office Between F2 & F3	Sink	7/7/2016	SHEHS-I-032	13.20											
Girls Restroom South Auditorium (left)	Sink	7/7/2016	SHEHS-I-033	8.72											
Girls Restroom South of Auditorium (right)	Sink	7/7/2016	SHEHS-I-034	4.43											
Hallway South of Auditorium	Fountain	7/7/2016	SHEHS-I-035	1.66											
Boys Restroom South Auditorium (left)	Sink	7/7/2016	SHEHS-I-036	6.04											
Boys Restroom South Auditorium (right)	Sink	7/7/2016	SHEHS-I-037	4.61											
F6 Large Double Basin (Back)	Sink	7/7/2016	SHEHS-I-038	12.40											
F6 Large Double Basin (Front)	Sink	7/7/2016	SHEHS-I-039	72.60	9/12/2016	SHEHS-F-222	ND	11/15/2016	11/16/2016	SHEHS-I-291	2.39				
Storage Room in F6	Sink	7/7/2016	SHEHS-I-040	28.60	9/12/2016	SHEHS-F-223	ND	10/6/2016	10/7/2016	SHEHS-I-273	1.43				
F5	Fountain	7/7/2016	SHEHS-I-041	4.48											
F5 Large Double Basin (Back)	Sink	7/7/2016	SHEHS-I-042	7.88											
F5 Large Double Basin (Front)	Sink	7/7/2016	SHEHS-I-043	8.61											
Storage Room in F5	Sink	7/7/2016	SHEHS-I-044	372.00	9/12/2016	SHEHS-F-221	ND	10/6/2016	10/7/2016	SHEHS-I-272	2.43				
Large Gym South East	Fountain	7/7/2016	SHEHS-I-045	3.43											
Large Gym South West	Fountain	7/7/2016	SHEHS-I-046	3.19											
Large Gym Northwest	Fountain	7/7/2016	SHEHS-I-047	63.10	9/12/2016	SHEHS-F-225	5.18	10/6/2016	10/7/2016	SHEHS-I-264	6.99				
Large Gym Northeast	Fountain	7/7/2016	SHEHS-I-048	4.62											
Small Gym (Weight Room)	Fountain	7/7/2016	SHEHS-I-049	12.10											
Hallway East of Large Gym (left)	Fountain	7/7/2016	SHEHS-I-050	28.90	9/12/2016	SHEHS-F-218	2.78	10/6/2016	10/7/2016	SHEHS-I-268	6.75				
Hallway East of Large Gym (right)	Fountain	7/7/2016	SHEHS-I-051	15.10											
Concession Stand by Large Gym	Sink	7/7/2016	SHEHS-I-052	30.00	9/12/2016	SHEHS-F-224	1.42	10/6/2016	10/7/2016	SHEHS-I-265	7.72				
Girls Locker Room East end of Island	Fountain	7/7/2016	SHEHS-I-053	1.08											
Girls Locker Room (left)	Sink	7/7/2016	SHEHS-I-054	3.07											
Girls Locker Room (right)	Sink	7/7/2016	SHEHS-I-055	3.36											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
<b>Sheldon High School</b>															
Girls Locker Room West end of Island	Fountain	7/7/2016	SHEHS-I-056	14.30											
Women's Restroom in Office by Girls Locker Room	Sink	7/7/2016	SHEHS-I-057	52.60	9/12/2016	SHEHS-F-226	ND	10/6/2016	10/7/2016	SHEHS-I-263	3.62				
Men's Restroom in Office/Small Locker Room	Sink	7/7/2016	SHEHS-I-058	35.50	9/12/2016	SHEHS-F-227	2.06	10/6/2016	10/7/2016	SHEHS-I-262	1.67				
Boys Locker Room East end of Island	Fountain	7/7/2016	SHEHS-I-059	5.97											
Boys Locker Room (left)	Sink	7/7/2016	SHEHS-I-060	11.00											
Boys Locker Room (right)	Sink	7/7/2016	SHEHS-I-061	5.87											
Boys Locker Room West end of Island	Fountain	7/7/2016	SHEHS-I-062	8.81											
End of Hallway by Locker Rooms/Team Rooms	Fountain	7/7/2016	SHEHS-I-063	13.00											
Boys Team Room	Fountain	7/7/2016	SHEHS-I-064	3.91											
Boys Team Room (left)	Sink	7/7/2016	SHEHS-I-065	6.38											
Boys Team Room (right)	Sink	7/7/2016	SHEHS-I-066	1.73											
Girls Restroom (left)	Sink	7/7/2016	SHEHS-I-067	2.24											
Girls Restroom (right)	Sink	7/7/2016	SHEHS-I-068	1.00											
Boys Restroom (left)	Sink	7/7/2016	SHEHS-I-069	1.24											
Boys Restroom (right)	Sink	7/7/2016	SHEHS-I-070	1.27											
Hallway by KRVM	Fountain	7/7/2016	SHEHS-I-071	3.69											
Boys Restroom by KRVM	Sink	7/7/2016	SHEHS-I-072	1.83											
Girls Restroom by KRV	Sink	7/7/2016	SHEHS-I-073	3.06											
CTV Men's Restroom	Sink	7/7/2016	SHEHS-I-074	18.00											
CTV Main Area	Sink	7/7/2016	SHEHS-I-075	6.67											
CTV Women's Restroom	Sink	7/7/2016	SHEHS-I-076	7.03											
CTV Main Area	Fountain	7/7/2016	SHEHS-I-077	2.80											
B30	Sink	7/7/2016	SHEHS-I-078	14.20											
Hall outside B30	Fountain	7/7/2016	SHEHS-I-079	9.77											
B28a	Sink	7/7/2016	SHEHS-I-080	15.40											
Learning Center Office	Sink	7/7/2016	SHEHS-I-081	10.50											
Restroom in Learning Center Office (left)	Sink	7/7/2016	SHEHS-I-082	13.20											
Restroom in Learning Center Office (right)	Sink	7/7/2016	SHEHS-I-083	38.30	9/12/2016	SHEHS-F-231	3.33	10/6/2016	10/7/2016	SHEHS-I-258	2.33				
Hall outside B22	Fountain	7/7/2016	SHEHS-I-084	11.60											
Hall outside B18	Fountain	7/7/2016	SHEHS-I-085	2.70											
Math Resource Center	Sink	7/7/2016	SHEHS-I-086	12.20											
Hall Outside B13/F.L.O.	Fountain	7/7/2016	SHEHS-I-087	38.60	9/12/2016	SHEHS-F-229	2.88								
Hall outside B14	Fountain	7/7/2016	SHEHS-I-088	3.64											
Foreign Language Office	Sink	7/7/2016	SHEHS-I-089	31.10	9/12/2016	SHEHS-F-230	3.33	10/6/2016	10/7/2016	SHEHS-I-257	1.54				
Hallway outside B4	Fountain	7/7/2016	SHEHS-I-090	7.81											
Hallway S12 (Lower)	Fountain	7/7/2016	SHEHS-I-091	0.48											
Hallway S12 (Upper)	Fountain	7/7/2016	SHEHS-I-092	0.91											
S13	Sink	7/7/2016	SHEHS-I-093	6.28											
S13	Insta-Hot	7/7/2016	SHEHS-I-094	0.53											
Cafeteria (Left)	Fountain	7/7/2016	SHEHS-I-095	7.10											
Cafeteria (Right)	Fountain	7/7/2016	SHEHS-I-096	2.97											
"Market" Window Handwash - Kitchen	Sink	7/7/2016	SHEHS-I-097	13.50											
Kitchen Restroom	Sink	7/7/2016	SHEHS-I-098	14.10											
Kitchen Vegetable Prep Area - Faucet	Sink	7/7/2016	SHEHS-I-099	4.10											
Kitchen Vegetable Prep Area Handwash	Sink	7/7/2016	SHEHS-I-100	12.20											
Kitchen Pots and Pans Basin (wash) (Left)	Sink	7/7/2016	SHEHS-I-101	6.34											
Kitchen Pots and Pans Basins rinse (Mid)	Sink	7/7/2016	SHEHS-I-102	22.90	9/13/2016	SHEHS-F-233	1.45	11/21/2016	2/2/2017	SHEHS-I-297	1.32				
Kitchen Pots and Pans Basins sanitize (Right)	Sink	7/7/2016	SHEHS-I-103	6.66											
Kitchen Dishwash area west wall (corrected east vs west based on map & Sample ID #)	Sink	7/7/2016	SHEHS-I-104	87.10	9/13/2016	SHEHS-F-234	ND	10/6/2016	10/7/2016	SHEHS-I-266	73.50	Replaced nipples and stops, 11/9/16	2/2/2017	SHEHS-I-296	3.26
Kitchen Dishwash area east wall (corrected east vs west based on map & Sample ID #)	Sink	7/7/2016	SHEHS-I-105	8.81											
Custodial Office Restroom	Sink	7/7/2016	SHEHS-I-106	2.78											
D4 - Wrestling	Fountain	7/7/2016	SHEHS-I-107	13.00											
Restroom next to D4	Sink	7/7/2016	SHEHS-I-108	6.21											
Training Room Small on counter	Sink	7/7/2016	SHEHS-I-109	1.71											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
<b>Sheldon High School</b>															
Training Room Large Filling Basin	Sink	7/7/2016	SHEHS-I-110	8.92											
Training Room Ice Machine	Ice Machine	7/7/2016	SHEHS-I-111	0.48											
D2 - This is actually D1. No water in D1.	Sink	7/7/2016	SHEHS-I-112	24.50	9/13/2016	SHEHS-F-232	ND	11/15/2016	11/16/2016	SHEHS-I-292	ND				
C1 West Wall (Left)	Sink	7/7/2016	SHEHS-I-113	10.20											
C1 West Wall (right)	Sink	7/7/2016	SHEHS-I-114	38.50	9/13/2016	SHEHS-F-235	1.01	10/6/2016	10/7/2016	SHEHS-I-261	6.89				
C1 East Wall (left)	Sink	7/7/2016	SHEHS-I-115	6.08											
C1 East Wall (center)	Sink	7/7/2016	SHEHS-I-116	18.20											
C1 East Wall (right)	Sink	7/7/2016	SHEHS-I-117	25.90	9/13/2016	SHEHS-F-236	ND	10/6/2016	10/7/2016	SHEHS-I-260	2.13				
C1 South Wall	Sink	7/7/2016	SHEHS-I-118	13.80											
Attendance Office C2	Sink	7/7/2016	SHEHS-I-119	11.10											
C4	Sink	7/7/2016	SHEHS-I-120	28.10	9/13/2016	SHEHS-F-237	ND	10/6/2016	10/7/2016	SHEHS-I-259	1.25				
Boys Restroom across from C5 (LEFT)	Sink	7/7/2016	SHEHS-I-121	1.88											
Boys Restroom across from C5 (middle)	Sink	7/7/2016	SHEHS-I-122	1.18											
Boys Restroom across from C5 (right)	Sink	7/7/2016	SHEHS-I-123	1.34											
Girls Restroom across from C5 (left)	Sink	7/7/2016	SHEHS-I-124	2.57											
Girls Restroom across from C5 (middle)	Sink	7/7/2016	SHEHS-I-125	0.94											
Girls Restroom across from C5 (right)	Sink	7/7/2016	SHEHS-I-126	0.66											
Girls Restroom across from C10 (left)	Sink	7/7/2016	SHEHS-I-127	4.98											
Girls Restroom across from C10 (middle)	Sink	7/7/2016	SHEHS-I-128	4.18											
Girls Restroom across from C10 (right)	Sink	7/7/2016	SHEHS-I-129	2.83											
Boys Restroom across from C10 (left)	Sink	7/7/2016	SHEHS-I-130	11.10											
Boys Restroom across from C10 (middle)	Sink	7/7/2016	SHEHS-I-131	3.31											
Boys Restroom across from C10 (right)	Sink	7/7/2016	SHEHS-I-132	2.42											
Library Front Office Area	Sink	7/7/2016	SHEHS-I-133	6.53											
C15	Sink	7/20/2016	SHEHS-I-134	28.40	9/8/2016	SHEHS-F-196	2.41	11/15/2016	11/16/2016	SHEHS-I-276	4.09				
C14	Sink	7/20/2016	SHEHS-I-135	23.00	9/8/2016	SHEHS-F-197	2.43	11/15/2016	11/16/2016	SHEHS-I-277	5.67				
S1	Sink	7/20/2016	SHEHS-I-136	12.00											
S2 South end of West Wall	Sink	7/20/2016	SHEHS-I-137	20.50	9/8/2016	SHEHS-F-198	15.60	11/15/2016	11/16/2016	SHEHS-I-284	3.36				
S2 Middle on West Wall	Sink	7/20/2016	SHEHS-I-138	46.80	9/8/2016	SHEHS-F-199	3.58	11/15/2016	11/16/2016	SHEHS-I-285	8.67				
S2 North end on West Wall	Sink	7/20/2016	SHEHS-I-139	30.10	9/8/2016	SHEHS-F-200	3.37	11/15/2016	11/16/2016	SHEHS-I-286	2.95				
S2 Supply Room	Sink	7/20/2016	SHEHS-I-140	48.00	9/8/2016	SHEHS-F-201	1.99	11/15/2016	11/16/2016	SHEHS-I-287	7.05				
S2 North end on East Wall	Sink	7/20/2016	SHEHS-I-141	45.90	9/8/2016	SHEHS-F-202	2.23	11/15/2016	11/16/2016	SHEHS-I-288	3.15				
S2 North Middle on East Wall	Sink	7/20/2016	SHEHS-I-142	57.10	9/8/2016	SHEHS-F-203	1.80	11/15/2016	11/16/2016	SHEHS-I-289	4.19				
S2 South Middle on East Wall	Sink	7/20/2016	SHEHS-I-143	19.80											
S2 South end on East Wall	Sink	7/20/2016	SHEHS-I-144	24.10	9/8/2016	SHEHS-F-204	2.21	11/15/2016	11/16/2016	SHEHS-I-290	16.90				
S3	Sink	7/20/2016	SHEHS-I-145	7.92											
S4 West Wall South Set (left)	Sink	7/20/2016	SHEHS-I-146	27.20	9/8/2016	SHEHS-F-205	2.66	11/15/2016	11/16/2016	SHEHS-I-279	5.81				
S4 West Wall South Set (right)	Sink	7/20/2016	SHEHS-I-147	22.10	9/8/2016	SHEHS-F-206	3.85	11/15/2016	11/16/2016	SHEHS-I-280	3.03				
S4 West Wall Middle Set (left)	Sink	7/20/2016	SHEHS-I-148	21.60	9/8/2016	SHEHS-F-207	3.73	11/15/2016	11/16/2016	SHEHS-I-281	3.13				
S4 West Wall Middle Set (right)	Sink	7/20/2016	SHEHS-I-149	13.50											
S4 West Wall North Set (left)	Sink	7/20/2016	SHEHS-I-150	20.40	9/8/2016	SHEHS-F-208	1.90	11/15/2016	11/16/2016	SHEHS-I-282	7.22				
S4 West Wall North Set (right)	Sink	7/20/2016	SHEHS-I-151	10.80											
S4 West Wall at Back of Room	Sink	7/20/2016	SHEHS-I-152	17.50											
S4 Chemical Storage Room	Sink	7/20/2016	SHEHS-I-153	16.50											
S4 North Wall at Back of Room	Sink	7/20/2016	SHEHS-I-154	39.80	9/8/2016	SHEHS-F-209	2.23	11/15/2016	11/16/2016	SHEHS-I-283	8.21				
S4 East Wall North Set (Left)	Sink	7/20/2016	SHEHS-I-155	19.60											
S4 East Wall North set (right)	Sink	7/20/2016	SHEHS-I-156	19.50											
S4 East Wall North Middle Set (left)	Sink	7/20/2016	SHEHS-I-157	16.30											
S4 East Wall North Middle Set (right)	Sink	7/20/2016	SHEHS-I-158	10.50											
S4 East Wall South Middle Set (left)	Sink	7/20/2016	SHEHS-I-159	12.50											
S4 East Wall South Middle Set (right)	Sink	7/20/2016	SHEHS-I-160	6.88											
S4 East Wall South Set (left)	Sink	7/20/2016	SHEHS-I-161	13.10											
S4 East Wall South Set (right)	Sink	7/20/2016	SHEHS-I-162	6.74											
S5	Sink	7/20/2016	SHEHS-I-163	6.81											
S6 North Wall West End	Sink	7/20/2016	SHEHS-I-164	9.13											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J  
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
<b>Sheldon High School</b>															
S6 North Wall West Middle	Sink	7/20/2016	SHEHS-I-165	10.60											
S6 North Wall East Middle	Sink	7/20/2016	SHEHS-I-166	12.00											
S6 North Wall East End	Sink	7/20/2016	SHEHS-I-167	14.90											
S6 East Wall	Sink	7/20/2016	SHEHS-I-168	6.93											
S6 South Wall East End	Sink	7/20/2016	SHEHS-I-169	11.60											
S6 South Wall East Middle	Sink	7/20/2016	SHEHS-I-170	9.69											
S6 South Wall West Middle	Sink	7/20/2016	SHEHS-I-171	18.10											
S6 South Wall West End	Sink	7/20/2016	SHEHS-I-172	8.40											
S7 North Wall (left)	Sink	7/20/2016	SHEHS-I-173	6.35											
S7 North Wall Middle	Sink	7/20/2016	SHEHS-I-174	5.01											
S7 North Wall (right)	Sink	7/20/2016	SHEHS-I-175	6.36											
S7 South Wall (left)	Sink	7/20/2016	SHEHS-I-176	9.03											
S7 Middle	Sink	7/20/2016	SHEHS-I-177	10.40											
S7 (right)	Sink	7/20/2016	SHEHS-I-178	23.40	9/8/2016	SHEHS-F-210	3.89	11/15/2016	11/16/2016	SHEHS-I-278	2.22				
S7 on Island at front of room	Sink	7/20/2016	SHEHS-I-179	11.10											
S8	Sink	7/20/2016	SHEHS-I-180	13.60											
S9 North Wall (left)	Sink	7/20/2016	SHEHS-I-181	13.30											
S9 North Wall (Middle)	Sink	7/20/2016	SHEHS-I-182	4.66											
S9 North Wall (right)	Sink	7/20/2016	SHEHS-I-183	12.80											
S9 South Wall (left)	Sink	7/20/2016	SHEHS-I-184	9.27											
S9 South Wall (middle)	Sink	7/20/2016	SHEHS-I-185	5.37											
S9 South Wall (right)	Sink	7/20/2016	SHEHS-I-186	4.63											
S9 Island at front of room	Sink	7/20/2016	SHEHS-I-187	9.89											
S10 North Wall	Sink	7/20/2016	SHEHS-I-188	9.75											
S10 East Wall (left)	Sink	7/20/2016	SHEHS-I-189	8.83											
S10 East Wall (right)	Sink	7/20/2016	SHEHS-I-190	6.20											
S10 South Wall	Sink	7/20/2016	SHEHS-I-191	11.20											
S10 Island at front of room	Sink	7/20/2016	SHEHS-I-192	9.54											
Kitchen Dishwash Room East Sprayer	Sink	7/20/2016	SHEHS-I-193	10.20											
Kitchen Dishwash Room West Sprayer	Sink	7/20/2016	SHEHS-I-194	13.50											
Back Stage in Auditorium	Sink	7/20/2016	SHEHS-I-195	26.80	9/8/2016	SHEHS-F-211	2.33	10/6/2016	10/7/2016	SHEHS-I-271	2.46				
Hall Outside B13/F.L.O. - Re-Test of Sample #087	Fountain	9/12/2016	SHEHS-I-228	2.79											
Upper Gym West	Fountain	9/22/2016	SHEHS-I-238	5.62											
Upper Gym East	Fountain	9/22/2016	SHEHS-I-239	4.46											
Football Field North	Hose Bib	9/22/2016	SHEHS-I-240	ND											
Football Field South	Hose Bib	9/22/2016	SHEHS-I-241	1.46											
Baseball Field, 3rd Baseline, East	Hose Bib	9/22/2016	SHEHS-I-242	4.68											
Baseball Field, 3rd Baseline, Central	Hose Bib	9/22/2016	SHEHS-I-243	8.22											
Baseball Field, 3rd Baseline, Behind Small Grandstand	Hose Bib	9/22/2016	SHEHS-I-244	5.61											
Baseball Field, 1st Baseline, Outside Mobile Concession	Hose Bib	9/22/2016	SHEHS-I-245	2.35											
Baseball Field, 1st Baseline, Inside Concessions	Sink	9/22/2016	SHEHS-I-246	19.20											
D1	Fountain	9/24/2016	SHEHS-I-249	1.04											
Math Resource Center - Re-Test	Sink	9/24/2016	SHEHS-I-248	2.92											
Hall outside B14 - Re-Test	Fountain	9/24/2016	SHEHS-I-247	4.01											
Hall Outside B13/F.L.O. - 2nd Re-Test of Sample #087	Fountain	10/4/2016	DW-001	ND											
Hall Outside B13/F.L.O. - 2nd Re-Test of Sample #087	Bottle Filler	10/4/2016	DW-002	ND											
Staff Room Refrigerator - In Door	Water	10/8/2016	SHEHS-I-250	ND											
Staff Room Refrigerator - In Door	Ice Machine	10/8/2016	SHEHS-I-251	ND											
Market / Snack Bar	Ice Machine	10/8/2016	SHEHS-I-267	ND											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.