

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
Spencer Butte Middle School															
Office Kitchen Area	Sink	6/27/2016	SBMS-I-001	2.69											
Office Restroom	Sink	6/27/2016	SBMS-I-002	2.02											
Teachers Conference Room	Sink	6/27/2016	SBMS-I-003	16.90											
Health Room	Fountain	6/27/2016	SBMS-I-004	3.82											
Health Room	Sink	6/27/2016	SBMS-I-005	18.10											
Gym Nearest to Office	Fountain	6/27/2016	SBMS-I-006	0.51											
Music 31	Fountain	6/27/2016	SBMS-I-007	2.07											
Music 31	Sink	6/27/2016	SBMS-I-008	0.95											
Hallway outside Room 33	Fountain	6/27/2016	SBMS-I-009	1.39											
Boys Locker Room (Left)	Sink	6/27/2016	SBMS-I-010	1.05											
Boys Locker Room (Right)	Sink	6/27/2016	SBMS-I-011	1.75											
Locker Room Office Restroom	Sink	6/27/2016	SBMS-I-012	6.29											
Room 33	Sink	6/27/2016	SBMS-I-013	4.62											
Room 34	Sink	6/27/2016	SBMS-I-014	0.91											
Room 35	Sink	6/27/2016	SBMS-I-015	1.75											
Room 35	Sink	6/27/2016	SBMS-I-016	1.41											
Room 35	Sink	6/27/2016	SBMS-I-017	1.91											
Small Gym	Fountain	6/27/2016	SBMS-I-018	0.94											
Girls Locker Room Office Restroom	Sink	6/27/2016	SBMS-I-019	3.91											
Girls Locker Room (Left)	Sink	6/27/2016	SBMS-I-020	0.68											
Girls Locker Room(Right)	Sink	6/27/2016	SBMS-I-021	0.77											
Girls Locker Room	Fountain	6/27/2016	SBMS-I-022	5.41											
Girls Restroom next to Locker Room (Right)	Sink	6/27/2016	SBMS-I-023	1.37											
Girls Restroom next to Locker Room (Left)	Sink	6/27/2016	SBMS-I-024	1.43											
Boys Restroom next to Locker Room (Right)	Sink	6/27/2016	SBMS-I-025	0.86											
Boys Restroom next to Locker Room (Left)	Sink	6/27/2016	SBMS-I-026	1.54											
Hallway outside Library	Fountain	6/27/2016	SBMS-I-027	2.69											
Library Workroom	Sink	6/27/2016	SBMS-I-028	7.50											
Wheelchair Restroom/Life Skills	Sink	6/27/2016	SBMS-I-029	5.96											
Room 7 Instructional Materials Center	Fountain	6/27/2016	SBMS-I-030	5.58											
Room 7 Instructional Materials Center	Sink	6/27/2016	SBMS-I-031	47.40	8/18/2016	SBMS-F-090	5.07	8/26/2016	8/26/2016	SBMS-I-097	44.10	Sink was decommissioned.			
Girls Restroom across from IMC (Left)	Sink	6/27/2016	SBMS-I-032	3.31											
Girls Restroom across from IMC (Middle)	Sink	6/27/2016	SBMS-I-033	3.93											
Girls Restroom across from IMC (Right)	Sink	6/27/2016	SBMS-I-034	4.39											
Boys Restroom across from Room 6 (Left)	Sink	6/27/2016	SBMS-I-035	4.13											
Boys Restroom across from Room 6 (Middle)	Sink	6/27/2016	SBMS-I-036	2.64											
Boys Restroom across form Room 6 (Right)	Sink	6/27/2016	SBMS-I-037	1.79											
Room 5	Fountain	6/27/2016	SBMS-I-038	0.83											
Room 5	Sink	6/27/2016	SBMS-I-039	10.50											
Hallway between Boys RR & Room 5	Fountain	6/27/2016	SBMS-I-040	0.66											
Room 2 Island in front of room	Sink	6/27/2016	SBMS-I-041	10.40											
Room 2 South Wall (Left)	Sink	6/27/2016	SBMS-I-042	0.84											
Room 2 South Wall (Middle)	Sink	6/27/2016	SBMS-I-043	0.79											
Room 2 South Wall (Right)	Sink	6/27/2016	SBMS-I-044	0.56											
Room between Room 2 & 4 Sprayer	Sink	6/27/2016	SBMS-I-045	46.60	8/18/2016	SBMS-F-088	3.92	8/26/2016	8/26/2016	SBMS-I-096	3.17				
Room between Room 2 & 4	Sink	6/27/2016	SBMS-I-046	3.22											
Room between Room 2 & 4	Insta-Hot	6/27/2016	SBMS-I-047	ND											
Room 4 Island front of room	Sink	6/27/2016	SBMS-I-048	3.29											
Room 4 South Wall (Left)	Sink	6/27/2016	SBMS-I-049	1.72											
Room 4 South Wall (Middle)	Sink	6/27/2016	SBMS-I-050	3.67											
Room 4 South Wall (Right)	Sink	6/27/2016	SBMS-I-051	4.06											
Room 6	Fountain	6/27/2016	SBMS-I-052	1.68											
Room 6	Sink	6/27/2016	SBMS-I-053	7.08											
Room 6A	Sink	6/27/2016	SBMS-I-054	14.90											
Room 8 North Wall (Left)	Sink	6/27/2016	SBMS-I-055	11.90											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
Spencer Butte Middle School															
Room 8 North Wall (Middle)	Sink	6/27/2016	SBMS-I-056	7.03											
Room 8 North Wall (Right)	Sink	6/27/2016	SBMS-I-057	0.92											
Room 8 South Wall (Left)	Sink	6/27/2016	SBMS-I-058	3.76											
Room 8 South Wall (Middle)	Sink	6/27/2016	SBMS-I-059	50.70	8/18/2016	SBMS-F-093	1.52	8/26/2016	8/26/2016	SBMS-I-098	1.40				
Room 8 South Wall (Right)	Sink	6/27/2016	SBMS-I-060	27.30	8/18/2016	SBMS-F-094	1.09	8/26/2016	8/26/2016	SBMS-I-099	3.54				
Room 10	Sink	6/27/2016	SBMS-I-061	3.72											
Girls Restroom by Library (Left)	Sink	6/27/2016	SBMS-I-062	4.88											
Girls Restroom by Library (Right)	Sink	6/27/2016	SBMS-I-063	3.06											
Boys Restroom by Library (Left)	Sink	6/27/2016	SBMS-I-064	3.14											
Boys Restroom by Library (Right)	Sink	6/27/2016	SBMS-I-065	4.08											
Men's Faculty Restroom	Sink	6/27/2016	SBMS-I-066	0.91											
Outside Room 12	Fountain	6/27/2016	SBMS-I-067	7.98											
Faculty Women's Restroom (Left)	Sink	6/27/2016	SBMS-I-068	0.40											
Faculty Women's Restroom (Right)	Sink	6/27/2016	SBMS-I-069	0.47											
Staff Room 16A	Sink	6/27/2016	SBMS-I-070	2.37											
Across from Staff Room 16A	Fountain	6/27/2016	SBMS-I-071	6.83											
Room 3	Fountain	6/27/2016	SBMS-I-072	2.21											
Room 3	Sink	6/27/2016	SBMS-I-073	20.00											
Room 1	Fountain	6/27/2016	SBMS-I-074	2.04											
Room 1	Sink	6/27/2016	SBMS-I-075	45.20	8/18/2016	SBMS-F-089	4.52	8/26/2016	8/26/2016	SBMS-I-095	14.20				
Men's Wheelchair Access @ end of ramp (left)	Sink	6/27/2016	SBMS-I-076	3.69											
Men's Wheelchair Access @ end of ramp (Middle)	Sink	6/27/2016	SBMS-I-077	2.69											
Men's Wheelchair Access @ end of ramp (Right)	Sink	6/27/2016	SBMS-I-078	2.17											
Women's Wheelchair Access @ end of ramp (left)	Sink	6/27/2016	SBMS-I-079	3.53											
Women's Wheelchair Access @ end of ramp (Right)	Sink	6/27/2016	SBMS-I-080	1.77											
Staff Lounge across from Cafeteria	Sink	6/27/2016	SBMS-I-081	4.76											
Kitchen Restroom near exterior exit	Sink	6/27/2016	SBMS-I-082	6.38											
Kitchen Large Basin on Island - Sprayer	Sink	6/27/2016	SBMS-I-083	1.63											
Kitchen South Wall Hand Wash/Produce	Sink	6/27/2016	SBMS-I-084	0.99											
Cafeteria South Wall	Fountain	6/27/2016	SBMS-I-085	1.01											
Men's/Women Restroom nearest Office	Sink	6/27/2016	SBMS-I-086	1.76											
Hallway East of office	Fountain	6/27/2016	SBMS-I-087	2.36											
Kitchen Middle Island, North Side of Wall	Sink	8/18/2016	SBMS-I-091	1.47											
Cafeteria - Student Store	Sink	8/18/2016	SBMS-I-092	22.30	9/6/2016	SBMS-F-100	3.41	10/12/2016	10/13/2016	SBMS-I-101	12.70				
Custodial Closet, Southwest of Gym	Sink	10/20/2016	SBMS-I-102	ND											
Staff Room Refrigerator - In Freezer - Not Operational	Ice Machine														

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.