

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
Willagillespie Elementary School															
Girls Restroom near Office (North)	Sink	7/1/2016	WILES-I-001	0.46											
Girls Restroom near Office (North Center)	Sink	7/1/2016	WILES-I-002	1.13											
Girls Restroom near Office (South Center)	Sink	7/1/2016	WILES-I-003	0.78											
Girls Restroom near Office (South)	Sink	7/1/2016	WILES-I-004	0.91											
Boys Restroom near Office (South)	Sink	7/1/2016	WILES-I-005	0.57											
Boys Restroom near Office (South Center)	Sink	7/1/2016	WILES-I-006	0.75											
Boys Restroom near Office (North Center)	Sink	7/1/2016	WILES-I-007	0.93											
Boys Restroom near Office (North)	Sink	7/1/2016	WILES-I-008	0.83											
Room 26	Fountain	7/1/2016	WILES-I-009	4.32											
Room 26	Sink	7/1/2016	WILES-I-010	0.33											
Room 25	Fountain	7/1/2016	WILES-I-011	1.62											
Room 25	Sink	7/1/2016	WILES-I-012	1.43											
Room 24	Fountain	7/1/2016	WILES-I-013	2.61											
Room 24	Sink	7/1/2016	WILES-I-014	1.47											
Room 1	Fountain	7/1/2016	WILES-I-015	ND											
Room 1	Sink	7/1/2016	WILES-I-016	0.53											
Room 2	Fountain	7/1/2016	WILES-I-017	2.26											
Room 2	Sink	7/1/2016	WILES-I-018	33.90	8/29/2016	WILES-F-092	1.91	9/2/2016	9/7/2016	WILES-I-094	21.50	Replaced nipples and stops.	10/18/2016	WILES-I-094	4.96
Room 3	Fountain	7/1/2016	WILES-I-019	0.23											
Room 3	Sink	7/1/2016	WILES-I-020	0.69											
Room 5	Fountain	7/1/2016	WILES-I-021	0.22											
Room 5	Sink	7/1/2016	WILES-I-022	0.42											
Room 4	Fountain	7/1/2016	WILES-I-023	1.26											
Room 4	Sink	7/1/2016	WILES-I-024	9.57											
Room 6 South Restroom	Sink	7/1/2016	WILES-I-025	5.29											
Room 5 North Restroom	Sink	7/1/2016	WILES-I-026	1.68											
Room 6	Fountain	7/1/2016	WILES-I-027	2.21											
Room 6	Sink	7/1/2016	WILES-I-028	14.10											
Room 7-8	Sink	7/1/2016	WILES-I-029	0.59											
Room 7-8 Restroom	Sink	7/1/2016	WILES-I-030	0.54											
Kitchen Restroom	Sink	7/1/2016	WILES-I-031	5.54											
Kitchen Produce Sink	Sprayer	7/1/2016	WILES-I-032	0.64											
Kitchen Handwashing Sink	Sink	7/1/2016	WILES-I-033	1.93											
Kitchen Dishwashing Sink	Sink	7/1/2016	WILES-I-034	0.49											
Cafeteria	Fountain	7/1/2016	WILES-I-035	2.62											
Girls Restroom near Cafeteria (North)	Sink	7/1/2016	WILES-I-036	6.09											
Girls Restroom near Cafeteria (South)	Sink	7/1/2016	WILES-I-037	1.80											
Corridor outside Cafeteria	Fountain	7/1/2016	WILES-I-038	1.02											
Boys Restroom near Cafeteria (South)	Sink	7/1/2016	WILES-I-039	2.82											
Boys Restroom near Cafeteria (North)	Sink	7/1/2016	WILES-I-040	4.27											
Gym	Fountain	7/1/2016	WILES-I-041	0.70											
Library Workroom	Sink	7/1/2016	WILES-I-042	1.22											
Room 9	Fountain	7/1/2016	WILES-I-043	7.77											
Room 9	Sink	7/1/2016	WILES-I-044	2.13											
Room 10	Fountain	7/1/2016	WILES-I-045	6.70											
Room 10	Sink	7/1/2016	WILES-I-046	2.99											
Room 11	Fountain	7/1/2016	WILES-I-047	3.84											
Room 11	Sink	7/1/2016	WILES-I-048	3.22											
Room 12	Fountain	7/1/2016	WILES-I-049	4.43											
Room 12	Sink	7/1/2016	WILES-I-050	1.29											
Room 13	Fountain	7/1/2016	WILES-I-051	4.71											
Room 13	Sink	7/1/2016	WILES-I-052	1.42											
Room 14	Fountain	7/1/2016	WILES-I-053	3.83											
Room 14	Sink	7/1/2016	WILES-I-054	2.24											
Room 15	Fountain	7/1/2016	WILES-I-055	3.03											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw				Follow Up - New Fixture Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)	Additional Action	Date Sampled	Sample ID #	Result (ppb)
Room 15	Sink	7/1/2016	WILES-I-056	2.56											
Room 16	Fountain	7/1/2016	WILES-I-057	6.69											
Room 16	Sink	7/1/2016	WILES-I-058	3.14											
Room 17	Fountain	7/1/2016	WILES-I-059	3.63											
Room 17	Sink	7/1/2016	WILES-I-060	0.62											
Room 18	Fountain	7/1/2016	WILES-I-061	3.30											
Room 18	Sink	7/1/2016	WILES-I-062	1.01											
North Wing Corridor East End	Fountain	7/1/2016	WILES-I-063	0.39											
North Wing Corridor Staff Women's Restroom	Sink	7/1/2016	WILES-I-064	8.30											
North Wing Corridor Staff Men's Restroom	Sink	7/1/2016	WILES-I-065	9.43											
Room 40	Fountain	7/1/2016	WILES-I-066	0.67											
Room 40	Sink	7/1/2016	WILES-I-067	1.50											
Room 41	Fountain	7/1/2016	WILES-I-068	0.43											
Room 41	Sink	7/1/2016	WILES-I-069	0.62											
Room 19	Fountain	7/1/2016	WILES-I-070	0.59											
Room 19	Sink	7/1/2016	WILES-I-071	2.59											
Room 20	Fountain	7/1/2016	WILES-I-072	3.02											
Room 20	Sink	7/1/2016	WILES-I-073	0.99											
Room 21	Fountain	7/1/2016	WILES-I-074	1.16											
Room 21	Sink	7/1/2016	WILES-I-075	4.80											
Room 22	Fountain	7/1/2016	WILES-I-076	0.88											
Room 22	Sink	7/1/2016	WILES-I-077	1.13											
Room 23	Fountain	7/1/2016	WILES-I-078	0.59											
Room 23	Sink	7/1/2016	WILES-I-079	0.82											
Room 19-23 Corridor	Fountain	7/1/2016	WILES-I-080	2.45											
Room 19-23 Boys Restroom (West)	Sink	7/1/2016	WILES-I-081	1.34											
Room 19-23 Boys Restroom (East)	Sink	7/1/2016	WILES-I-082	3.37											
Room 19-23 Girls Restroom (East)	Sink	7/1/2016	WILES-I-083	1.90											
Room 19-23 Girls Restroom (West)	Sink	7/1/2016	WILES-I-084	1.68											
Administrative Mail/File Room	Sink	7/1/2016	WILES-I-085	0.79											
Health Room	Sink	7/1/2016	WILES-I-086	0.76											
Health Room Restroom	Sink	7/1/2016	WILES-I-087	ND											
Administrative West Staff Restroom	Sink	7/1/2016	WILES-I-088	0.32											
Administrative East Staff Restroom	Sink	7/1/2016	WILES-I-089	ND											
Staff Lounge	Insta-Hot	7/1/2016	WILES-I-090	0.73											
Staff Lounge	Sink	7/1/2016	WILES-I-091	0.32											
Principal Office	Sink	9/7/2016	WILES-I-093	ND											
Room 4 Restroom, South	Sink	9/7/2016	WILES-I-095	21.70	9/22/2016	WILES-F-097	ND	10/17/2016	10/18/2016	WILES-I-100	2.77				
Room 4 Restroom, North	Sink	9/7/2016	WILES-I-096	2.63											
Staff Room Refrigerator	Ice Machine	10/7/2016	WILES-I-098	ND											

Using EPA's water sampling method for schools, action level is >20 parts per billion (ppb). Samples that tested above the action level are highlighted.