

Radon test result report for:SILVER LEA BUILDING. PROGRAMS:
CORRIDOR AND YUJIN GAKUEN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9178219		2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	0.6 ± 0.3	2019-02-18
9178224	1	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.8 ± 0.3	2019-02-18
9178033	10	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178043	11	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178023	11	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.8 ± 0.3	2019-02-18
9178019	12	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178010	13	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178020	14	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.6 ± 0.3	2019-02-18
9178018	15	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178011	16	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178017	17	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178028	18	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.6 ± 0.3	2019-02-18
9178210	19	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178206	19	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178217	19A	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178209	2	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178205	20	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	0.5 ± 0.3	2019-02-18
9178211	21	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178218	21A	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178212	22	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178223	3	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	2.4 ± 0.4	2019-02-18
9178227	4	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.6 ± 0.3	2019-02-18
9178057	5	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.9 ± 0.3	2019-02-18
9178041	6	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.8 ± 0.3	2019-02-18
9178030	7	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178016	7A	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.7 ± 0.3	2019-02-18
9178012	8	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178026	9	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178027	9	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178190	BLANK	2019-02-12 @ 11:00 am	2019-02-15 @ 11:00 am	< 0.3	2019-02-18
9178186	BLANK	2019-02-12 @ 11:00 am	2019-02-15 @ 11:00 am	< 0.3	2019-02-18
9178226	CAFETERIA	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	1.1 ± 0.3	2019-02-18
9178220	CAFETERIA	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	1.2 ± 0.3	2019-02-18
9178225	GYM	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	0.9 ± 0.3	2019-02-18
9178035	IMC	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178042	LACTATION ROOM	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.6 ± 0.3	2019-02-18
9178034	LIBRARY	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	1.6 ± 0.3	2019-02-18

Radon test result report for:SILVER LEA BUILDING. PROGRAMS:
CORRIDOR AND YUJIN GAKUEN

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9178036	NURSE	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.6 ± 0.3	2019-02-18
9178037	OFFICE	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178015	OFFICE	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.6 ± 0.3	2019-02-18
9178203	P1	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178014	P2	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178021	P3	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178013	P4	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178201	PRINCIPLE OFFICE	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178202	STAFF	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178215	THE LEARNING CENTER	2019-02-11 @ 4:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178208	YG IMC	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	0.6 ± 0.3	2019-02-18
9178022	YG NURSE	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178025	YG OFFICE	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18
9178029	YG STAFF	2019-02-11 @ 3:00 pm	2019-02-14 @ 6:00 pm	< 0.3	2019-02-18