

Radon test result report for:**Facilities Management**

<b>Kit #</b>	<b>Room Id</b>	<b>Started</b>	<b>Ended</b>	<b>pCi/L</b>	<b>Analyzed</b>
9199264	10	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	1.9 ± 0.4	2019-03-25
9199252	11	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	2.0 ± 0.4	2019-03-25
9199267	17	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	1.2 ± 0.4	2019-03-25
9199258	2	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	2.9 ± 0.5	2019-03-25
9199263	20	2019-03-18 @ 4:00 pm	2019-03-21 @ 4:00 pm	0.5 ± 0.3	2019-03-25
9199260	20	2019-03-18 @ 4:00 pm	2019-03-21 @ 4:00 pm	< 0.3	2019-03-25
9199254	3	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	1.7 ± 0.4	2019-03-25
9199266	6	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	1.4 ± 0.4	2019-03-25
9199265	7	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	3.1 ± 0.4	2019-03-25
9199251	8	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	1.9 ± 0.4	2019-03-25
9199253	9	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	2.0 ± 0.4	2019-03-25
9199259	BARN 11	2019-03-18 @ 4:00 pm	2019-03-21 @ 4:00 pm	0.9 ± 0.4	2019-03-25
9199270	BARN 12	2019-03-18 @ 4:00 pm	2019-03-21 @ 4:00 pm	0.7 ± 0.4	2019-03-25
9199256	BARN 12D	2019-03-18 @ 4:00 pm	2019-03-21 @ 4:00 pm	0.6 ± 0.4	2019-03-25
9199421	BLANK	2019-03-19 @ 12:00 pm	2019-03-22 @ 11:00 am	< 0.3	2019-03-25
9199422	BLANK	2019-03-19 @ 12:00 pm	2019-03-22 @ 11:00 am	< 0.3	2019-03-25
9199262	ELEC	2019-03-18 @ 4:00 pm	2019-03-21 @ 4:00 pm	1.1 ± 0.4	2019-03-25
9199257	HVAC	2019-03-18 @ 4:00 pm	2019-03-21 @ 4:00 pm	2.9 ± 0.5	2019-03-25
9199255	OFFICE MAIN	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	2.5 ± 0.4	2019-03-25
9199261	OFFICE MAIN D	2019-03-18 @ 4:00 pm	2019-03-21 @ 3:00 pm	3.0 ± 0.4	2019-03-25