

Radon test result report for:

Transportation

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9199417	BLANK	2019-03-19 @ 12:00 pm	2019-03-22 @ 11:00 am	< 0.3	2019-03-25
9199237	BREAKROOM	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199229	BREAKROOM D	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199236	CONFERENCE ROOM	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199240	DIC	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199250	GARAGE	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199247	GARAGE	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199248	GARAGE	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199245	GARAGE	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199249	GARAGE	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199246	GARAGE	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199243	GARAGE OFFICE	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	0.6 ± 0.3	2019-03-25
9199244	GARAGE OFFICE D	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	0.6 ± 0.4	2019-03-25
9199235	MANAGERB	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199242	STAFF 1	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	0.8 ± 0.3	2019-03-25
9199241	STAFF 2	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	1.0 ± 0.3	2019-03-25
9199234	STAFF BREAK	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199239	SUPERVISOR	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25
9199238	TRAINING COORDINATOR	2019-03-18 @ 3:00 pm	2019-03-21 @ 3:00 pm	< 0.3	2019-03-25