

Eugene School District 4J
Water Quality: Lead Testing Results

Eugene School District 4J - Location	Fixture Type	First Draw			Flushed Draw			New Fixture First Draw			
		Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Fixture Replaced	Date Sampled	Sample ID #	Result (ppb)
4J Education Center											
Annex (ECCO) - Classroom 1 Sink	Sink	9/26/2019	A9I0952-01	1.21							
Annex (ECCO) - Classroom 2 Sink	Sink	9/26/2019	A9I0952-02	1.20							
Annex (ECCO) - Classroom 3 Sink	Sink	9/26/2019	A9I0952-03	1.84							
Annex (ECCO) - Classroom 4 Sink	Sink	9/26/2019	A9I0952-04	1.32							
Annex (ECCO) - Classroom 5 Sink	Sink	9/26/2019	A9I0952-05	0.90							
Annex (ECCO) - Classroom 6 Sink	Sink	9/26/2019	A9I0952-06	0.83							
Annex (ECCO) - Staff Restroom Sink	Sink	9/26/2019	A9I0952-07	0.29							
Annex (ECCO) - Womens Restroom Sink North faucet	Sink	9/26/2019	A9I0952-08	0.77							
Annex (ECCO) - Womens Restroom Sink Middle faucet	Sink	9/26/2019	A9I0952-09	0.46							
Annex (ECCO) - Womens Restroom Sink South faucet	Sink	9/26/2019	A9I0952-10	0.70							
Annex (ECCO) - Mens Restroom Sink South faucet	Sink	9/26/2019	A9I0952-11	1.00							
Annex (ECCO) - Mens Restroom Sink Middle faucet	Sink	9/26/2019	A9I0952-12	0.51							
Annex (ECCO) - Mens Restroom Sink North faucet	Sink	9/26/2019	A9I0952-13	0.50							
Annex (ECCO) - Lower Drinking Fountain	Fountain	9/26/2019	A9I0952-14	ND							
Annex (ECCO) - Upper Drinking Fountain	Fountain	9/26/2019	A9I0952-15	ND							
Annex (ECCO) - Served (Kitchen) Sink	Sink	9/26/2019	A9I0952-16	6.97							
Annex (ECCO) - Daycare Sink	Sink	9/26/2019	A9I0952-17	0.86							
Annex (ECCO) - Daycare Restroom Sink	Sink	9/26/2019	A9I0952-18	0.54							

Using EPA's water sampling method for schools, action level is 15 parts per billion or greater, EXCEPT prior to 2019 testing was >20 parts per billion (ppb). Samples that tested above the action level are highlighted.