

Parker/ Charlemagne Elementary- Lead Water Testing 2023		Water Test				Retest (if needed)				2nd Retest (if needed)				Resolution- Action Items
Location	Fixture Type	Date Sampled	Date Received	Sample ID #	Result (ppb)	Date Sampled	Date Received	Sample ID #	Result (ppb)	Date Sampled	Date Received	Sample ID #	Result (ppb)	
Room 1	Sink	10/11/22	11/4/22	20822400-068CF	2.37									
Room 1	Fountain	10/11/22	11/4/22	20822400-069DW	4.58									
Room 1	Sink	10/11/22	11/4/22	20822400-070BF	0.57									
Room 2	Sink	10/11/22	11/4/22	20822400-065CF	0.74									
Room 2	Fountain	10/11/22	11/4/22	20822400-066DW	4.00									
Room 2	Sink	10/11/22	11/4/22	20822400-067BF	0.20									
Room 3	Sink	10/11/22	11/4/22	20822400-062CF	9.82									
Room 3	Fountain	10/11/22	11/4/22	20822400-063DW	1.39									
Room 3	Sink	10/11/22	11/4/22	20822400-064BF	0.52									
Room 4	Sink	10/11/22	11/4/22	20822400-033CF	3.57									
Room 4	Fountain	10/11/22	11/4/22	20822400-034DW	1.32									
Room 5	Sink	10/11/22	11/4/22	20822400-037CF	1.44									
Room 5	Fountain	10/11/22	11/4/22	20822400-038DW	1.45									
Room 6	Sink	10/11/22	11/4/22	20822400-040CF	32.60	11/29/22	12/13/22	20822400-040CF	5.20					replaced fixture 11/28/22
Room 6	Fountain	10/11/22	11/4/22	20822400-041DW	1.31									
Room 7	Sink	10/11/22	11/4/22	20822400-042CF	10.10									
Room 7	Fountain	10/11/22	11/4/22	20822400-045DW	3.26									
Staff Restroom, Right	Sink	10/11/22	11/4/22	20822400-043BF	5.76									
Staff Restroom, Left	Sink	10/11/22	11/4/22	20822400-044BF	8.17									
Accessible Restroom, Right	Sink	10/11/22	11/4/22	20822400-057BF	11.70									
Accessible Restroom, Left	Sink	10/11/22	11/4/22	20822400-058BF	18.70	11/29/22	12/13/22	20822400-058BF	34.40	1/11/23	1/20/23	20822400-058BF	5.34	replaced fixture 11/28/22, Replaced supply valve 1/10/23
Vestibule Between Rooms 7 & 8	Bottle Filler	10/11/22	11/4/22	20822400-047WB	0.46									
Vestibule Between Rooms 7 & 8	Fountain	10/11/22	11/4/22	20822400-048DW	0.42									
Room 8	Sink	10/11/22	11/4/22	20822400-051CF	2.24									
Room 9	Sink	10/11/22	11/4/22	20822400-053CF	1.05									
Room 9	Sink	10/11/22	11/4/22	20822400-097CF	0.38									
Room 10 Restroom	Sink	10/11/22	11/4/22	20822400-052BF	0.42									
Room 10	Sink	10/11/22	11/4/22	20822400-055CF	2.78									
Room 10	Sink	10/11/22	11/4/22	20822400-056CF	1.60									
Room 11	Fountain	10/11/22	11/4/22	20822400-031DW	1.61									
Room 11	Sink	10/11/22	11/4/22	20822400-032CF	2.73									
Room 12	Fountain	10/11/22	11/4/22	20822400-029DW	1.13									
Room 12	Sink	10/11/22	11/4/22	20822400-030CF	1.35									
Room 13	Fountain	10/11/22	11/4/22	20822400-027DW	1.53									
Room 13	Sink	10/11/22	11/4/22	20822400-028CF	2.38									
Workroom	Sink	10/11/22	11/4/22	20822400-023DW	3.94									
Boy's Restroom, Right	Sink	10/11/22	11/4/22	20822400-022BF	0.33									
Boy's Restroom, Left	Sink	10/11/22	11/4/22	20822400-025BF	0.84									
Girl's Restroom, Left	Sink	10/11/22	11/4/22	20822400-019BF	0.73									
Girl's Restroom, Right	Sink	10/11/22	11/4/22	20822400-020BF	0.88									
Room 14	Fountain	10/11/22	11/4/22	20822400-017DW	6.94									
Room 14	Sink	10/11/22	11/4/22	20822400-018CF	1.05									
Room 15	Fountain	10/11/22	11/4/22	20822400-001DW	2.21									
Room 15	Sink	10/11/22	11/4/22	20822400-002CF	1.08									
Room 16	Fountain	10/11/22	11/4/22	20822400-003DW	3.49									
Room 16	Sink	10/11/22	11/4/22	20822400-004CF	70.50	11/29/22	12/13/22	20822400-004CF	5.51					Replaced supply valve 11/28/22
Room 17	Fountain	10/11/22	11/4/22	20822400-005DW	1.98									
Room 17	Sink	10/11/22	11/4/22	20822400-006CF	2.17									
Girl's Restroom, Left	Sink	10/11/22	11/4/22	20822400-010BF	0.90									
Girl's Restroom, Right	Sink	10/11/22	11/4/22	20822400-011BF	0.74									
Boy's Restroom, Left	Sink	10/11/22	11/4/22	20822400-008BF	0.94									
Boy's Restroom, Right	Sink	10/11/22	11/4/22	20822400-009BF	0.68									
Restroom Vestibule	Fountain	10/11/22	11/4/22	20822400-016DW	17.40	11/29/22	12/13/22	20822400-016DW	7.94					Replaced fixture 11/28/22
Room 18	Fountain	10/11/22	11/4/22	20822400-014DW	50.70	11/29/22	12/13/22	20822400-014DW	11.80					Replaced supply valve 11/28/22
Room 18	Sink	10/11/22	11/4/22	20822400-015CF	12.40									
Kitchen	Sprayer	10/11/22	11/4/22	20822400-079KF	26.60	11/29/22	12/13/22	20822400-079KF	2.31					replaced fixture 11/28/22
Kitchen	Sink	10/11/22	11/4/22	20822400-075KF	1.01									

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retesting until results were below 15 ppb

Parker/ Charlemagne Elementary- Lead Water Testing 2023		Water Test				Retest (if needed)				2nd Retest (if needed)				Resolution- Action Items
Location	Fixture Type	Date Sampled	Date Received	Sample ID #	Result (ppb)	Date Sampled	Date Received	Sample ID #	Result (ppb)	Date Sampled	Date Received	Sample ID #	Result (ppb)	
Kitchen	Sprayer	10/11/22	11/4/22	20822400-076OT	1.60									
Kitchen-Restroom	Sink	10/11/22	11/4/22	20822400-078BF	2.79									
Cafeteria Hallway	Fountain	10/11/22	11/4/22	20822400-084DW	0.91									
Cafeteria Hallway	Bottle Filler	10/11/22	11/4/22	20822400-085WB	0.97									
Women's Restroom, Left	Sink	10/11/22	11/4/22	20822400-080BF	1.41									
Women's Restroom, Right	Sink	10/11/22	11/4/22	20822400-081BF	0.64									
Men's Restroom, Left	Sink	10/11/22	11/4/22	20822400-071BF	1.10									
Men's Restroom, Right	Sink	10/11/22	11/4/22	20822400-072BF	1.01									
Nurses Office	Sink	10/11/22	11/4/22	20822400-089NF	1.28									
Main Office Restroom	Sink	10/11/22	11/4/22	20822400-094BF	4.42									
Library	Sink	10/11/22	11/4/22	20822400-088SF	9.47									
Staff Room	Sprayer	10/11/22	11/4/22	20822400-091OT	1.96									
Staff Room	Sink	10/11/22	11/4/22	20822400-092SF	1.10									
Staff Room	Sink	10/11/22	11/4/22	20822400-093OT	0.34									
Staff Restroom	Sink	10/11/22	11/4/22	20822400-096BF	0.62									

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retesting until results were below 15 ppb