

Edgewood Elementary- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Nurses Office	Sink	10/4/22	20822900-067NS23A	7.0							
Main Office Staff Room	Sink	10/4/22	20822900-070SF23A	0.7							
Main Office Staff Room	Insta-Hot	10/4/22	20822900-071OT23A	0.7							
Main Office Restroom	Sink	10/4/22	20822900-069BF23A	4.9							
Main Office Women's Restroom	Sink	10/4/22	20822900-078BF23A	3.2							
IMC Room / Production Room	Sink	10/4/22	20822900-077SF23A	7.2							
Library Work Room	Sink	10/4/22	20822900-080SF23A	10.1							
Main Office Library Hallway	Fountain	10/4/22	20822900-081DW23A	3.2							
Main Office Student Restroom	Sink	10/4/22	20822900-068BF23A	6.8							
Main Office Library Hallway Entry	Fountain	10/4/22	20822900-076DW23A	ND							
Main Office Library Hallway Entry	Bottle Filler	10/4/22	20822900-075WB23A	ND							
Main Office Work Room	Sink	10/4/22	20822900-079SF23A	0.2							
Room D1	Sink	10/4/22	20822900-096CF26A	3.1							
Room D1	Fountain	10/4/22	20822900-095DW23A	6.0							
Room D2	Sink	10/4/22	20822900-082CF23A	0.6							
Room D2	Fountain	10/4/22	20822900-083DW23A	0.7							
Doug Fir Girl's Restroom-Right	Sink	10/4/22	20822900-099BF23A	0.3							
Doug Fir Girl's Restroom-Left	Sink	10/4/22	20822900-098BF23A	0.5							
Doug Fir Boy's Restroom-Right	Sink	10/4/22	20822900-090BF23A	0.5							
Doug Fir Boy's Restroom-Left	Sink	10/4/22	20822900-089BF23A	0.4							
Room D3	Sink	10/4/22	20822900-084CF23A	4.7							
Room D3	Fountain	10/4/22	20822900-085DW23A	2.5							
Room D4	Sink	10/4/22	20822900-093CF23A	0.7							
Room D4	Fountain	10/4/22	20822900-094DW23A	1.0							
Room E1	Sink	10/4/22	20822900-109CF23A	2.8							
Room E1	Fountain	10/4/22	20822900-108DW23A	5.0							
Room E2	Sink	10/4/22	20822900-115CF23A	2.3							
Room E2	Fountain	10/4/22	20822900-114DW23A	8.0							
Evergreen Girl's Restroom-Right	Sink	10/4/22	20822900-112BF23A	0.5							
Evergreen Girl's Restroom-Left	Sink	10/4/22	20822900-111BF23A	1.6							
Evergreen Boy's Restroom-Left	Sink	10/4/22	20822900-103BF23A	3.3							
Evergreen Boy's Restroom-Right	Sink	10/4/22	20822900-104BF23A	9.7							
Room E3	Sink	10/4/22	20822900-100CF23A	1.4							
Room E3	Fountain	10/4/22	20822900-101DW23A	0.5							
Room E4	Sink	10/4/22	20822900-106CF23A	2.0							
Room E4	Fountain	10/4/22	20822900-105DW23A	1.7							
Room A1	Sink	10/4/22	20822900-022CF23A	2.7							
Alder Hallway-West	Fountain	10/4/22	20822900-024DW23A	13.2							
Alder Hallway-East	Fountain	10/4/22	20822900-032DW23A	39.3	11/8/22	20822900-032DW23A	7.9				Bubbler Head replaced 10/28/22
Room A2	Sink	10/4/22	20822900-023CF23A	2.8							
Alder Girl's Restroom-Right	Sink	10/4/22	20822900-026BF23A	46.9	11/8/22	20822900-026BF23A	3.3				Faucet replaced 10/28/22
Alder Girl's Restroom-Left	Sink	10/4/22	20822900-025BF23A	3.9							
Alder Boy's Restroom-Left	Sink	10/4/22	20822900-034BF23A	0.9							
Alder Boy's Restroom-Right	Sink	10/4/22	20822900-033BF23A	1.4							
Room A3	Sink	10/4/22	20822900-031CF23A	5.6							
Room A4	Sink	10/4/22	20822900-030CF23A	2.6							
Room B1	Sink	10/4/22	20822900-037CF23A	8.2							
Birch Hallway West Wall	Fountain	10/4/22	20822900-039DW23A	18.0	Fixture was removed since there is an adjacent fountain						Water Fountain removed 11/3/22

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest. ND test result- lead was not detected.

Edgewood Elementary- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Birch Hallway East Wall	Fountain	10/4/22	20822900-047DW23A	7.5							
Room B2	Sink	10/4/22	20822900-038CF23A	2.4							
Birch Girl's Restroom-Left	Sink	10/4/22	20822900-040BF23A	0.9							
Birch Girl's Restroom-Right	Sink	10/4/22	20822900-041BF23A	0.3							
Birch Boy's Restroom-Left	Sink	10/4/22	20822900-045BF23A	3.6							
Birch Boy's Restroom-Right	Sink	10/4/22	20822900-046BF23A	0.8							
Room B3	Sink	10/4/22	20822900-048CF23A	0.8							
Room B4	Sink	10/4/22	20822900-049CF23A	2.5							
Room C1	Sink	10/4/22	20822900-051CF23A	5.3							
Room C2	Sink	10/4/22	20822900-052CF23A	6.5							
Cedar Hallway West Wall	Fountain	10/4/22	20822900-053DW23A	1.8							
Cedar Hallway East Wall	Fountain	10/4/22	20822900-061DW23A	5.4							
Cedar Girl's Restroom-Right	Sink	10/4/22	20822900-055BF23A	8.7							
Cedar Girl's Restroom-Left	Sink	10/4/22	20822900-054BF23A	2.0							
Cedar Boy's Restroom Left	Sink	10/4/22	20822900-059BF23A	0.9							
Cedar Boy's Restroom Right	Sink	10/4/22	20822900-060BF23A	4.1							
Room C3	Sink	10/4/22	20822900-062CF23A	2.4							
Room C4	Sink	10/4/22	20822900-063CF23A	2.9							
Kitchen-Produce	Sink	10/4/22	20822900-012KF23A	3.7							
Kitchen-Produce Sprayer	Sprayer	10/4/22	20822900-116KF23A	0.6							
Kitchen-Hand Washing	Sink	10/4/22	20822900-013KF23A	0.3							
Kitchen-Dishwasher Sprayer	Sprayer	10/4/22	20822900-008KF23A	0.2							
Kitchen Restroom	Sink	10/4/22	20822900-009BF23A	11.5							
Cafeteria Hallway	Fountain	10/4/22	20822900-005DW23A	ND							
Cafeteria Hallway	Bottle Filler	10/4/22	20822900-006WB23A	ND							
Cafeteria Boy's Restroom-Right	Sink	10/4/22	20822900-003BF23A	1.1							
Cafeteria Boy's Restroom-Left	Sink	10/4/22	20822900-004BF23A	1.9							
Cafeteria Girl's Restroom-Left	Sink	10/4/22	20822900-016BF23A	3.7							
Cafeteria Girl's Bathroom-Right	Sink	10/4/22	20822900-015BF23A	0.5							
Music Room	Fountain	10/4/22	20822900-018DW23A	4.9							
Music Room	Sink	10/4/22	20822900-019CF23A	1.5							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest. ND test result- lead was not detected.