

Gilham Elementary- Lead Water Testing- includes building addition		Water Test				Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Results 2022 (parts per billion) Existing	Results 2023 (parts per billion) Addition	Date Sampled	Sample ID #	Results (parts per billion)	Date Sampled	Sample ID #	Results (parts per billion)	
Main entrance - Bottle Filler	Bottle Filler	12/3/21	20820600-051WB	ND								
Main entrance - Drinking Fountain	Fountain	12/3/21	20820600-052DW	ND								
D Center hallway Men's Restroom (left)	Sink	12/3/21	20820600-054BF	ND								
D Center hallway Men's Restroom (right)	Sink	12/3/21	20820600-053BF	0.5								
D Center hallway Women's Restroom (right)	Sink	12/3/21	20820600-073SF	12.5								
Unit D Center	Sink	9/8/21	20820600-067CF	10.6								
D1- (right)	Sink	10/15/21	20820600-057CF	2.7								
D1 (left)	Fountain	9/8/21	20820600-056DW	5.8								
D2 (left)	Fountain	9/8/21	20820600-059DW	2.1								
D2 (right)	Sink	9/8/21	20820600-060CF	5.4								
D3 (right)	Fountain	9/8/21	20820600-062DW	2.7								
D3 (left)	Sink	9/8/21	20820600-061CF	7.5								
D4 (left)	Sink	10/15/21	20820600-065CF	5.8								
Girls Restroom by B118 (left)	Sink	12/3/21	20820600-104BF	0.7								
Girls Restroom by B118 (middle)	Sink	12/3/21	20820600-105BF	0.2								
Girls Restroom by B118 (right)	Sink	12/3/21	20820600-106BF	0.5								
Outside Girls Restroom (Lower)	Fountain	12/3/21	20820600-107DW	0.4								
Outside Girls Restroom (Upper)	Fountain	12/3/21	20820600-108DW	0.6								
Unit E Interior (Right) of door (Right)	Fountain	12/3/21	20820600-005DW	ND								
Unit E Restroom	Sink	12/3/21	20820600-004BF	0.2								
E4 (left)	Sink	4/8/22	20820600-001CF	0.9								
E4 (right)	Fountain	12/3/21	20820600-002DW	1.7								
E3 (left)	Fountain	12/3/21	20820600-008DW	1.2								
E3 (right)	Sink	3/15/22	20820600-007CF	2.0								
E2 (left)	Fountain	12/3/21	20820600-014DW	1.0								
E2 (right)	Sink	3/15/22	20820600-013CF	3.5								
E1 (left)	Fountain	12/3/21	20820600-012DW	2.4								
E1 (right)	Sink	4/8/22	20820600-011CF	1.1								
Unit E Center	Sink	2/8/22	20820600-009CF	11.6								
Unit F Interior (right) of door (Upper)	Fountain	12/3/21	20820600-032DW	ND								
Unit F Interior (right) of door (Lower)	Fountain	12/3/21	20820600-031DW	0.6								
Unit F Restroom	Sink	12/3/21	20820600-018BF	ND								
F4 (left)	Fountain	12/3/21	20820600-017DW	3.8								
F4 (right)	Fountain	3/15/22	20820600-016CF	3.3								
F3 (left)	Fountain	12/3/21	20820600-021DW	0.3								
F3 (right)	Sink	3/15/22	20820600-020CF	2.9								
F2 (left)	Fountain	12/3/21	20820600-024DW	0.8								
F2 (right)	Sink	3/15/22	20820600-023CF	1.3								
F1 (left)	Sink	4/8/22	20820600-034CF	0.7								
F1 (right)	Fountain	12/3/21	20820600-033DW	0.9								
Unit F Center	Sink	3/15/22	20820600-019CF	2.3								
Boys Restroom by A101 (left)	Sink	12/3/21	20820600-140BF	0.2								
Boys Restroom by A101 (middle)	Sink	12/3/21	20820600-141BF	ND								
Boys Restroom by A101 (right)	Sink	12/3/21	20820600-142BF	ND								
Girls Restroom by A101 (left)	Sink	12/3/21	20820600-136BF	ND								
Girls Restroom by A101 (middle)	Sink	12/3/21	20820600-137BF	0.2								
Girls Restroom By a101 (right)	Sink	12/3/21	20820600-138BF	1.0								
Hallway across from A101 (Lower)	Fountain	12/3/21	20820600-134DW	ND								
Hallway across from A101 (Upper)	Bottle Filler	12/3/21	20820600-135WB	ND								
Cafeteria - North wall (Lower)	Fountain	12/3/21	20820600-119DW	0.3								
Cafeteria - North wall (Upper)	Fountain	12/3/21	20820600-120DW	0.8								
Kitchen West Wall Sprayer	Sprayer	12/3/21	20820600-122KF	0.3								
Kitchen Northwest Corner	Sink	12/3/21	20820600-131KF	1.9								
Kitchen Center Island Large Prep (right)	Sink	12/3/21	20820600-129KF	3.3								
Kitchen Center Island Large Prep (Left)	Sink	12/3/21	20820600-128KF	7.1								
Kitchen Restroom	Sink	12/3/21	20820600-130BF	ND								
Kitchen Basin Sprayer	Sprayer	12/3/21	20820600-127KF	13.4								
Kitchen Produce Sprayer	Sprayer	12/3/21	20820600-126KF	0.3								
Kitchen By Service window (left)	Sink	12/3/21	20820600-125KF	4.6								
Kitchen by Service Window (right)	Sink	12/3/21	20820600-123KF	0.9								
Room B101	Sink	12/3/21	20820600-118CF	0.5								
Room B101	Fountain	12/3/21	20820600-117DW	4.8								
Room B102	Fountain	12/3/21	20820600-115DW	3.3								
Room B102	Sink	12/3/21	20820600-116CF	0.6								
Room B103	Fountain	12/3/21	20820600-110DW	3.9								
Room B103	Sink	12/3/21	20820600-111CF	0.9								
Room B104	Sink	12/3/21	20820600-113CF	0.7								
Room B107	Fountain	12/3/21	20820600-101DW	2.0								

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.
ND result- lead was not detected

Gilham Elementary- Lead Water Testing- includes building addition		Water Test				Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Results 2022 (parts per billion) Existing	Results 2023 (parts per billion) Addition	Date Sampled	Sample ID #	Results (parts per billion)	Date Sampled	Sample ID #	Results (parts per billion)	
Room B107	Sink	12/3/21	20820600-102CF	3.4								
Room B109	Sink	12/3/21	20820600-098CF	0.4								
Room B109	Fountain	12/3/21	20820600-097DW	4.6								
Room B110	Fountain	12/3/21	20820600-086DW	1.2								
Room B110	Sink	12/3/21	20820600-087CF	1.0								
Room B111	Sink	12/3/21	20820600-089CF	0.8								
Room B111	Fountain	12/3/21	20820600-088DW	2.3								
Room B112	Sink	12/3/21	20820600-028CF	0.8								
Room B112	Fountain	12/3/21	20820600-027DW	0.3								
Room B113	Fountain	12/3/21	20820600-029DW	2.5								
Room B113	Sink	12/3/21	20820600-030CF	0.6								
Hallway across from B109 (Lower)	Fountain	12/3/21	20820600-092DW	0.8								
Hallway across from B109 (Upper)	Fountain	12/3/21	20820600-093DW	0.4								
Boys Restroom next to B117 (left)	Sink	12/3/21	20820600-096BF	0.3								
Boys Restroom next to B117 (middle)	Sink	12/3/21	20820600-095BF	0.3								
Boys Restroom next to B117 (right)	Sink	12/3/21	20820600-094BF	0.3								
Room C121	Sink	12/3/21	20820600-075CF	3.8								
Room C121	Fountain	12/3/21	20820600-076DW	6.6								
Library Office	Sink	2/8/22	20820600-081SF	4.5								
Room C106	Sink	12/3/21	20820600-084CF	4.3								
Room C109	Fountain	12/3/21	20820600-083DW	10.7								
Room C109	Sink	12/3/21	20820600-082CF	3.5								
Room C112	Sink	12/3/21	20820600-077SF	1.1								
Staff Room	Sink	12/3/21	20820600-045SF	0.8								
Staff Room	Insta-Hot	12/3/21	20820600-044OT	ND								
Staff Room Men's Restroom	Sink	12/3/21	20820600-046BF	0.5								
Staff Room Women's Restroom	Sink	12/3/21	20820600-047BF	0.3								
C120 First Aid Room	Sink	12/3/21	20820600-048NS	2.5								
Women's Restroom near D Pod (L)	Sink	12/3/21	20820600-069BF	0.5								
B104	Fountain	12/3/21	20820600-112DW	0.3								
A119 (Music Room)	Sink	12/3/21	20820600-144CF	ND								
Staff Room Refrigerator - In Door	Water D.	12/3/21	20820600-043OT	ND								
Staff Room Refrigerator - In Door	Ice Machine	12/3/21	20820600-145OT	ND								
Room C122 Learning Center	Fountain	12/3/21	20820600-079DW	1.2								
Room C122 Learning Center	Sink	3/15/22	20820600-078CF	4.1								
Room C124 Multi-Purpose Room Left	Sink	3/15/22	20820600-040CF	1.2								
Room C124 Multi-Purpose Room Left	Fountain	12/3/21	20820600-039DW	1.0								
Room C124 Multi-Purpose Room Right	Sink	3/15/22	20820600-041CF	0.8								
Room C124 Multi-Purpose Room Utility	Sink	12/3/21	20820600-085CF	ND								
Room B116A - Single Occ Restroom	Sink	12/3/21	20820600-145OT	ND								
PE Coaches Office Bathroom	Sink	12/3/21	20820600-121BF	0.2								
B128 Community Room	Sink	3/15/22	20820600-071CF	2.1								
B128 Community Room	Fountain	12/3/21	20820600-072DW	2.2								
Women's Restroom near D Pod (R)	Sink	12/3/21	20820600-068BF	0.3								
Unit E Interior (Right) of door (Left)	Fountain	12/3/21	20820600-006DW	ND								
Nurse Office Bathroom	Sink	12/3/21	20820600-049BF	0.3								
G Pod Gir's Bathroom	Sink	8/5/22	20820600-146BF		0.4							
G Pod Gir's Bathroom	Sink	8/5/22	20820600-147BF		0.5							
G101	Sink	8/5/22	20820600-148CF		0.5							
G101	Fountain	8/5/22	20820600-149DW		0.5							
G102	Sink	8/5/22	20820600-150CF		0.6							
G102	Fountain	8/5/22	20820600-151DW		0.2							
G103	Fountain	8/5/22	20820600-152DW		0.5							
G103	Sink	8/5/22	20820600-153CF		0.5							
G104	Fountain	8/5/22	20820600-154DW		NC							
G104	Sink	8/5/22	20820600-155CF		0.5							
G Pod Boy's Bathroom	Sink	8/5/22	20820600-156BF		0.4							
G Pod Boy's Bathroom	Sink	8/5/22	20820600-157BF		0.7							
Auxiliary Gym Bathroom Faucet	Sink	8/5/22	20820600-158BF		0.7							
Main Hallway By F1-New Installation	Fountain	1/20/23	2082600-159DW		ND							
Main Hallway By F1-New Installation	Bottle Filler	1/20/23	2082600-160WB		ND							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.
ND result- lead was not detected