

South Eugene HS- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Custodial Room	Sink	10/20/22	20822200-028SF	ND							
Pre-school Changing Room	Sink	10/20/22	20822200-054BF	48.8	11/29/22	20822200-054BF	1.0				replaced fixture 11/9/22
Pre-school Changing Room	Sink	10/20/22	20822200-055BF	1.0							
Hallway 200	Fountain	10/20/22	20822200-108DW	6.4							
Staff Restroom	Sink	10/20/22	20822200-112BF	2.9							
Room 204 Dish Room	Sink	10/20/22	20822200-077CF	1.3							
Room 204 Dish Room	Sprayer	10/20/22	20822200-078CF	22.8	11/29/22	20822200-078CF	2.4				replaced fixture 11/9/22
Room 204	Sink	10/20/22	20822200-105CF	0.2							
Room 204	Sink	10/20/22	20822200-110CF	0.9							
Room 204	Sink	10/20/22	20822200-113CF	0.4							
Room 204	Sink	10/20/22	20822200-114CF	0.4							
Room 204	Sink	10/20/22	20822200-111CF	0.3							
Room 204	Sink	10/20/22	20822200-109CF	ND							
Room 205 Kitchen	Sink	10/20/22	20822200-116SF	0.4							
Room 205	Sink	10/20/22	20822200-117CF	157.0	11/29/22	20822200-117CF	25.3	1/11/23	20822200-117CF	1.2	replaced fixture 11/9/22, replaced supply valve 1/9/23
Room 205	Sink	2/22/23	20822200-329CF	14.1							
Hallway 200	Fountain	10/20/22	20822200-121DW	1.6							
Main Office Staff Room	Sink	10/20/22	20822200-122SF	3.7							
Corridor By Main Office	Bottle Filler	10/20/22	20822200-125WB	ND							
Corridor By Main Office	Fountain	10/20/22	20822200-126DW	ND							
Corridor By Room 13	Fountain	10/20/22	20822200-130DW	36.9	11/29/22	20822200-130DW	10.3				replaced fixture 11/10/22
Hallway 300	Fountain	10/20/22	20822200-273DW	15.0	11/29/22	20822200-273DW	22.5	1/11/23	20822200-273DW	82.5	replaced fixture 11/10/22, Removed fixture 2/1/23
Girls Restroom By Library, Left	Sink	10/20/22	20822200-275BF	1.5							
Girls Restroom By Library, Right	Sink	10/20/22	20822200-276BF	0.8							
Girls Restroom By Library, Left	Sink	10/20/22	20822200-133BF	0.4							
Girls Restroom By Library, Right	Sink	10/20/22	20822200-134BF	0.7							
Boy's Restroom By Library, Right	Sink	10/20/22	20822200-144BF	1.2							
Boy's Restroom By Library, Left	Sink	10/20/22	20822200-145BF	1.4							
Boy's Restroom By Library, Right	Sink	10/20/22	20822200-140BF	0.3							
Boy's Restroom By Library, Left	Sink	10/20/22	20822200-141BF	0.7							
Library Staff Restroom	Sink	10/20/22	20822200-137BF	2.0							
Library Staff Room	Sink	10/20/22	20822200-138SF	3.2							
Room 19	Sink	10/20/22	20822200-139SF	2.7							
Hallway 400, Girl's Restroom, Right	Sink	10/20/22	20822200-149BF	0.4							
Hallway 400, Girl's Restroom, Left	Sink	10/20/22	20822200-150BF	0.5							
Family Room	Sink	10/20/22	20822200-269BF	0.7							
Hallway 400	Fountain	10/20/22	20822200-270DW	2.6							
Hallway 400	Fountain	10/20/22	20822200-147DW	5.5							
Girl's Restroom, By Classroom 27	Sink	10/20/22	20822200-155BF	0.5							
Girl's Restroom, By Classroom 27	Sink	10/20/22	20822200-156BF	0.8							
Girl's Restroom, By Classroom 27	Sink	10/20/22	20822200-151BF	0.6							
Girl's Restroom, By Classroom 27	Sink	10/20/22	20822200-152BF	1.4							
Boy's Restroom, By Classroom 27	Sink	10/20/22	20822200-160BF	1.2							
Boy's Restroom, By Classroom 27	Sink	10/20/22	20822200-161BF	2.4							
Boy's Restroom, By Classroom 27	Sink	10/20/22	20822200-157BF	0.8							
Boy's Restroom, By Classroom 27	Sink	10/20/22	20822200-158BF	0.9							
Corridor @ Room 31	Fountain	10/20/22	20822200-278DW	1.5							
All Gender Restroom	Sink	10/20/22	20822200-164BF	4.8							
Hallway 700, Boy's Restroom	Sink	10/20/22	20822200-280BF	1.5							
Hallway 700, Boy's Restroom	Sink	10/20/22	20822200-281BF	1.0							
Hallway 700, Boy's Restroom	Sink	10/20/22	20822200-282BF	0.6							
Hallway 700, Boy's Restroom	Sink	10/20/22	20822200-283BF	0.9							
Hallway 700, Girl's Restroom	Sink	10/20/22	20822200-286BF	5.8							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.

ND test result- lead was not detected

South Eugene HS- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Hallway 700, Girl's Restroom	Sink	10/20/22	20822200-287BF	6.3							
Hallway 700, Girl's Restroom	Sink	10/20/22	20822200-288BF	3.5							
Hallway 700, Girl's Restroom	Sink	10/20/22	20822200-289BF	2.4							
Room 721	Sink	10/20/22	20822200-291SF	5.9							
Hallway 700	Fountain	10/20/22	20822200-292DW	ND							
Hallway 700	Bottle Filler	10/20/22	20822200-293WB	ND							
Hallway 700, Boy's Restroom	Sink	10/20/22	20822200-294BF	2.6							
Hallway 700, Boy's Restroom	Sink	10/20/22	20822200-295BF	1.4							
Hallway 700, Boy's Restroom	Sink	10/20/22	20822200-296BF	0.7							
Hallway 700, Boy's Restroom	Sink	10/20/22	20822200-297BF	0.6							
Hallway 700	Fountain	10/20/22	20822200-299DW	4.6							
Hallway 700, Girl's Restroom	Sink	10/20/22	20822200-301BF	1.8							
Hallway 700, Girl's Restroom	Sink	10/20/22	20822200-302BF	4.0							
Hallway 700, Girl's Restroom	Sink	10/20/22	20822200-303BF	0.5							
Hallway 700, Girl's Restroom	Sink	10/20/22	20822200-304BF	2.1							
Hallway 700	Fountain	10/20/22	20822200-305DW	1.3							
Hallway By Classroom 7	Fountain	10/20/22	20822200-115DW	1.4							
Room 205	Sink	10/20/22	20822200-323CF	0.5							
Hallway By Library	Fountain	10/20/22	20822200-136DW	0.7							
Hallway By Classroom 21	Fountain	10/20/22	20822200-146DW	1.6							
Auditorium Lobby, Men's Restroom	Sink	10/20/22	20822200-165BF	1.7							
Auditorium Lobby, Men's Restroom	Sink	10/20/22	20822200-166BF	4.4							
Auditorium Lobby, Men's Restroom	Sink	10/20/22	20822200-167BF	6.0							
Auditorium Lobby	Fountain	10/20/22	20822200-175DW	13.8							
Auditorium Lobby	Fountain	10/20/22	20822200-173DW	12.9							
Auditorium Lobby, Women's Restroom	Sink	10/20/22	20822200-169BF	1.2							
Auditorium Lobby, Women's Restroom	Sink	10/20/22	20822200-170BF	1.2							
Auditorium Lobby, Women's Restroom	Sink	10/20/22	20822200-171BF	2.8							
Hallway 500, Boy's Restroom	Sink	10/20/22	20822200-179BF	5.0							
Hallway 500, Boy's Restroom	Sink	10/20/22	20822200-180BF	0.8							
Hallway 500, Boy's Restroom, Center	Sink	10/20/22	20822200-324BF	17.5	11/29/22	20822200-324BF	1.0				replaced fixture 11/12/22
Hallway 500, Boy's Restroom	Sink	10/20/22	20822200-182BF	0.8							
Hallway 500, Boy's Restroom	Sink	10/20/22	20822200-183BF	0.6							
Hallway 500, By Classroom 504	Fountain	10/20/22	20822200-178DW	6.9							
Hallway 500, Girl's Restroom	Sink	10/20/22	20822200-219BF	0.9							
Hallway 500, Girl's Restroom, Center	Sink	10/20/22	20822200-325BF	0.7							
Hallway 500, Girl's Restroom	Sink	10/20/22	20822200-220BF	0.9							
Hallway 500, Girl's Restroom	Sink	10/20/22	20822200-185BF	0.8							
Hallway 500, Girl's Restroom	Sink	10/20/22	20822200-186BF	5.9							
Backstage Hallway	Fountain	10/20/22	20822200-187DW	1.3							
Backstage Student Restroom	Sink	10/20/22	20822200-189BF	0.6							
Backstage Staff Restroom	Sink	10/20/22	20822200-190BF	0.8							
Choir Room	Fountain	10/20/22	20822200-188DW	2.5							
Band Room	Fountain	10/20/22	20822200-192DW	2.8							
Room 517B	Sink	10/20/22	20822200-193SF	15.4	11/29/22	20822200-193SF	5.3				replaced fixture 11/12/22
Room 517C	Sink	10/20/22	20822200-195SF	2.7							
Hallway By Room 521A	Fountain	10/20/22	20822200-215DW	2.4							
Women's Restroom By Classroom 523	Sink	10/20/22	20822200-213BF	0.5							
Room 521	Sink	10/20/22	20822200-217CF	4.6							
Men's Restroom By Classroom 523	Sink	10/20/22	20822200-211BF	0.3							
Room 523-01	Sink	10/20/22	20822200-214CF	15.9	11/29/22	20822200-214CF	5.8				replaced fixture 11/12/22
Hallway By Classroom 524	Fountain	10/20/22	20822200-209DW	ND							
Hallway By Classroom 524	Bottle Filler	10/20/22	20822200-210WB	ND							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.  
ND test result- lead was not detected

South Eugene HS- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Art Room	Sink	10/20/22	20822200-204CF	0.5							
Art Room	Sink	10/20/22	20822200-207CF	0.3							
Art Room	Sink	10/20/22	20822200-208CF	5.9							
Room 531	Sink	10/20/22	20822200-201SF	0.9							
Room 528	Sink	10/20/22	20822200-309CF	5.9							
Room 528 Shop	Sink	10/20/22	20822200-206CF	7.0							
Room 532	Sink	10/20/22	20822200-202SF	3.1							
Hallway By 534	Fountain	10/20/22	20822200-198DW	0.3							
Women's Restroom By Classroom 534, Left	Sink	10/20/22	20822200-199BF	0.4							
Women's Restroom By Classroom 534, Right	Sink	10/20/22	20822200-200BF	0.8							
Men's Restroom By Classroom 534, Right	Sink	10/20/22	20822200-196BF	1.4							
Men's Restroom By Classroom 534, Left	Sink	10/20/22	20822200-197BF	5.9							
Room 729	Sink	10/20/22	20822200-279BF	6.5							
Science Building, All Gender Restroom	Sink	10/20/22	20822200-260BF	1.3							
Room 422-RC	Sink	10/20/22	20822200-257SF	4.7							
Room 422-S	Sink	10/20/22	20822200-258SF	0.4							
Room 418-Y	Sink	10/20/22	20822200-247SF	0.2							
Hallway By Classroom 419	Fountain	10/20/22	20822200-238DW	ND							
Hallway By Classroom 419	Bottle Filler	10/20/22	20822200-239WB	ND							
Room 420	Sink	10/20/22	20822200-234SF	0.8							
Hydrant By Concession Building	Sink	10/20/22	20822200-321OT	5.0							
Softball Complex Building	Fountain	10/20/22	20822200-310DW	ND							
Softball Complex Building	Fountain	10/20/22	20822200-311DW	ND							
Softball Complex Building	Bottle Filler	10/20/22	20822200-312WB	ND							
Softball Complex Building, Boys	Sink	10/20/22	20822200-316BF	0.8							
Softball Complex Building, Boys	Sink	10/20/22	20822200-317BF	ND							
Softball Complex Building, Girls	Sink	10/20/22	20822200-313BF	ND							
Softball Complex Building, Girls	Sink	10/20/22	20822200-314BF	0.2							
Softball Complex Building, Accessible Restroom	Sink	10/20/22	20822200-315BF	0.6							
Concessions Building	Sink	10/20/22	20822200-319OT	1.2							
Concessions Building	Sink	10/20/22	20822200-320OT	2.3							
Kitchen	Sink	10/20/22	20822200-011KF	0.5							
Kitchen, Sprayer	Sprayer	10/20/22	20822200-009KF	0.7							
Kitchen	Sink	10/20/22	20822200-328KF	0.6							
Kitchen	Sink	10/20/22	20822200-007KF	2.3							
Kitchen	Sink	10/20/22	20822200-002BF	0.8							
Kitchen	Sink	10/20/22	20822200-006KF	3.2							
Kitchen	Sink	10/20/22	20822200-008KF	0.5							
Kitchen	Sink	10/20/22	20822200-280KF	2.2							
Kitchen	Sink	10/20/22	20822200-010KF	1.7							
Cafeteria	Fountain	10/20/22	20822200-004DW	0.6							
Cafeteria	Fountain	10/20/22	20822200-005DW	0.9							
Cafeteria	Fountain	10/20/22	20822200-013DW	ND							
Cafeteria	Fountain	10/20/22	20822200-014DW	ND							
Cafeteria	Fountain	10/20/22	20822200-023DW	3.7							
Cafeteria	Fountain	10/20/22	20822200-024DW	1.5							
Cafeteria, Staff Room	Sink	10/20/22	20822200-025SF	0.7							
Cafeteria, Snack Bar	Sink	10/20/22	20822200-119KF	1.6							
Cafeteria, Snack Bar	Sink	10/20/22	20822200-120KF	ND							
Hallway 300	Fountain	10/20/22	20822200-020DW	ND							
Hallway 300	Bottle Filler	10/20/22	20822200-021WB	ND							
Hallway 300, Girls Restroom	Sink	10/20/22	20822200-015BF	0.4							
Hallway 300, Girls Restroom	Sink	10/20/22	20822200-016BF	0.8							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.

ND test result- lead was not detected

South Eugene HS- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Hallway 300, Girls Restroom	Sink	10/20/22	20822200-018BF	0.3							
Hallway 300, Girls Restroom	Sink	10/20/22	20822200-019BF	0.8							
Hallway 300, Boys Restroom	Sink	10/20/22	20822200-129BF	0.8							
Hallway 300, Boys Restroom	Sink	10/20/22	20822200-128BF	0.2							
Hallway 300, Boys Restroom	Sink	10/20/22	20822200-123BF	0.4							
Hallway 300, Boys Restroom	Sink	10/20/22	20822200-124BF	0.5							
Room 422-S	Insta-Hot	10/20/22	20822200-327OT	ND							
Room 523	Sink	10/20/22	20822200-326CF	1.8							
Hallway By Health Center	Fountain	10/20/22	20822200-070DW	1.8							
Health Center	Sink	10/20/22	20822200-032BF	1.0							
Health Center	Sink	10/20/22	20822200-031NS	34.1	11/29/22	20822200-031NS	8.9				replaced fixture 11/12/22
Health Center	Sink	10/20/22	20822200-034NS	3.8							
Health Center	Insta-Hot	10/20/22	20822200-035OT	ND							
Health Center	Sink	10/20/22	20822200-068NS	1.2							
Health Center	Sink	10/20/22	20822200-069BF	1.4							
Hallway By Weight Room	Fountain	10/20/22	20822200-039DW	ND							
Hallway By Weight Room	Bottle Filler	10/20/22	20822200-040WB	ND							
Girl's PE Office	Sink	10/20/22	20822200-041BF	3.8							
Small Gymnasium	Fountain	10/20/22	20822200-036DW	4.6							
Training Room	Sink	10/20/22	20822200-319SF	1.3							
Training Room	Sink	10/20/22	20822200-320SF	3.3							
Training Room	Ice Machine	10/20/22	20822200-079IM	ND							
Training Room	Sink	10/20/22	20822200-073SF	1.2							
Hallway By Training Room	Fountain	10/20/22	20822200-071DW	ND							
Hallway By Training Room	Bottle Filler	10/20/22	20822200-072WB	ND							
All Gender Restroom By Room 1	Sink	10/20/22	20822200-104BF	0.4							
Gymnasium Lobby, Boy's Restroom	Sink	10/20/22	20822200-097BF	3.0							
Gymnasium Lobby, Boy's Restroom	Sink	10/20/22	20822200-098BF	1.8							
Gymnasium Lobby, Boy's Restroom	Sink	10/20/22	20822200-099BF	1.7							
Gymnasium Lobby, Boy's Restroom	Sink	10/20/22	20822200-100BF	2.8							
Gymnasium Lobby, Boy's Restroom	Sink	10/20/22	20822200-101BF	1.0							
Gymnasium Lobby, Boy's Restroom	Sink	10/20/22	20822200-102BF	0.6							
Gymnasium Lobby, Girl's Restroom	Sink	10/20/22	20822200-089BF	1.1							
Gymnasium Lobby, Girl's Restroom	Sink	10/20/22	20822200-090BF	1.4							
Gymnasium Lobby, Girl's Restroom	Sink	10/20/22	20822200-091BF	3.0							
Gymnasium Lobby, Girl's Restroom	Sink	10/20/22	20822200-092BF	3.7							
Gymnasium Lobby, Girl's Restroom	Sink	10/20/22	20822200-093BF	1.9							
Gymnasium Lobby, Girl's Restroom	Sink	10/20/22	20822200-094BF	7.2							
Gymnasium Concessions	Sink	10/20/22	20822200-086KF	1.1							
Gymnasium Lobby	Fountain	10/20/22	20822200-088DW	0.6							
Gymnasium Lobby	Fountain	10/20/22	20822200-095DW	2.0							
Gymnasium Upper Floor	Fountain	10/20/22	20822200-308DW	ND							
Gymnasium Upper Floor	Fountain	10/20/22	20822200-306DW	ND							
Gymnasium Upper Floor	Bottle Filler	10/20/22	20822200-307WB	ND							
Room 113	Sink	10/20/22	20822200-033CF	6.4							
Concession Room 326, Snack Bar	Ice Machine	10/20/22	20822200-022IM	ND							
Girl's Locker Room	Ice Machine	10/20/22	20822200-277IM	ND							
Girl's Locker Room	Sink	10/20/22	20822200-037BF	0.4							
Girl's Locker Room	Sink	10/20/22	20822200-038BF	0.3							
Girl's Locker Room	Fountain	10/20/22	20822200-043DW	ND							
Girl's Locker Room	Bottle Filler	10/20/22	20822200-044WB	ND							
Girl's Locker Room	Fountain	10/20/22	20822200-045DW	ND							
Girl's Locker Room	Bottle Filler	10/20/22	20822200-046WB	ND							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.

ND test result- lead was not detected

South Eugene HS- Lead Water Testing 2023		Water Test			Retest (if needed)			2nd Retest (if needed)			Resolution- Action Items
Location	Fixture Type	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	Date Sampled	Sample ID #	Result (ppb)	
Girl's Locker Room	Sink	10/20/22	20822200-048BF	5.7							
Girl's Locker Room	Sink	10/20/22	20822200-049BF	1.6							
Girl's Locker Room	Sink	10/20/22	20822200-050BF	6.5							
Girl's Locker Room	Sink	10/20/22	20822200-051BF	2.5							
Boy's Locker Room	Fountain	10/20/22	20822200-057DW	4.6							
Boy's Locker Room	Ice Machine	10/20/22	20822200-059IM	ND							
Boy's Locker Room	Sink	10/20/22	20822200-060BF	1.6							
Boy's Locker Room	Sink	10/20/22	20822200-061BF	0.4							
Boy's Locker Room	Fountain	10/20/22	20822200-062DW	1.1							
Boy's Locker Room	Sink	10/20/22	20822200-063BF	0.6							
Boy's Locker Room	Fountain	10/20/22	20822200-064DW	2.9							
Main Gymnasium	Sink	10/20/22	20822200-065BF	6.3							
Main Gymnasium	Fountain	10/20/22	20822200-067DW	1.4							
Main Gymnasium	Fountain	10/20/22	20822200-103DW	0.7							
Main Gymnasium	Fountain	10/20/22	20822200-085DW	1.2							
Turf Sports Field- west	Hydrant	11/29/22	20822200-318OT	55.1	1/11/23	20822200-318OT	4.4				replaced hydrant 1/9/23
Classroom 205	Sink	2/22/23	20822200-329CF	14.1							

Water test results above OHA/ EPA action level of 15.0 parts per billion (ppb) required remedial action and retest.  
ND test result- lead was not detected