



Harborfields Central School District

2 OLDFIELD ROAD • GREENLAWN, NEW YORK 11740-1200

(631) 754-5320 Ext. 321 • FAX (631) 261-0068

Diana Todaro
Superintendent of Schools

November 15, 2016

Dear Harborfields School-Community,

We would like to provide an update on the water testing recently conducted in the District.

As a result of the second test results, Enviroscience Consultants, Inc. conducted a third testing of the identified locations at each school. The attached reports reflect the results of this testing process.

The remediation of the identified locations at each school has resulted in the replacement of several sink faucets. Additionally, signs were placed on sinks in the science lab, technology lab, and art room, indicating that the water is not potable and cannot be used for drinking. In general, eating and drinking should not occur in these identified areas, by code.

We will continue to keep you apprised of this process. If you should have any questions, please contact us.

As always, the safety of our staff and students is our top priority.

Thank you.

Sincerely,



Diana Todaro

Superintendent of Schools

DT/vb

Attachment



2150 Smithtown Ave., Suite 3, Ronkonkoma, NY 11779
T: 631.580.3191 • F: 631.580.3195 • W: envirohealth.org

November 10, 2016

To: Harborfields Central School District

Attached please find the results and remediation response of sampling performed in compliance with the United States Environmental Protection Agency's "3T's for Reducing Lead in Drinking Water in Schools", October, 2006 and New York State Department of Health Subpart 67-4 of Title 10, September 2016.

Sincerely,

A handwritten signature in black ink, appearing to read "Glenn Neuschwender", written in a cursive style.

Glenn Neuschwender
President

DESIGN • INSPECTION • TESTING • ANALYSIS

DISTRICT WIDE LEAD IN DRINKING WATER
HARBORFIELDS CENTRAL SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

HARBORFIELDS HIGH SCHOOL	
First Draw Samples Collected	271
First Draw Samples > 15 Parts Per Billion	81
Number of Sources Capped or Taken Off Line	77
Post Remediation Samples <= 15 PPB	1
Number of Sources Pending For Remediation	3
<i>Maximum Pb Concentration Observed</i>	<i>400</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Main Office BR	SK	ND	-	-	None	-	-
Kitchen Prep	SK	1.3	-	-	None	-	-
Kitchen Women's BR	SK	7.68	-	-	None	-	-
Kitchen Men's BR	SK	1.42	-	-	None	-	-
Cafeteria	WF	ND	-	-	None	-	-
Girl's BR by Wellness Center	SK	ND	-	-	None	-	-
Boy's BR by Wellness Center	SK	1.73	-	-	None	-	-
Women's Dressing RM Auditorium	SK	25.8	5.6	<1.0	FR	Completed FR	Pending Retest
Men's Dressing RM Auditorium	SK	5.82	-	-	None	-	-
Nurse's Office	SK	1.23	-	-	None	-	-
Main Faculty BR Women's	SK	5.93	-	-	None	-	-
Main Faculty BR Men's	SK	2.21	-	-	None	-	-
Hallway-Band Room	WF	ND	-	-	None	-	-
Band Storage Room	SK	1.02	-	-	None	-	-
Men's BR next to RM 107	SK	1.61	-	-	None	-	-
Women's BR next to RM 105	SK	ND	-	-	None	-	-
Hallway-Room B12	WF	ND	-	-	None	-	-
Room 106B	SK	1.08	-	-	None	-	-
Art Office-100 Hallway	SK	8.15	-	-	None	-	-
RM 102	SK	ND	-	-	None	-	-
RM 101	SK	3.5	-	-	None	-	-
RM 104	SK	3.1	-	-	None	-	-
Faculty Men's BR by RM 207	SK	61.6	54	6	FRSLV	SIGN	
Faculty Women's BR by RM 205	SK	161	31	19	FRSLVPA	SIGN	
Hallway-RM 207B	WF	1.92	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Boy's Locker RM BR- North Gym	SK	ND	-	-	None	-	-
North Gym- by Boy's Locker RM	WF	ND	-	-	None	-	-
North Gym- by Girl's Locker RM	WF	ND	-	-	None	-	-
Girl's Locker RM BR- North Gym	SK	ND	-	-	None	-	-
Girl's P.E. Office BR	SK	1.6	-	-	None	-	-
Boy's P.E. Office BR	SK	1.38	-	-	None	-	-
South Gym Boy's Locker RM- Coaches BR	SK	1.01	-	-	None	-	-
South Gym Boy's Locker RM BR	SK	6.06	-	-	None	-	-
South Gym	WF	ND	-	-	None	-	-
Trainer's Office BR	SK	1.1	-	-	None	-	-
South Gym Girl's Locker RM BR	SK	ND	-	-	None	-	-
Girl's BR-T Wing	SK	1.23	-	-	None	-	-
Boy's BR-Twing	SK	1.27	-	-	None	-	-
Hallway-T Wing	WF	ND	-	-	None	-	-
Faculty BR- next to RM T25	SK	1.33	-	-	None	-	-
MPR Room Prep	SK	2.11	-	-	None	-	-
English Dept. BR	SK	ND	-	-	None	-	-
Hallway by Business Office	WF	2.76	-	-	None	-	-
Faculty Woman BR by Business Office	SK	ND	-	-	None	-	-
Faculty Men BR by Business Office	SK	8.05	-	-	None	-	-
RM 512	SK	27.8	76	18	FRSLVPA	SIGN	
RM 513	SK	38.8	2.8	2.1	FR	SIGN	
RM 513 (Prep RM 511)	SK	14.4	-	-	None	-	-
Chemical Storage	SK	72.6	22	3.5	FRSLV	SIGN	
Hallway-RM 511	WF	ND	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 509	SK	26.7	6.4	4.6	FR	SIGN	
Faculty Women BR by RM 509	SK	27.8	3.5	2.1	FR	SIGN	
RM 508	SK	22.1	6.2	7.9	FR	SIGN	
Hallway- by RM 507A	WF	1.82	-	-	None	-	-
RM 507A	SK	33.4	6.4	4.9	FR	SIGN	
RM 506	SK	26.4	10	3.2	FR	SIGN	
RM 507	SK	32.2	11	10	FR	SIGN	
Hallway- by RM 503A	WF	1.06	-	-	None	-	-
RM 503A	SK	16	4	2	FR	SIGN	
RM 503	SK	77	11	4.8	FR	SIGN	
RM 504	SK	89.8	81	25	FRSLVPA	SIGN	
Faculty Men BR by RM 504	SK	13.3	-	-	None	-	-
RM 501	SK	11.2	-	-	None	-	-
RM 502	SK	29.1	5.1	4.7	FR	SIGN	
RM 412 Men's Faculty BR	SK	13.5	-	-	None	-	-
RM 412 Women's Faculty BR	SK	4.28	-	-	None	-	-
RM 412	SK	3.44	-	-	None	-	-
RM 411	SK	24.3	2.8	1.9	FR	SIGN	
RM 409	SK	156	5.5	3.8	FR	SIGN	
Girls BR by RM 407	SK	4.36	-	-	None	-	-
Hallway- by RM 407	WF	ND	-	-	None	-	-
RM 407	SK	23.2	3.1	3.9	FR	SIGN	
RM 408	SK	2.69	-	-	None	-	-
Hallway by RM 408	WF	1.26	-	-	None	-	-
Hallway by RM 404	WF	1.76	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Men's BR by RM 404	SK	1.89	-	-	None	-	-
South Boy's Locker RM - Outside	SP	16.8	<1.0	<1.0	FR	Completed FR	1
Kitchen Handwash	SK	44			FR	SIGN	
Kitchen Sanitary Station @ (A)	SK	1.1	-	-	None	-	-
Kitchen Sanitary Station @ (B)	SK	2.7	-	-	None	-	-
Kitchen Island Prep	SK	<1.0	-	-	None	-	-
Serving Line Handwash	SK	<1.0	-	-	None	-	-
Dishwasher Station	SPRAY	3.5	-	-	None	-	-
Girl's BR By Wellness Center @ (B)	SK	19			FR	Completed FR	Pending Retest
Girl's BR By Wellness Center @ (C)	SK	<1.0	-	-	None	-	-
Boy's BR By Wellness Center @ (B)	SK	2.4	-	-	None	-	-
Nurse's Office BR	SK	4.6	-	-	None	-	-
Hallway Bandroom (Higher)	WF	<1.0	-	-	None	-	-
Band Room Storage	SK	<1.0	-	-	None	-	-
Men's BR Next To Room 107 @ (B)	SK	2	-	-	None	-	-
Women's BR Next To 105 @ (B)	SK	<1.0	-	-	None	-	-
Room 106 @ (B)	SK	4.4	-	-	None	-	-
Art Office BR	SK	2.8	-	-	None	-	-
Room 102 @ (B)	SK	8.3	-	-	None	-	-
Room 102 @ (C)	SK	5.9	-	-	None	-	-
Room 102 @ (D)	SK	7.8	-	-	None	-	-
Room: 102 @ (E)	SK	4.4	-	-	None	-	-
Room 101 @ (B)	SK	4.9	-	-	None	-	-
Room 104 @ (B)	SK	1.2	-	-	None	-	-
Room 103	SK	<1.0	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 103	SPRAY	11	-	-	None	-	-
Room 103 BR	SK	<1.0	-	-	None	-	-
Faculty Men's BR By Room 207 @ (B)	SK	1.4	-	-	None	-	-
Faculty Men's BR By Room: 207 @ (C)	SK	2.7	-	-	None	-	-
Faculty Women's BR By Room 205 @ (B)	SK	<1.0	-	-	None	-	-
Faculty Women's BR By Room 205 @ (C)	SK	4.4	-	-	None	-	-
Faculty Women's BR By Room 205 @ (D)	SK	6.3	-	-	None	-	-
North Gym Girl's Side	WF	<1.0	-	-	None	-	-
North Gym Boy's Side	WF	<1.0	-	-	None	-	-
South Gym Boy's LR BR @ (B)	SK	9.5	-	-	None	-	-
South Gym Girl's LR BR @ (B)	SK	4.5	-	-	None	-	-
Girl's BR T Wing @ (B)	SK	3.5	-	-	None	-	-
Boy's BR T Wing @ (B)	SK	1.5	-	-	None	-	-
MPR Handwash	SK	35			FR	SIGN	
Faculty Women's BR By Business Office	SK	1.6	-	-	None	-	-
Faculty Men's BR By Business Office @ (B)	SK	<1.0	-	-	None	-	-
Faculty Men's BR By Business Office @ (C)	SK	4	-	-	None	-	-
Room 512 Pod 1 @ (A)	SK	16			FR	SIGN	
Room 512 Pod 1 @ (B)	SK	13	-	-	None	-	-
Room 512 Pod 2 @ (A)	SK	13	-	-	None	-	-
Room 512 Pod 2 @ (B)	SK	19			FR	SIGN	
Room 512 Pod 3 @ (A)	SK	11	-	-	None	-	-
Room 512 Pod 3 @ (B)	SK	14	-	-	None	-	-
Room 512 Pod 4 @ (A)	SK	8.5	-	-	None	-	-
Room 512 Pod 4 @ (B)	SK	11	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 512 Pod 5 @ (A)	SK	7.6	-	-	None	-	-
Room 512 Pod 5 @ (B)	SK	17	-	-	FR	SIGN	-
Room 512 Pod 6 @ (A)	SK	5.6	-	-	None	-	-
Room 512 Pod 6 @ (B)	SK	15	-	-	None	-	-
Room 512 Fume Hood	SK	16	-	-	FR	SIGN	-
Room 512 Counter	SK	13	-	-	None	-	-
Room 513 Pod 1 @ (A)	SK	<1.0	-	-	None	-	-
Room 513 Pod 1 @ (B)	SK	4.3	-	-	None	-	-
Room 513 Pod 2 @ (A)	SK	6.3	-	-	None	-	-
Room 513 Pod 2 @ (B)	SK	9.2	-	-	None	-	-
Room 513 Pod 3 @ (A)	SK	24	-	-	FR	SIGN	-
Room 513 Pod 3 @ (B)	SK	19	-	-	FR	SIGN	-
Room 513 Pod 4 @ (A)	SK	12	-	-	None	-	-
Room 513 Pod 4 @ (B)	SK	9	-	-	None	-	-
Room 513 Pod 5 @ (A)	SK	4	-	-	None	-	-
Room 513 Pod 5 @ (B)	SK	2.2	-	-	None	-	-
Room 513 Pod 6 @ (A)	SK	19	-	-	FR	SIGN	-
Room 513 Pod 6 @ (B)	SK	13	-	-	None	-	-
Room 513 Pod 7 @ (A)	SK	13	-	-	None	-	-
Room 513 Pod 7 @ (B)	SK	7.1	-	-	None	-	-
Room 513 Counter	SK	17	-	-	FR	SIGN	-
Room 513 Fume Hood	SK	23	-	-	FR	SIGN	-
Faculty Women's BR By Room 509 @ (B)	SK	34	-	-	FR	SIGN	-
Faculty Women's BR By Room 509 @ (C)	SK	5.4	-	-	None	-	-
Faculty Women's BR By Room 509 @ (D)	SK	4.8	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 509 Pod 1 @ (A)	SK	4.8	-	-	None	-	-
Room 509 Pod 1 @ (B)	SK	22	-	-	FR	SIGN	-
Room 509 Pod 2 @ (A)	SK	22	-	-	FR	SIGN	-
Room 509 Pod 2 @ (B)	SK	13	-	-	None	-	-
Room 509 Pod 3 @ (A)	SK	12	-	-	None	-	-
Room 509 Pod 3 @ (B)	SK	13	-	-	None	-	-
Room 509 Pod 4 @ (A)	SK	22	-	-	FR	SIGN	-
Room 509 Pod 4 @ (B)	SK	5.2	-	-	None	-	-
Room 509 Pod 5 @ (A)	SK	8.2	-	-	None	-	-
Room 509 Pod 5 @ (B)	SK	8	-	-	None	-	-
Room 509 Pod 6 @ (A)	SK	6.9	-	-	None	-	-
Room 509 Pod 6 @ (B)	SK	5.6	-	-	None	-	-
Room 509 Pod 7 @ (A)	SK	30	-	-	FR	SIGN	-
Room 509 Pod 7 @ (B)	SK	6.3	-	-	None	-	-
Room 509 Fume Hood	SK	94	-	-	FR	SIGN	-
Room 509 Counter	SK	19	-	-	FR	SIGN	-
Room 507 Pod 1 @ (A)	SK	8.7	-	-	None	-	-
Room 507 Pod 1 @ (B)	SK	3.3	-	-	None	-	-
Room 507 Pod 2 @ (A)	SK	8	-	-	None	-	-
Room 507 Pod 2 @ (B)	SK	5.8	-	-	None	-	-
Room 507 Pod 3 @ (A)	SK	12	-	-	None	-	-
Room 507 Pod 3 @ (B)	SK	8.8	-	-	None	-	-
Room 507 Pod 4 @ (A)	SK	17	-	-	FR	SIGN	-
Room 507 Pod 4 @ (B)	SK	1.1	-	-	None	-	-
Room 507 Pod 5 @ (A)	SK	6.6	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 507 Pod 5 @ (B)	SK	2.7	-	-	None	-	-
Room 507 Pod 6 @ (A)	SK	2.4	-	-	None	-	-
Room 507 Pod 6 @ (B)	SK	1.9	-	-	None	-	-
Room 507 Pod 7 @ (A)	SK	1.4	-	-	None	-	-
Room 507 Pod 7 @ (B)	SK	6	-	-	None	-	-
Room 507 Counter	SK	29			FR	SIGN	
Room 507 Fume Hood	SK	25			FR	SIGN	
Room 508 Pod 1 @ (A)	SK	2.6	-	-	None	-	-
Room 508 Pod 1 @ (B)	SK	3.5	-	-	None	-	-
Room 508 Pod 2 @ (A)	SK	7.5	-	-	None	-	-
Room 508 Pod 2 @ (B)	SK	3.6	-	-	None	-	-
Room 508 Pod 3 @ (A)	SK	<1.0	-	-	None	-	-
Room 508 Pod 3 @ (B)	SK	2.2	-	-	None	-	-
Room 508 Pod 4 @ (A)	SK	2.8	-	-	None	-	-
Room 508 Pod 4 @ (B)	SK	2.4	-	-	None	-	-
Room 508 Pod 5 @ (A)	SK	2.5	-	-	None	-	-
Room 508 Pod 5 @ (B)	SK	2.2	-	-	None	-	-
Room 508 Pod 6 @ (A)	SK	<1.0	-	-	None	-	-
Room 508 Pod 6 @ (B)	SK	2.9	-	-	None	-	-
Room 508 Pod 7 @ (A)	SK	4.4	-	-	None	-	-
Room 508 Pod 7 @ (B)	SK	7.5	-	-	None	-	-
Room 508 Fume Hood	SK	44			FR	SIGN	
Room 508 Counter	SK	33			FR	SIGN	
Room 506 Pod 1 @ (A)	SK	11	-	-	None	-	-
Room 506 Pod 1 @ (B)	SK	8.8	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 506 Pod 2 @ (A)	SK	21			FR	SIGN	
Room 506 Pod 2 @ (B)	SK	18			FR	SIGN	
Room 506 Pod 3 @ (A)	SK	12	-	-	None	-	-
Room: 506 Pod 3 @ (B)	SK	14	-	-	None	-	-
Room 506 Pod 4 @ (A)	SK	19			FR	SIGN	
Room 506 Pod 4 @ (B)	SK	6.2	-	-	None	-	-
Room 506 Pod 5 @ (A)	SK	14	-	-	None	-	-
Room 506 Pod 5 @ (B)	SK	12	-	-	None	-	-
Room 506 Pod 6 @ (A)	SK	8.9	-	-	None	-	-
Room 506 Pod 6 @ (B)	SK	17			FR	SIGN	
Room 506 Fume Hood	SK	77			FR	SIGN	
Room 506 Counter	SK	28			FR	SIGN	
Room 503 Pod 1 @ (A)	SK	18			FR	SIGN	
Room 503 Pod 1 @ (B)	SK	14	-	-	None	-	-
Room 503 Pod 2 @ (A)	SK	8.5	-	-	None	-	-
Room 503 Pod 2 @ (B)	SK	6.8	-	-	None	-	-
Room 503 Pod 3 @ (A)	SK	7.5	-	-	None	-	-
Room 503 Pod 3 @ (B)	SK	13	-	-	None	-	-
Room 503 Pod 4 @ (A)	SK	20			FR	SIGN	
Room 503 Pod 4 @ (B)	SK	15	-	-	None	-	-
Room 503 Pod 5 @ (A)	SK	20			FR	SIGN	
Room 503 Pod 5 @ (B)	SK	15	-	-	None	-	-
Room 503 Pod 6 @ (A)	SK	20			FR	SIGN	
Room: 503 Pod 6 @ (B)	SK	15	-	-	None	-	-
Room 503 Fume Hood	SK	400			FR	SIGN	

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 503 Counter	SK	25			FR	SIGN	
Room 504 Table 1 @ (B)	SK	46			FR	SIGN	
Room 504 Table 3 @ (A)	SK	66			FR	SIGN	
Room 504 Table 3 @ (B)	SK	23			FR	SIGN	
Room 504 Table 4 @ (A)	SK	110			FR	SIGN	
Room 504 Table 4 @ (B)	SK	10	-	-	None	-	-
Room 504 Table 5 @ (A)	SK	110			FR	SIGN	
Room 504 Table 5 @ (B)	SK	140			FR	SIGN	
Room 504 Table 5 @ (C)	SK	320			FR	SIGN	
Room 504 Teacher's Station @ (B)	SK	23			FR	SIGN	
Faculty Men's BR By Room 504 @ (B)	SK	5.5	-	-	None	-	-
Faculty Men's BR By Room 504 @ (C)	SK	3.3	-	-	None	-	-
Faculty Men's BR By Room 504 @ (D)	SK	2.7	-	-	None	-	-
Room 412 WoMen's Faculty BR @ (B)	SK	10	-	-	None	-	-
Room 411 Counter 1 @ (A)	SK	12	-	-	None	-	-
Room 411 Counter 1 @ (B)	SK	8.4	-	-	None	-	-
Room 411 Counter 1 @ (C)	SK	39			FR	SIGN	
Room 411 Counter 1 @ (D)	SK	10	-	-	None	-	-
Room 411 Counter 1 @ (E)	SK	18			FR	SIGN	
Room 411 Counter 1 @ (F)	SK	14	-	-	None	-	-
Room 411 Counter 1 @ (G)	SK	12	-	-	None	-	-
Room 411 Counter 1 @ (H)	SK	6.1	-	-	None	-	-
Room 411 Counter 1 @ (I)	SK	11	-	-	None	-	-
Room 411 Counter 1 @ (J)	SK	11	-	-	None	-	-
Room 411 Counter 1 @ (K)	SK	25			FR	SIGN	

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room 411 Counter 2	SK	37			FR	SIGN	
Girl's BR By Room 407 @ (B)	SK	2.8	-	-	None	-	-
Girl's BR By Room 407 @ (C)	SK	1.1	-	-	None	-	-
Girl's BR By Room 407 @ (D)	SK	1.9	-	-	None	-	-
Room 407 Counter 1 @ (A)	SK	18			FR	SIGN	
Room 407 Counter 1 @ (B)	SK	28			FR	SIGN	
Room 407 Counter 1 @ (C)	SK	19			FR	SIGN	
Room 407 Counter 1 @ (D)	SK	23			FR	SIGN	
Room 407 Counter 1 @ (E)	SK	10	-	-	None	-	-
Room 407 Counter 2	SK	45			FR	SIGN	
Room 407 Counter 3 @ (A)	SK	86			FR	SIGN	
Room 407 Counter 3 @ (B)	SK	130			FR	SIGN	
Room 407 Counter 3 @ (C)	SK	78			FR	SIGN	
Room 407 Counter 3 @ (D)	SK	17			FR	SIGN	
Room 407 Counter 3 @ (E)	SK	110			FR	SIGN	
Room 407 Counter 3 @ (F)	SK	50			FR	SIGN	
Men's BR By Room 404 @ (B)	SK	<1.0	-	-	None	-	-
Men's BR By Room 404 @ (C)	SK	22			FR	SIGN	
Men's BR By Room 404 @ (D)	SK	<1.0	-	-	None	-	-
Outside South Gym Girl's	SP	140			FR	FILTER INSTALLED	Pending Retest
South Gym Trainer's Office	IM	<1.0	-	-	None	-	-

**DISTRICT WIDE LEAD IN DRINKING WATER
HARBORFIELDS CENTRAL SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016**

OLD FIELD MIDDLE SCHOOL	
First Draw Samples Collected	142
First Draw Samples > 15 Parts Per Billion	9
Number of Sources Capped or Taken Off Line	5
Post Remediation Samples <= 15 PPB	1
Number of Sources Pending For Remediation	3
<i>Maximum Pb Concentration Observed</i>	<i>106</i>

Harborfields CSD
Old Field Middle School

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1" Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Hallway WF by RM B15	WF	ND	-	-	None	-	-
Men's BR SK by Head Custodian Office	SK	2.27	-	-	None	-	-
Boy's BR SK by B15	SK	ND	-	-	None	-	-
Ladies BR SK by Special Ed.	SK	ND	-	-	None	-	-
Main Office Kitchen	SK	3.07	-	-	None	-	-
Women's BR SK by Main Office	SK	4.13	-	-	None	-	-
Hallway WF by Main Office	WF	ND	-	-	None	-	-
Men's BR SK Main Lobby	SK	2.26	-	-	None	-	-
Hallway WF by Men's BR Main Lobby	WF	ND	-	-	None	-	-
Business Office	SK	ND	-	-	None	-	-
Girl's BR SK by RM A109	SK	3.71	-	-	None	-	-
Ladies BR by A112	SK	9.44	-	-	None	-	-
Hallway WF by RM A107	WF	ND	-	-	None	-	-
Room A105	SK	3.76	-	-	None	-	-
Boy's BR SK B-Wing	SK	5.05	-	-	None	-	-
Girl's BR SK B-Wing	SK	ND	-	-	None	-	-
Hallway WF by RM B216	WF	ND	-	-	None	-	-
Room B214	SK	5.91	-	-	None	-	-
Room B216	SK	4.66	-	-	None	-	-
Room B218	SK	43.9	1.8	1.1	FR	SIGN	
Room B220	SK	7.96	-	-	None	-	-
Hallway WF by Guidance Office	WF	ND	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
District Office Kitchen	SK	ND	-	-	None	-	-
Men's BR SK by District Office	SK	2.58	-	-	None	-	-
Ladies BR SK by District Office	SK	5.79	-	-	None	-	-
Teacher's Faculty RM Ladies BR	SK	ND	-	-	None	-	-
Teacher's Faculty RM Men's BR	SK	3.3	-	-	None	-	-
Hallway WF by Teacher's Faculty Lounge	WF	ND	-	-	None	-	-
Boy's BR SK by Nurses Office	SK	1.03	-	-	None	-	-
Girl's BR SK by Nurses Office	SK	ND	-	-	None	-	-
Nurses Office	SK	1.28	-	-	None	-	-
Nurses Office BR	SK	1.76	-	-	None	-	-
Kitchen Ladies BR	SK	21.4	12	4.7	FR	Completed FR	Pending Retest
Kitchen Main Cooking	SK	ND	-	-	None	-	-
Kitchen Prep	SK	ND	-	-	None	-	-
Teacher's Café	SK	1.08	-	-	None	-	-
Cafeteria WF - West	WF	ND	-	-	None	-	-
Cafeteria WF - East	WF	ND	-	-	None	-	-
Hallway WF by Gym - West	WF	ND	-	-	None	-	-
Hallway WF by Gym - East	SK	ND	-	-	None	-	-
Gym Hallway Girl's BR	SK	1.57	-	-	None	-	-
Gym Hallway Boy's BR	SK	ND	-	-	None	-	-
Boy's Coaches BR	SK	7.35	-	-	None	-	-
Boy's Locker Room BR	SK	4.37	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Girl's Coaches BR	SK	4.36	-	-	None	-	-
Girl's Locker Room BR	SK	1	-	-	None	-	-
Ice Machine SP- Behind Girl's LR	SP	58.6	<1.0	2.6	FR	Completed FR	3.6
Boy's BR SK by RM B317	SK	ND	-	-	None	-	-
Girl's BR SK by RM B322	SK	2.31	-	-	None	-	-
Hallway WF by RM B324	WF	ND	-	-	None	-	-
Room B328	SK	7.5	-	-	None	-	-
Room A-316 (Library Coffee RM)	SK	3.23	-	-	None	-	-
Boy's BR SK by RM A313	SK	ND	-	-	None	-	-
Women's BR SK by RM A311	SK	1.2	-	-	None	-	-
Girl's BR SK by RM A311	SK	ND	-	-	None	-	-
Hallway WF by RM A308	WF	ND	-	-	None	-	-
Art Room B113	SK	ND	-	-	None	-	-
Art Room A107	SK	106	16	4.5	FRSLV	SIGN	
Kitchen Ladies BR @ (B)	SK	<2.5	-	-	None	-	-
Kitchen 3 Compartment @ (A)	SK	<2.5	-	-	None	-	-
Kitchen 3 Compartment @ (B)	SK	<2.5	-	-	None	-	-
Kitchen 3 Compartment @ (C)	SK	<2.5	-	-	None	-	-
Kitchen Handwash @ (A)	SK	<2.5	-	-	None	-	-
Kitchen Prep @ (B)	SK	<2.5	-	-	None	-	-
Kitchen Pot Filler	SP	14	-	-	None	-	-
Kitchen Handwash @ (B)	SK	<2.5	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
W Serving Line Handwash	SK	<2.5	-	-	None	-	-
Dishwashing	SPRAY	<2.5	-	-	None	-	-
Dishwashing	SK	7	-	-	None	-	-
E Serving Line Handwash	SK	<2.5	-	-	None	-	-
Kitchen	IM	<2.5	-	-	None	-	-
Girl's LR BR @ (B)	SK	<2.5	-	-	None	-	-
Boy's LR BR @ (B)	SK	<2.5	-	-	None	-	-
Gym Hallway Boy's BR @ (B)	SK	<2.5	-	-	None	-	-
Gym Hallway Girl's BR @ (B)	SK	<2.5	-	-	None	-	-
Teacher's Faculty Ladies BR @ (B)	SK	<2.5	-	-	None	-	-
Teacher's Faculty Men's BR @ (B)	SK	<2.5	-	-	None	-	-
Boy's BR by Nurse's Office @ (B)	SK	<2.5	-	-	None	-	-
Boy's BR by Nurse's Office @ (C)	SK	<2.5	-	-	None	-	-
Girl's BR by Nurse's Office @ (B)	SK	<2.5	-	-	None	-	-
Girl's BR by Nurse's Office @ (C)	SK	<2.5	-	-	None	-	-
Boy's BR by 2nd Fl. B Wing @ (B)	SK	<2.5	-	-	None	-	-
Boy's BR by 2nd Fl. B Wing @ (C)	SK	<2.5	-	-	None	-	-
Girl's BR by 2nd Fl. B Wing @ (B)	SK	<2.5	-	-	None	-	-
Girl's BR by 2nd Fl. B Wing @ (C)	SK	<2.5	-	-	None	-	-
Room B214 Counter @ (A)	SK	<2.5	-	-	None	-	-
Room B214 Counter @ (B)	SK	<2.5	-	-	None	-	-
Room B214-A	SK	<2.5	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room B216 Table 1 @ (A)	SK	3.9	-	-	None	-	-
Room B216 Table 1 @ (B)	SK	3.5	-	-	None	-	-
Room B216 Table 2 @ (A)	SK	2.6	-	-	None	-	-
Room B216 Table 2 @ (B)	SK	9.8	-	-	None	-	-
Room B216 Table 3 @ (A)	SK	34	-	-	FR	SIGN	-
Room B216 Table 3 @ (B)	SK	4.8	-	-	None	-	-
Room B216 Table 4 @ (A)	SK	5.9	-	-	None	-	-
Room B216 Table 4 @ (B)	SK	15	-	-	None	-	-
Room B216 Table 5 @ (A)	SK	11	-	-	None	-	-
Room B216 Table 5 @ (B)	SK	<2.5	-	-	None	-	-
Room B218 Counter @ (A)	SK	<2.5	-	-	None	-	-
Room B218 Counter @ (B)	SK	<2.5	-	-	None	-	-
Room B218-A	SK	11	-	-	None	-	-
Room B220 Table 1 @ (A)	SK	<2.5	-	-	None	-	-
Room B220 Table 1 @ (B)	SK	<2.5	-	-	None	-	-
Room B220 Table 2 @ (A)	SK	8.2	-	-	None	-	-
Room B220 Table 2 @ (B)	SK	9.7	-	-	None	-	-
Room B220 Table 3 @ (A)	SK	4.4	-	-	None	-	-
Room B220 Table 3 @ (B)	SK	45	-	-	FR	SIGN	-
Room B220 Table 4 @ (A)	SK	74	-	-	None	-	-
Room B220 Table 4 @ (B)	SK	<2.5	-	-	None	-	-
Room B220 Table 5 @ (A)	SK	<2.5	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room B220 Table 5 @ (B)	SK	<2.5	-	-	None	-	-
Boy's BR by RM B317 @ (B)	SK	<2.5	-	-	None	-	-
Boy's BR by RM B317 @ (C)	SK	<2.5	-	-	None	-	-
Men's BR by RM B317	SK	<2.5	-	-	None	-	-
Girl's BR by RM B322 @ (B)	SK	<2.5	-	-	None	-	-
Girl's BR by RM B322 @ (C)	SK	<2.5	-	-	None	-	-
Room B322	SK	<2.5	-	-	None	-	-
Room A322	SK	48			FR	TBD	
Room 322 Unit @ (A)	SK	4	-	-	None	-	-
Room 322 Unit @ (B)	SK	<2.5	-	-	None	-	-
Boy's BR by RM A313 @ (B)	SK	<2.5	-	-	None	-	-
Boy's BR by RM A313 @ (C)	SK	<2.5	-	-	None	-	-
Girl's BR by RM A311 @ (B)	SK	<2.5	-	-	None	-	-
Girl's BR by RM A311 @ (C)	SK	<2.5	-	-	None	-	-
Girl's BR by RM A112 @ (B)	SK	2.8	-	-	None	-	-
Girl's BR by RM A112 @ (C)	SK	<2.5	-	-	None	-	-
Room A107 Counter @ (B)	SK	24			FR	SIGN	
Room A107 Counter @ (C)	SK	2.8	-	-	None	-	-
Room A105 Station 1	SK	<2.5	-	-	None	-	-
Room A105 Station 2	SK	<2.5	-	-	None	-	-
Room A105 Station 3	SK	<2.5	-	-	None	-	-
Men's BR by Main Lobby @ (B)	SK	4.3	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Harborfields CSD
Old Field Middle School

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Women's BR by Main Office @ (B)	SK	3.2	-	-	None	-	-
Principal's Office BR	SK	7.5	-	-	None	-	-
Boy's BR by B15 @ (B)	SK	<2.5	-	-	None	-	-
Boy's BR by B15 @ (C)	SK	<2.5	-	-	None	-	-
Room B113 Counter @ (B)	SK	103	-	-	FR	TBD	-
Room B113 Counter @ (C)	SK	<2.5	-	-	None	-	-
Room B113 Counter @ (D)	SK	<2.5	-	-	None	-	-
Room B115 Unit @ (B)	SK	<2.5	-	-	None	-	-
Room B117 Unit @ (A)	SK	3.2	-	-	None	-	-
Room B117 Unit @ (B)	SK	<2.5	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

**DISTRICT WIDE LEAD IN DRINKING WATER
HARBORFIELDS CENTRAL SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016**

THOMAS J. LAHEY ELEMENTARY SCHOOL	
First Draw Samples Collected	60
First Draw Samples > 15 Parts Per Billion	5
Number of Sources Capped or Taken Off Line	2
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	3
<i>Maximum Pb Concentration Observed</i>	<i>78.9</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room A1	WF	2.7	-	-	None	-	-
Room A2	SK	4.04	-	-	None	-	-
Room A3	SK	5.79	-	-	None	-	-
Room A4	SK	5.55	-	-	None	-	-
North MPR	WF	2.1	-	-	None	-	-
Room B1	SK	5.05	-	-	None	-	-
Room B4	SK	7.94	-	-	None	-	-
Room B2	WF	2.1	-	-	None	-	-
Room B3	SK	4.51	-	-	None	-	-
Main Hall by Office 2	WF	ND	-	-	None	-	-
Library Office	SK	13.4	-	-	None	-	-
Main Hall Men Bath	SK	9.02	-	-	None	-	-
Main Hall Women Bath	SK	1.17	-	-	None	-	-
Main Hall Across 64H	WF	ND	-	-	None	-	-
64H North Side	WF	ND	-	-	None	-	-
North Coaches Office	SK	7.31	-	-	None	-	-
South Coaches Office	SK	53.1	14	4.7	FR	CAP	49 (9/20/2016)
H Wing Facility Bath	SK	1.38	-	-	None	-	-
E, F Wing by RM F5	WF	ND	-	-	None	-	-
L Wing by Room L1	WF	ND	-	-	None	-	-
Room L1	SK	ND	-	-	None	-	-
Room L4	SK	ND	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room L2	SK	ND	-	-	None	-	-
Room L3	SK	ND	-	-	None	-	-
Room R1	SK	78.9	5.7	4.7	FR	CAP	59 (9/20/2016)
South MPR	WF	3.11	-	-	None	-	-
C, D Wing Women Bath	SK	1.83	-	-	None	-	-
C, D Wing Men Bath	SK	2.48	-	-	None	-	-
Room D1	WF	4.84	-	-	None	-	-
Room D2	WF	8.9	-	-	None	-	-
Room D3	WF	4.32	-	-	None	-	-
Room D4	WF	ND	-	-	None	-	-
Room C1	WF	4.88	-	-	None	-	-
Room C2	SK	2.29	-	-	None	-	-
Room C3	SK	2.12	-	-	None	-	-
Room C4	WF	ND	-	-	None	-	-
South Serving Line	SK	1.43	-	-	None	-	-
Kitchen Main / Middle Sink	SK	1.01	-	-	None	-	-
Kitchen Pre Sink	SK	2.05	-	-	None	-	-
Kitchen Pot Filler by Store	SK	10.1	-	-	None	-	-
North Serving Line	SK	3.8	-	-	None	-	-
TJA Garage	SK	-	<10	<10	FR	Pending First Draw	
Sanitizer Sink @ (A)	SK	12	-	-	None	-	-
Sanitizer Sink @ (B)	SK	7.1	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1" Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Kitchen handwash	SK	75			FR	Pending Flushes	
Kitchen dishwasher	SPRAY	12	-	-	None	-	-
Kitchen Women's BR	SK	3.2	-	-	None	-	-
Nurse's Office	SK	4.8	-	-	None	-	-
Nurse's Office BR	SK	<2.5	-	-	None	-	-
Main Hall Men Bath @ (B)	SK	32			FR	Pending Flushes	
Main Hall Women Bath @ (B)	SK	8.1	-	-	None	-	-
Art Room @ (A)	SK	<2.5	-	-	None	-	-
Art Room @ (B)	SK	6.4	-	-	None	-	-
C,D Wing Men Bath @ (B)	SK	5.7	-	-	None	-	-
C,D Wing Women Bath @ (A)	SK	3.6	-	-	None	-	-
L Wing Staff Bath	SK	<2.5	-	-	None	-	-
L Wing Girl's Bath	SK	6.4	-	-	None	-	-
L Wing Boy's Bath	SK	3.8	-	-	None	-	-
Music Room	SK	6.6	-	-	None	-	-
Orchestra Room	SK	31			FR	Pending Flushes	

DISTRICT WIDE LEAD IN DRINKING WATER
HARBORFIELDS CENTRAL SCHOOL DISTRICT
SUMMARY REPORT AS OF
11/10/2016

WASHINGTON DRIVE ELEMENTARY SCHOOL	
First Draw Samples Collected	155
First Draw Samples > 15 Parts Per Billion	4
Number of Sources Capped or Taken Off Line	0
Post Remediation Samples <= 15 PPB	0
Number of Sources Pending For Remediation	4
<i>Maximum Pb Concentration Observed</i>	<i>303</i>

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
"F" Wing BR by Elevator	SK	3.74	-	-	None	-	-
Room F2	SK	1.54	-	-	None	-	-
Room F4	WF	ND	-	-	None	-	-
Room F6	WF	2	-	-	None	-	-
"F" Wing Boy's BR	SK	3.15	-	-	None	-	-
"F" Wing Girl's BR	SK	2.33	-	-	None	-	-
"F" Wing Girl's BR	WF	ND	-	-	None	-	-
Room F5	SK	1.28	-	-	None	-	-
Room F3	WF	ND	-	-	None	-	-
Room F1	SK	1.07	-	-	None	-	-
"E" Wing Girl's BR	SK	4.78	-	-	None	-	-
"E" Wing Girl's BR	WF	ND	-	-	None	-	-
"E" Wing Boy's BR	SK	5.28	-	-	None	-	-
Room E2	WF	1.26	-	-	None	-	-
Room E4	WF	1.47	-	-	None	-	-
Room E6	WF	8.57	-	-	None	-	-
Room E8	WF	14.9	-	-	None	-	-
Room E7	WF	7.61	-	-	None	-	-
Room E5	WF	ND	-	-	None	-	-
Room E3	WF	60.9	2.9	2	FR	Completed FR	Pending Retest
Room E1	WF	1.53	-	-	None	-	-
Room C2	SK	1.34	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room C4	WF	ND	-	-	None	-	-
Room C6	WF	1.41	-	-	None	-	-
"C" Wing Boy's BR	SK	2.28	-	-	None	-	-
"C" Wing Girl's BR	SK	3.03	-	-	None	-	-
Room C5	SK	ND	-	-	None	-	-
Room C3	WF	2.04	-	-	None	-	-
Room C1	WF	2.57	-	-	None	-	-
Hallway by Gym	WF	ND	-	-	None	-	-
PE-2 Office	SK	10	-	-	None	-	-
PE-1 Office	SK	7.13	-	-	None	-	-
Room D1	WF	ND	-	-	None	-	-
Room D3	WF	ND	-	-	None	-	-
Room D5	WF	1.18	-	-	None	-	-
Room D7	WF	ND	-	-	None	-	-
Room D9	WF	ND	-	-	None	-	-
Room D10	WF	ND	-	-	None	-	-
Room D8	WF	ND	-	-	None	-	-
Room D6	WF	ND	-	-	None	-	-
Room D4	WF	ND	-	-	None	-	-
Room D2	WF	ND	-	-	None	-	-
"D" Wing Girl's BR	SK	5.15	-	-	None	-	-
"D" Wing Boy's BR	SK	4.97	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
"B" Wing Girl's BR	SK	3.91	-	-	None	-	-
"B" Wing Boy's BR	SK	3.22	-	-	None	-	-
"B" Wing by Girl's BR	WF	ND	-	-	None	-	-
Room B2	WF	1.23	-	-	None	-	-
Room B4	WF	ND	-	-	None	-	-
Room B6	WF	ND	-	-	None	-	-
Room B8	WF	1.97	-	-	None	-	-
Room B7	WF	1.15	-	-	None	-	-
Room B5	WF	1.08	-	-	None	-	-
Room B3	SK	4.25	-	-	None	-	-
Room B1	SK	2.06	-	-	None	-	-
Room A11	WF	2.5	-	-	None	-	-
Room A10	WF	ND	-	-	None	-	-
Room A9	WF	1.16	-	-	None	-	-
Room A8	WF	1.27	-	-	None	-	-
Room A7	WF	ND	-	-	None	-	-
Room A5	WF	ND	-	-	None	-	-
Room A3	WF	ND	-	-	None	-	-
Room A1	WF	2.48	-	-	None	-	-
"A" Wing Girl's BR	SK	5.53	-	-	None	-	-
"A" Wing by Girl's BR	WF	ND	-	-	None	-	-
Room A2	WF	5.55	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room A4	WF	4.33	-	-	None	-	-
Room A6	WF	ND	-	-	None	-	-
"A" Wing Boy's BR	SK	6.58	-	-	None	-	-
Nurse Office	SK	2.21	-	-	None	-	-
Nurse Office BR	SK	10.6	-	-	None	-	-
Main Office BR	SK	3.26	-	-	None	-	-
Kitchen Pre Sink	SK	1.24	-	-	None	-	-
Kitchen Main / Middle Sink	SK	1.98	-	-	None	-	-
Kitchen Pot Filler by Stove	SK	ND	-	-	None	-	-
Kitchen North Pot Filler	SK	12.4	-	-	None	-	-
Serving Line South	SK	ND	-	-	None	-	-
Serving Line North	SK	3.36	-	-	None	-	-
Faculty Room	SK	1.61	-	-	None	-	-
Main Hall Women BR	SK	3.94	-	-	None	-	-
Main Hall by Men BR	WF	ND	-	-	None	-	-
Main Hall by Men BR	SK	4.85	-	-	None	-	-
"F" Wing Girl's BR @ (B)	SK	<2.5	-	-	None	-	-
"F" Wing Girl's BR @ (C)	SK	2.9	-	-	None	-	-
"F" Wing Boy's BR @ (B)	SK	<2.5	-	-	None	-	-
"F" Wing Boy's BR @ (C)	SK	6.4	-	-	None	-	-
Room F6	SK	<2.5	-	-	None	-	-
Room F5 @ (B)	SK	4.6	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room F4	SK	<2.5	-	-	None	-	-
Room F3	SK	<2.5	-	-	None	-	-
Room F2 BR	SK	7.4	-	-	None	-	-
"E" Wing Girl's BR @ (B)	SK	5.4	-	-	None	-	-
"E" Wing Boy's BR @ (B)	SK	<2.5	-	-	None	-	-
Room E1	SK	<2.5	-	-	None	-	-
Room E2	SK	<2.5	-	-	None	-	-
Room E4	SK	<2.5	-	-	None	-	-
Room E3	SK	4.7	-	-	None	-	-
Room E5	SK	<2.5	-	-	None	-	-
Room E6	SK	<2.5	-	-	None	-	-
Room E7	SK	<2.5	-	-	None	-	-
Room E8	SK	<2.5	-	-	None	-	-
Room B8	SK	<2.5	-	-	None	-	-
Room B6	SK	<2.5	-	-	None	-	-
Room B7	SK	5.7	-	-	None	-	-
Room B7 BR	SK	5.5	-	-	None	-	-
Room B5	SK	<2.5	-	-	None	-	-
Room B4	SK	<2.5	-	-	None	-	-
Room B2	SK	10	-	-	None	-	-
"B" Wing Girl's BR @ (B)	SK	<2.5	-	-	None	-	-
"B" Wing Boy's BR @ (B)	SK	<2.5	-	-	None	-	-

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Room A11	SK	<2.5	-	-	None	-	-
Room A10	SK	<2.5	-	-	None	-	-
Room A9	SK	<2.5	-	-	None	-	-
Room A7	SK	<2.5	-	-	None	-	-
Room A5	SK	3.4	-	-	None	-	-
Room A6	SK	<2.5	-	-	None	-	-
Room A3	SK	<2.5	-	-	None	-	-
Room A4	SK	<2.5	-	-	None	-	-
Room A8	SK	<2.5	-	-	None	-	-
Room A2	SK	4.7	-	-	None	-	-
Room A1	SK	<2.5	-	-	None	-	-
"A" Wing Girl's BR @ (B)	SK	<2.5	-	-	None	-	-
"A" Wing Boy's BR @ (B)	SK	<2.5	-	-	None	-	-
Kitchen Handwash @ (A)	SK	116	-	-	FR	Pending Flushes	-
Kitchen Handwash @ (B)	SK	<2.5	-	-	None	-	-
Kitchen Dishwash 3 Bay	SK	<2.5	-	-	None	-	-
Kitchen Dishwash 3 Bay	SPRAY	<2.5	-	-	None	-	-
Kitchen Dishwash	SPRAY	47	-	-	FR	Pending Flushes	-
Main Hall Women's BR @ (B)	SK	<2.5	-	-	None	-	-
Main Hall Women's BR @ (C)	SK	<2.5	-	-	None	-	-
Main Hall Women's BR @ (D)	SK	<2.5	-	-	None	-	-
Main Hall Men's BR @ (B)	SK	4.3	-	-	None	-	-

Harborfields CSD
Washington Drive Elementary School

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Main Hall Men's BR @ (C)	SK	<2.5	-	-	None	-	-
"D" Wing Girl's BR @ (B)	SK	5	-	-	None	-	-
"D" Wing Boy's BR @ (B)	SK	3.3	-	-	None	-	-
Room D1	SK	<2.5	-	-	None	-	-
Room D2	SK	<2.5	-	-	None	-	-
Room D3	SK	<2.5	-	-	None	-	-
Room D4	SK	<2.5	-	-	None	-	-
Room D6	SK	<2.5	-	-	None	-	-
Room D5	SK	<2.5	-	-	None	-	-
Room D7	SK	<2.5	-	-	None	-	-
Room D8	SK	<2.5	-	-	None	-	-
Room D9	SK	<2.5	-	-	None	-	-
Room D10	SK	<2.5	-	-	None	-	-
Room C1	SK	<2.5	-	-	None	-	-
Room C2 BR	SK	<2.5	-	-	None	-	-
Room C3	SK	<2.5	-	-	None	-	-
Room C4	SK	<2.5	-	-	None	-	-
Room C5 @ (B)	SK	<2.5	-	-	None	-	-
Room C6	SK	<2.5	-	-	None	-	-
"C" Wing Boy's BR @ (B)	SK	<2.5	-	-	None	-	-
"C" Wing Boy's BR @ (C)	SK	<2.5	-	-	None	-	-
"C" Wing Girl's BR @ (B)	SK	303			FR	Pending Flushes	

Action Level = 15.0 parts per billion (ppb) (ug/L)

Harborfields CSD
Washington Drive Elementary School

Lead in Drinking Water Test Results

Sample Location	Fixture Type	1 st Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
"C" Wing Girl's BR @ (C)	SK	<2.5	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)